Subject: Re: FW: Follow-up on Wall and Carpet Damage - 1803/243 Franklin St From: "Sylvia Hao - Areal Property Hawthorn (MPM)" < MPM@email.propertyme.com>

**Date:** 12/5/68, 09:55

**To:** ck.chawakorn@gmail.com **CC:** mpm@email.propertyme.com

agent image

Hi Chawakorn,

Thank you for your detailed update and the photo.

I've followed up with the Owners Corporation to confirm that the leak has been resolved, and I've requested that the necessary rectification works be arranged without further delay. I've also asked them to provide a clear timeline for inspection and repairs.

I understand the inconvenience this has caused and appreciate your continued patience. I'll keep you updated as soon as I receive a confirmed plan from their side.

Best regards,

## Sylvia Hao Relationship Manager

M 0420 675 561

P 03 9818 8991

A 33 Camberwell Road, Hawthorn East VIC 3123



From: Chawakorn Kamnuansil <ck.chawakorn@gmail.com>

**Sent:** Saturday, 10 May 2025 1:30 PM

To: Sylvia Hao <sylvia.hao@areal.com.au>

Subject: Re: Follow-up on Wall and Carpet Damage - 1803/243 Franklin St

Hi Sylvia,

1 of 9 8/8/68, 17:18

Thanks for your reply. Here's an update on the wall — although the water has dried, there is still a visible stain and surface warping, as shown in the attached photo.

I've done my best to manage it temporarily using Gumption, but this is clearly not a long-term solution and shouldn't fall under the tenant's responsibility.

The wall is still visibly damaged and the room remains unsuitable for normal use. I need to know when someone will be sent to inspect and repair the affected area. This needs to be addressed properly, not just acknowledged.


Also, for record-keeping purposes, all communication regarding this matter must be done via email, as phone calls cannot be documented as evidence if needed.

I expect a response with a clear action plan and timeline.

Best regards,

Chawakorn

2 of 9 8/8/68, 17:18



Re: FW: Follow-up on Wall and Carpet Damage – 1803/243 Franklin St On Fri, 9 May 2025 at 14:23, Sylvia Hao <<u>sylvia.hao@areal.com.au</u>> wrote: Hi Chawakorn, Thank you for your email, and I do apologise for the lack of updates — I understand your concerns and appreciate your continued patience. The plumber who attended the unit last Wednesday was arranged by the Owner's Corporation to address the leak from the hot water system. We are currently waiting on their formal report to confirm that the issue has been fully resolved. In the meantime, could you please let me know if there has been any further water ingress or signs of dampness since their visit? This will help ensure there are no ongoing issues. Once we receive confirmation that the source of the leak is no longer active, we will arrange for quotations to repair the internal damage, including the wall and potentially affected carpet and underlay. I understand how frustrating this situation is and will continue to follow up with the relevant parties to ensure the matter is addressed appropriately.

7 of 9

Kind Regards,

	Sylvia Hao Relationship Manager  0420 675 561 sylvia.hao@areal.com.au 03 9818 8991 33 Camberwell Road Hawthorn East VIC 3123 www.areal.com.au				
have received this e-mail in error, any use, copy system and its related sub system and notify the	nce and the information contained in this and associated e- ying or inference with this information is unauthorized and p e sender. You must never copy, disclose, make conclusion pproved or agreed by it. Although Areal Property has taken	prohibited and please immedians and other information in this	ately delete it and any relate message that do not relate	d attachments or en	mails from your
From: Chawakorn K Sent: Friday, 9 May To: Sylvia Hao < sylv	Camnuansil < <u>ck.chawako</u>			n St	
Hi Sylvia,	eek since the plumber a		ad Thra wak	•	

progress on the condition of my unit. I had already sent photos clearly showing wall damage — fixing the leak alone doesn't resolve everything.

This unit is carpeted, and the leak went on for days. It's only logical to assume the carpet and underlay have been affected too. Does it really make sense to think the issue ends with the hot water pipe?

Also, why has there been complete silence? It's not even during a public holiday period this time, and yet I'm still left waiting with no information. Is the delay coming from the building manager, or is the owner just not interested in maintaining their own property?

I've been patient long enough. Please advise what steps are being taken regarding both the wall and the carpet, and whether an inspection will be arranged.

Regards,

Chawakorn

If you have any feedback regarding my service, please feel free to contact my manager.

Jamie Ong (Head of Property Management) jamie.ong@areal.com.au

DISCLAIMER & WARNING. This correspondence and the information contained in this and associated e-mails are confidential and were only intended for the exclusive use of the addressee(s). If you have received this e-mail in error, any use, copying or inference with this information is unauthorized and prohibited and please immediately delete it and any related attachments or emails from your system and its related sub system and notify the sender. You must never copy, disclose, make conclusions and other information in this message that do not relate to the business of the Areal Property and shall be understood as neither given nor approved or agreed by it. Although Areal Property has taken reasonable precautions to ensure no viruses are present in this e-mail, Areal Property cannot accept responsibility for any loss or damage arising from the use of this e-mail or attachments.

Click to unsubscribe from future email communication