

FIGURE 3.10 Shock angle versus inlet Mach number and turning angle [1]. Curves above dashed line hold for $M_2 < 1$, and curves below hold for $M_2 > 1$. (From Shapiro [1].)




FIGURE 3.11 Stagnation pressure ratio versus inlet Mach number, with turning angle as parameter [1]. Curves above dashed line hold for $M_2 > 1$, and curves below hold for $M_2 < 1$. (From Shapiro [1].)




FIGURE 3.12 Exit Mach number versus inlet Mach number, with turning angle as parameter [1]. Curves above dashed line correspond to small σ , and curves below correspond to large σ . (From Shapiro [1].)