XNOR - A.B + A.B XOR = A.B + A.B A - B + A . B = por distail bution. A.A+A.B+B.A+B.B bac camblements + A.B + B.A + 0 0 por conmutativa A-B 4 A.B



