Exam Code: 350-021

Exam Name: CCIE SP Cable Qualification Exam

Vendor: CISCO

Version: DEMO

Part: A

1: A router is set to boot from flash, but cannot find boot commands in the configuration. Also, valid files do not exist in the default flash device. The router will:

A.Boot from ROM, since there are no valid sources

B.Try to boot from the network, using a default filename

C.Terminate the boot process with an error message

D.Try to boot from the network, then boot from ROM as a backup

Correct Answers: D

2: A network administrator is using debug commands to check the performance of a network. What steps can the administrator take to ensure that the "debug" will not require too much CPU, or at least that she will not have to reboot the router to disable debug? (multiple answer)

A.Make the debug command as specific as possible

B.Use the max-time parameter of the debug command

C.In configuration mode, enter scheduler interval 15

D.Configure a loopback to channel debug traffic

Correct Answers: A C

3: If there are two different headends with two different frequencies available sharing the same plant, what frequency will the two groups of cable modems, which are brand new, and have never been on-line, lock on?

A.They will lock on the frequency configured on the linecard.

B. They will lock on the frequency configured on the upconverter.

C.They will lock on the first frequency they find.

D.They will lock on the lowest frequency.

E.They will lock on the last frequency remembered in ram.

Correct Answers: C

4: Which are HFC cable television forward path networks aligned to provide? (multiple answer)

A.For asymmetrical gain since the downstream and upstream bandwidths are also asymmetrical

B.For unity gain with a fixed input level and varying output levels adjusted by the selection of a fixed value attenuator and equalizer at the output stage in each of the forward amplifiers in the network

C.For unity gain with a fixed output level and varying input levels adjusted by the selection of a fixed value attenuator & equalizer at the input stage of each of the forward amplifiers in the network

D.It is not necessary to align the forward path amplifiers since the CMTS will automatically compensate for forward path gain discrepancies.

E.For unity gain and are level compensated by automatic gain and slope control systems utilizing RF pilot reference carriers

Correct Answers: C E

5: HFC cable television return path networks are aligned to provide: (multiple answer)

A.Asymmetrical gain since the downstream and upstream bandwidths are also asymmetrical B.Unity gain with a fixed input level and varying output levels adjusted by the selection of a fixed value attenuator and equalizer at the output stage in each of the return amplifiers in the network C.Unity gain with a fixed output level and varying input levels adjusted by the selection of a fixed value attenuator and equalizer at the input stage of each of the return amplifiers in the network D.Cable modems the ability to power range comfortably within their output power dynamic range E.It is not necessary to align the return path amplifiers since the CMTS will automatically adjust the cable modem transmit power levels.

Correct Answers: B D

6: Cisco recommends the use of a headend-grade coaxial cable or a quad-shield coaxial cable with a minimum of 60% + 40% braid and double foil insulation to connect the cable modem cards to the HFC network. The center conductor must be straight and extend 1/8 inch (3.2 mm) beyond the end of the connector, and the connector should be securely crimped to the cable. Select three recommended cable types that can be used to connect the Cisco uBR7200 series universal broadband routers: (multiple answer)

A.RG 58

B.RG 59

C.RG 59/U

D.RG6

E.RG7

Correct Answers: B C D

7: Given a PAL HFC and 8 MHz channel lineup in the downstream, is it possible to utilize 6 MHz DOCSIS cable modems and signals on the network?

A.No, only 8 MHz channel spacing is available for Downstream data signals

B. Yes, as long as the 6 MHz DOCSIS signal is within a valid 8 MHz channel

C.Yes, as long as the DOCSIS signal is upconverted through a PAL upconverter

D.No, DOCSIS cannot be mixed with EuroDOCSIS in the Donwstream

E.DOCSIS must be used only in an EIA-542 channel plans

Correct Answers: B

8: In a cable HFC plant, which devices are modulators? (multiple answer)

A.CMTS line card

B.Upconverter

C.Diplex filter

D.Set top box

E.Fiber node

Correct Answers: A D

9: Unity gain is being used for alignment. The first amplifier from the node has 25 dB of gain and is 2000 feet away with cable loss of 1 dB per 100 feet. The node has an output of 35 dBmV at 55.25 MHz. What is the input at the amplifier?

A.13dBmV

B.3dBmV

C.15dBmV

D.27dBmV

Correct Answers: C

10: There are two different headends with two different frequencies available sharing the same plant. There is a -10dB cable loss to the second active in the cascade. What is the required pad for balancing

A.A 0 pad

B.A 1 pad

C.A 2 pad

D.A 3 pad

E.A 4 pad

F.A 5 pad

Correct Answers: F

11: A DOCSIS 2-way data system is being designed to limit upstream traffic. Unknown modems should be kept from using precious Upstream bandwidth. Given these requirements, it should beensured that the DOCSIS configuration file has what set?

A.Exam Code-specific information field

B.Max-cpe should be set to 1

C.CMTS authentication field should be set

D.Network Access should be set to 0

E.Downstream frequency should be set above 450 MHz

Correct Answers: D

12: The name of the DOCSIS config file to download will be offered to the cable modem in what DHCP field?

A.giaddr

B.config-filename

C.packet-filename

D.siaddr

Correct Answers: C

13: Every time a typing mistake is made at the exec prompt of a router, the message from the router indicates a lookup is being performed. Also, there is a waiting period of several seconds before the next command can be typed. Can this behavior be changed?

A.No, this is a built in feature of Cisco IOS? software.

B.Yes, use the no ip domain-lookup command.

C.Yes, use the no ip helper-address command.

D.Yes, use the no ip multicast helper-map command.

E.Yes, use the no exec lookup command.

Correct Answers: B

14: Upon deleting an IOS image file from flash, an execution of show flash shows the file still in flash, with a 'D' preceding it (as shown in the exhibit). What step must be taken in order to remove the file completely?

```
stllab-8510>sh bootflash
-#- ED --type-- --crc--- -seek-- nlen -length- -----date/time----- name
1 .. unknown 9DA13DA5 3576AC 31 3241516 Aug 22 1998 08:34:22 cat8510c-in
2 .D unknown 8CDE134F 453BA3 22 2494584 Jul 20 1997 09:33:02 cat8510b-in
```

A.Erase the file from flash

B.Format the flash device

C.Replace the flash card - it is defective

D.Execute a squeeze command on the flash device

Correct Answers: D

15: What effect will this configuration command have?

line vty 04

no password vtypassword

```
A company has been assigned the Class B address of 191.8.0.0 by the NIC. They have decided
              to use a subnet mask of 255,255,255.0 and an autonomous system number of 1,
The configuration for Router A is as follows:
                                                                The configuration for Router B is as follows:
                                                                RouterB#show running-config
Router A#show running-config
Current configuration:
                                                                Current configuration:
                                                                version 11.3
version 11.3
                                                                1.) hostname RouterB
1.) hostname RouterA
2.) enable-password enablepassword
                                                                     enable-password san-fran
                                                                3.) interface tokenring 04.) ip address 191.8.2.1 255.255.255.0
3.) interface ethernet 0
4.) ip address 191.8.1.1 255.255.255.0
5.) no mop enabled
                                                                5.) ring-speed 16
                                                                6.) interface serial 0
7.) ip address 191.8.150.2 255.255.255.0
8.) ip name-server 255.255.255
6.) interface serial 0
7.) ip address 191.8.150.1 255.255.255.0
8.) ip name-server 255.255.255.255
9.) ip host RouterB 191.8.150.2 191.8.2.1
                                                                9.) ip host A 191.8.2.1 191.8.150.1 10.) snmp-server community ccie
10.) snmp-server community ccie
11.) line vty 0 4
                                                                11.) logging buffered
                                                                12.) line vty 0 4
12.) login
                                                                13.) login
13.) line con 0
                                                                14.) line con 0
14.) line aux 0
15.) line vty 0
                                                                15.) line aux 0
16.) line vty 0
16.) password vtypassword
                                                                17.) password cisco
17.) line vty 1
18.) password vtypassword
                                                                18.) line vty 1
19.) line vty 2
                                                                19.) password cisco
20.) password vtypassword
                                                                20.) line vty 2
21.) line vty 3
                                                                21.) password cisco
                                                                22.) line vty 3
22.) password vtypassword
23.) line vty 4
                                                                23.) password cisco
24.) line vty 4
24.) password vtypassword
                                                                25.) password cisco
26.) end
25.) end
Router A#
                                                                RouterB#
```

A.All telnet connections to the router will be denied.

B.Only one telnet connection at the router will be allowed at a time.

C. Virtual terminal sessions will not be able to enter enable mode.

D. Virtual terminal sessions will not be asked a user-level password.

E.It will have no effect.

Correct Answers: A