

Vendor: HP

Exam Code: HP0-S27

Exam Name: Implementing HP BladeSystem Solutions

Version: DEMO

QUESTION 1

Your customer wants to stack three enclosures installed in the same rack in a single Virtual Connect domain and wants to know which enclosure should be selected as the base enclosure. Which statement about base enclosures is true?

- A. An enclosure with redundant Onboard Administrator modules must be selected as the base enclosure.
- B. It is best practice to select the most populated enclosure as the base enclosure.
- C. The enclosure that has the most current Onboard Administrator firmware automatically becomes the base enclosure.
- D. Any enclosure can be selected as the base enclosure.

Answer: D

QUESTION 2

Which Onboard Administrator functionality allows you to automatically assign an IP address for c-Class interconnects?

- A. Enclosure Bay IP Addressing
- B. c-Class I/O Module Configuration Utility
- C. Virtual Connect Ethernet First Time Wizard
- D. Integration with HP Management software

Answer: A

QUESTION 3

Your customer is implementing a P4000 SAN solution connected to a c3000 Server Blade enclosure. Which interconnect option should you recommend for this environment?

- A. Brocade 8Gb SAN Switch
- B. Cisco MDS9124e
- C. Virtual Connect FlexFabric module
- D. HP 3Gb SAS Switch

Answer: C

QUESTION 4

How many uplinks can you configure per HP Virtual Connect 8Gb 20-port Fibre Channel module?


- A. 4
- B. 8
- C. 20
- D. 28

Answer: A


QUESTION 5

DRAG DROP

Click the Task button. You want to configure HP SIM to periodically compare the configuration of managed nodes. Place the recommended steps for accomplishing this in the correct order.



Answer:



QUESTION 6

A system administrator wants to access HP SIM via a browser. Which URL should be typed into the browser address bar to access the HP SIM login page?

- A. http://<MachineName>:2301
- B. http://<MachineName>:50000

- C. https://<MachineName>:2381
- D. https://<MachineName>:50000

Answer: D

QUESTION 7

Which features have been enhanced in the 6.0 release of HP SIM? (Select two.)

- A. virus detection
- B. Onboard Administrator integration
- C. License Manager
- D. storage essentials
- E. reporting

Answer: CE

QUESTION 8

Click the Exhibit button.



A customer asks about the blue question mark next to Version Control, which is shown in the exhibit. What does the blue question mark indicate?

- A. HP Version Control is not up to date.
- B. HP Version Control Agent is not configured.
- C. HP SIM is running in third-party compatibility mode.

D. HP SIM events need to be cleared.

Answer: B

QUESTION 9

Which VMware product enables IT organizations to provide self-service provisioning and management capabilities to internal teams?

- A. VMware Site Recovery Manager
- B. VMware Lab Manager
- C. VMware View
- D. VMware vCenter

Answer: B

QUESTION 10

An incorrect IP address has been configured on your blade switch. How do you correct this problem?

- A. Update your firmware on the Onboard Administrator.
- B. Run erase from SmartStart using Virtual Media.
- C. Remove and then replace the blade switch in the enclosure.
- D. Use the Command Line Interface through the Onboard Administrator.

Answer: D

QUESTION 11

You are working on a rack containing three c7000 enclosures. What provides you with the most information about enclosure status?

- A. Insight Display
- B. Integrated Management Log
- C. HP System Management Homepage
- D. Integrated Lights Out Log

Answer: A

QUESTION 12

Which interconnect module provides 16 uplink ports and 16 downlink ports, all capable of supporting 40Gbps bandwidth?

- A. HP BLc 4X QDR IB Switch for HP BladeSystem c-Class
- B. Cisco Catalyst Blade Switch 3120G/X for HP BladeSystem c-Class
- C. HP StorageWorks 3Gb SAS BL Switch for HP BladeSystem c-Class
- D. HP ProCurve 6120XG for HP BladeSystem c-Class

Answer: A

QUESTION 13

What may be needed to connect a SB40c with a full-height server?

- A. PCI Expansion Blade
- B. FC mezzanine card
- C. Flex10 Virtual Connect card
- D. PCI Express mezzanine pass-thru card

Answer: D

QUESTION 14

What should be identified as part of a troubleshooting action plan?

- A. opportunities for additional products and services
- B. specific root causes for the specified mode of failure
- C. current OS and virtualization solutions supported by HP
- D. scalability requirements and planned growth

Answer: B

QUESTION 15

Which HP Care Pack Service is categorized as High Availability?

- A. Proactive Select
- B. Proactive 24
- C. Support Plus 24
- D. Critical Service

Answer: D

QUESTION 16

Which key benefits are provided by HP UPS units? (Select three.)

- A. protection from power spikes
- B. increased power efficiency
- C. power conversion to DC output
- D. reduced noise and heat
- E. increased uptime

Answer: ABE

QUESTION 17

A customer decides to use an MSA2000sa as additional storage for the storage blades in their enclosure. Which components are required as part of the enclosure solution to enable this functionality? (Select two.)

- A. blades with embedded P400 Controllers
- B. blades with P700 Controller mezzanine cards
- C. an HP StorageWorks 3Gb SAS BL Switch

- D. an HP InfiniBand Switch
- E. an HP StorageWorks 600 Modular Disk System

Answer: BC

QUESTION 18

Which resource can be used to determine total cooling requirements for a proposed HP BladeSystem solution?

- A. Insight Display
- B. Onboard Administrator
- C. Product Bulletin
- D. BladeSystem Power Sizing Tool
- E. Performance Quick Reference Tool

Answer: D

QUESTION 19

Which function in the HP P4000 Storage Solution provides online scalability within volumes and across pools?

- A. SAN/IQ Storage Clustering
- B. SAN/IQ Multi-Site SAN
- C. Automatic Data Center Mirroring
- D. Centralized Management Console

Answer: A

QUESTION 20

On a server running HP Data Protector Express the customer wants to connect a c-Class tape blade. Which HP resource is used to install the required driver for the SC44Ge SAS HBA?

- A. HP Library & Tape Tools
- B. HP Software Update Manager
- C. HP StorageWorks Tape CD-ROM
- D. HP Version Control Manager

Answer: C

Thank You for Trying Our Product

Braindump2go Certification Exam Features:

- ★ More than 99,900 Satisfied Customers Worldwide.
- ★ Average 99.9% Success Rate.
- ★ Free Update to match latest and real exam scenarios.
- ★ Instant Download Access! No Setup required.
- ★ Questions & Answers are downloadable in PDF format and VCE test engine format.



- ★ Multi-Platform capabilities Windows, Laptop, Mac, Android, iPhone, iPod, iPad.
- ★ 100% Guaranteed Success or 100% Money Back Guarantee.
- ★ Fast, helpful support 24x7.

View list of all certification exams: http://www.braindump2go.com/all-products.html

























10% Discount Coupon Code: BDNT2014