Do not copy and/or distribute without permission.

CONFIDENTIAL

Deviation Report

Report Information			
Title:	Lasair particle monitoring equipment stopped recording results after first 400L sample	Priority:	Major
Status:	In Progress	Deviation Type:	Equipment
Date of Occurrence:	March 21, 2025	Department(s):	QA
Batch/Lot Number:	10000062	Quantity Impacted:	entire batch
Planned Deviation:	No	Initiator:	Matt

User Input - Original Deviation Description

On 21MAR2025, the Lasair particle monitoring equipment and stopped recording results after the first 400L sample was taken on the data printout. Review of the instrument shows that it sampled continuously from 0838 to 1631 on 21MAR2025, however the print out states "invalid" with no alerts or alarms with no particle quantification.

AI-Generated Analysis

Report Generated: August 08, 2025 03:21 AM | CostPlus Drug Company CONFIDENTIAL - Do not copy and/or distribute without permission