


- i. See Mathcad code
- ii. See Mathcad code
- iii. Repeat (ii) for 100 rpm




iv. Repeat (ii) for die diameter of 2 mm



v. Repeat (ii) for metering zone temperature of 90 C



vi. Repeat (ii) for 20% moisture content of dough



vii. Repeat (ii) for the case when you have 3 dies in the die assembly

