

Hand

(Set upper
collimator)

Keyboard
Handler

Data Entry
Complete

Offset parameters

Mode/energy

Mode/Energy Offset (MEOS)

Calibration
tables

Reset

Datent

Set Up Done

Set Up Test

Patient Treatment

Pause Treatment

Terminate Treatment

Date, Time, ID Changes

Treat

0

1

2

3

4

5

6

7

Tphase
control
variable