No. TB-350 001

Product:	Description	Date
Pressure Gauge	Docietanes Chart	Oct 04
Type:	Resistance Chart	Issue
Electrical		1

MEASURI	NG RA	NGE:	80 PS	I					10 -	- 192 C	HMS
PSI	0	10	20	30	40	50	60	70	80		
О	10	36	61	84	108	132	156	179	192		
MOVEMEN	UN TV	MBER	999 0	10 009	9						

REVISION 'B' (APR '95)

DIAL 999 040 007 999 040 030

MEASURI	NG RA	NGE -	SECO	ONDAF	RY SC	ALE: 5	BAR		10 - 1	92 OH	MS		
BAR	0	1	2	3	4	5							
0	10	48	82	116	151	184							
MOVEMEN	MOVEMENT NUMBER:												

REVISION 'B' (APR '95)

REFERENCE

MEASURII	NG RA	NGE:	80 PS	l					240 -	33.5 C	OHMS		
PSI	0	10	20	30	40	50	60	70	80				
0	240	196	153	125	103	87	67	50	33.5				
MOVEMEN	MOVEMENT NUMBER: 999 010 003												

REVISION 'B' (APR '95)

DIAL 999 040 006 999 040 028

MEASURI	NG RA	NGE -	SEC	ONDA	RY SC	ALE:	5 BAR		240 -	33.5 C	OHMS
BAR	0	1	2	3	4	5					
0	240	175	128	97	71	46					
MOVEME	NIT NILI	MBED		-	•		•	•		•	

REVISION 'B' (APR '95)

REFERENCE

MEASURII	NG RA	NGE:	5 BAR						10	-180 C	OHMS		
BAR	0	0.5	1	1.5	2	2.5	3	3.5	4	4.5	5		
BAIL 0 0.5 1 1.5 2 2.5 5 5.5 4 4.5 5													
О	10	30	48	65	82	99	116	134	151	168	184		
MOVEMEN	UT NILI	MRED	999 0	10 000	3								

REVISION 'B' (APR '95)

DIAL 999 040 003 999 040 026

MEASURII	NG RA	NGE:	100 P	SI					10 -	· 180 C	OHMS	
PSI	0	10	20	30	40	50	60	70	80	90	100	
0	10	34	52	69	84	97	108	121	137	155	180	
MOVEMEN	MOVEMENT NUMBER: 999 010 009											

REVISION 'B' (APR '95)

DIAL 999 040 008 999 040 031

MEASURI	NG RA	NGE -	SECO	ONDAF	RY SC	ALE: 7	BAR		10 - 1	80 OH	MS
BAR	0	1	2	3	4	5	6	7			
О	10	42	67	88	105	124	149	181			
MOVEMEN	I IN TI	MBFR	999 (10 008	3						

REVISION 'B' (APR '95)

MEASURI	NG RA	NGE:	100 P	SI					240 -	33.5 C	OHMS		
PSI 0 10 20 30 40 50 60 70 80 90 100													
0	240	188	160	138	121	103	92	76	60	46	33.5		
MOVEMEN	MOVEMENT NUMBER: 999 010 003												

REFERENCE

100	[
33.5	

REVISION 'B' (APR '95)

Automotive

DIAL 999 040 029 999 040 050

REVISION 'B' (APR '95)

REFERENCE

MEAS	JRING F	RANGE	- SEC	CONDA	ARY S	CALE:	7 BAR	2	240 - 3	3.5 OF	IMS
BAR	0	1	2	3	4	5	6	7			
0	240	173	140	118	96	73	52	33			
MOVEM	ENT NU	MBER	: 999 C	10 003	3						

MEASURII	MEASURING RANGE: 150 PSI 10-189.5 OHMS															
PSI	0	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
0	10	26	40	53	67	78	90.5	103	115	127	138	149	160	169	178	189.5
MOVEMEN	UN TV	MBER:	999 0	10 009	9											
MEASURII	NG RA	NGE -	10 B	AR					10-1	89.5 C	HMS		REVI	SION '	B' (AF	PR '95)

REVISION 'B' (APR '95)

DIAL NUMBER: 999 040 009

999 040 032

MEASURING RANGE - 10 BAR 10-189.5 OI											
BAR 0 2 4 6 8 10											
0 10 52 88 124 155 184											
MOVEMENT NUMBER:											

REFERENCE

MEASURING RANGE: 150 PSI 240 - 33.5 OHM												
PSI	0	15	30	45	60	75	90	105	120	135	150	
0	240	188	160	138	121	103	92	76	60	46	33.5	
MOVEMENT NUMBER: 999 010 003												

REVISION 'B' (APR '95)

DIAL 999 040 043 999 040 053

MEASURII	0 - 33.	5 OHN	/IS									
BAR 0 2 4 6 8 10												
0	240	162	125	96	67	37						
MOVEMENT NUMBER: 999 010 003												

REFERENCE

MEASURING RANGE - 10 BAR 10 -180 OHMS												
BAR 0 1 2 3 4 5 6 7 8 9 1											10	
0	0 10 31 52 71 88 106 124 140 155 170 184											
MOVEMENT NUMBER: 999 010 009												

REVISION 'B' (APR '95)

DIAL 999 040 004 999 040 027 999 040 049

	MEASURII	10 -180 OHMS										
PSI 0 30 60 90 120 150												
	0 10 55 90 127 162 189											
	MOVEMENT NUMBER:											

999 040 058 REVISION 'B' (APR '95)

MEASURING RANGE: 25 BAR 10 - 180 OF											
BAR 0 2.5 5 7.5 10 12.5 15 17.5 20 22.5											25
0	10	32	53	73	92	101	125	143	155	169	184
MOVEMENT NUMBER: 999 010 009											

REFERENCE

REVISION 'D' (APR '95)

DIAL 999 040 005

MEASURING RANGE: 400 PSI 10 - 184 OF											
PSI	0	50	100	150	200	250	300	350	400		
0	10	36	66	82	103	125	141	161	184		
MOVEMENT NUMBER: 999 010 009											

REVISION 'B' (APR '95)

DIAL 999 040 010 999 040 033

MEASURII	NG RA		10 - 1	84 OH	MS						
BAR	0	5	10	15	20	25					
0 10 50 69 110 136 169											
MOVEMENT NUMBER: 999 010 008											

REVISION 'B' (APR '95)

REFERENCE