

CW

SNO.	1	2	3	4	5	ABN.TYPE	OTHER	UDL	KGP	UDL	BWN	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
	CW	CW	CW	CW	CW							UDL7921	CHANDRASHEKHAR SAH	GD	01-06-2026	12:40			YS	APPUSER	60218	SREE	C/CONT	03-06-26 21:09	KGP	N	DETAIL:Modified Brave Van No ER 87022611834 BVCM Return Date 08/30 In This Brake Van Doors Key Missing Same Brake Van Of BPC BPC No 70000108198 Cc Rake Issue Date 14/05/2026 NMP/KGP/SER	CLOSE_REM:As per C&W Department, TM Chandrashekhar Sah (Mobile No.: 9046243632) stated that the keys to the brake van at UDL were not handed over to him by the previous TM. We referred the matter back to HWH for further action; however, HWH repeatedly sends us back without providing any concrete reason. The C&W/TFC Department at HWH is failing to take appropriate action; they are merely stalling the matter.	APP_REM:@CWCKGP/02-06-2026 14:23-As per TM CHANDRASHEKHAR SAH Mobile No 9046243632 Brake Van Key Was not handed over to him by last TM at UDL.This is not a C&W Issue.Kindly informed to Concern department.	02-06-2026 14:23	01-06-2026 12:45
	OTHER	OTHER	OTHER	DOORS				NGP	KGP	BSL	NGP	NGP7337	SAPAN R. POTBHARE	GDM	01-06-2026	13:30	446/03	837/24	YS	APPUSER	37007	AQE	12859	02-06-26 11:01	KGP	Y	DETAIL:No Chair In LWLRRM SER221587 EX CSTM TO HWH .It Is Very Difficult To Work Without Chair . There Is Not a Single Chair For Sitting In Entire LWLRRM SER 221587 .Not For Train Manager & Not For Power Car Staff.Please Arrange Atleast One Chair For Train Manager For Smooth Working.	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed to primary depot SRC/PDPK to attend the issue on date 02/06/26 during Primary Maintenance.	APP_REM:@CWCKGP/02-06-2026 02:21-Noted Matter Informed to primary depot SRC/PDPK to attend the issue on date 02/06/26 during Primary Maintenance.	02-06-2026 02:21	01-06-2026 13:58
	PRYJ	PRYJ	BZA	PRYJ				KGP	KGP	RCG	KHT	BZA7721	CHESWARA RAO	GDM	02-06-2026	17:06	61/30	61/28	YS	APPUSER	30429	TKDE	12864	04-06-26 06:53	KGP	Y	DETAIL:BP Suddenly Dropped And Recreated Between RCG - KHT at 61/30 Km (17.06-17.09 Hrs)	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to check rake during Primary Maintenance on 04/06/26.	APP_REM:@GTLCDWD/02-06-2026 23:09-Forward to PM depot SRC/KGP division SER@CWCKGP/03-06-2026 22:13-Noted. Message given to SRC Depot to check rake during Primary Maintenance on 04/06/26.	03-06-2026 22:13	02-06-2026 17:36
	KGP	KGP	KGP	KGP				PRYJ	PRYJ	DDU	DDU	PRYJ7793	DINESH KUMAR II	SGD	02-06-2026	23:25			YS	APPUSER	37492	BLEE	22858	04-06-26 06:53	KGP	Y	DETAIL:Corridor door is defective. LS5A No. SER 255413	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:08-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:24-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	03-06-2026 22:24	02-06-2026 23:27
	PRYJ	PRYJ	PRYJ	PRYJ				YS	APPUSER	37492	BLEE	22858	04-06-26 06:53	KGP	Y	DETAIL:Working / Writing table is very small, please provide standered size working table. LWLRRM No. SR 195422									Y	DETAIL:Working / Writing table is very small, please provide standered size working table. LWLRRM No. SR 195422	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:08-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:25-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	03-06-2026 22:25	02-06-2026 23:32	

11	10	9	8	7	6	SNO.
CW	CW	CW	CW	CW	CW	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	OTHER	OTHER	SUBHEAD
DDUN	NGP	BZA	PRYJ	PRYJ	PRYJ	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
DDU	NGP	GNT	PRYJ	PRYJ	PRYJ	FROM
CNBN	BSL	NBR	DDU	DDU	DDU	TO
DDUN7081	NGP7581	NDL1030	PRYJ7793	PRYJ7793	PRYJ7793	CREW/CLIID
SHYAM SUNDAR YADAV	AVADHESH KU. TIWARI	K.SATISH KUMAR	DINESH KUMAR II	DINESH KUMAR II	DINESH KUMAR II	CREW/CLINAME
SGD	GDM	LPM	SGD	SGD	SGD	DESIG
06-06-2026	05-06-2026	03-06-2026	03-06-2026	02-06-2026	02-06-2026	ABNDATE
06:38	00:15	02:20	00:40	23:45	23:35	ABN.TIME
125	000	05/30				FROMKM
459	000	05/32				TO KM
YS	YS	YS	YS	YS	YS	STATUS
APPUSER	APPUSER	CREW	APPUSER	APPUSER	APPUSER	FILLED BY
44395	37763	37598	37492	37492	37492	LOCO
DDUE	TATE	LGDE	BLEE	BLEE	BLEE	LOCO SHED
MJPJ	12222	18048	22858	22858	22858	TRAIN
06-06-26 21:23	05-06-26 13:26	04-06-26 06:50	04-06-26 06:50	04-06-26 06:50	04-06-26 06:53	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	RemStts
DETAIL:Revolving Chair OF BRAKE VAN Is Not Moving AND IS Fixed In Wrong Direction .kindly Fix It. B/VAN NO. ECOR 87122010247 BVCM R-10/2029 TRAIN NO. MJPJ LOCO NO 44395 BPC NO 50000898300 I /DATE-13/05/2026 NMP /KGP/SER CCR	DETAIL:ECOR 196768LWLRRM में डोंग बॉक्स की ऊंचाई ज्यादा होने से विंडो आधे से ज्यादा ढक गई है जो सुरक्षित परिचालन के लिए ठीक नहीं है।कृपया डोंग बॉक्स की ऊंचाई रेलवे बोर्ड के मानक के अनुसार कम करें।	DETAIL:FDU ACTEDON COACH NO 196610 B2,WHILE RESET OBSERVED NO INDICATION FDU	DETAIL:Demand of pest control. LWLRRM No. SR195422	DETAIL:Hand break rounding stopper rod not provide. LWLRRM No. SR 195422	DETAIL:All window glass is very dirty and cabin cleaning is not satisfactory. LWLRRM No. SR 195422	
CLOSE_REM:AS PER C&W DEPT Noted matter informed to BPC issuing station NMP to attend the issue on arrival at NRY/NMP.	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed to primary depot SRC to attend the issue on date 8/6/26 during Primary Maintenance.	CLOSE_REM:AS PER C&W DEPT Already message received from CWC/GNT regarding this matter. Same will be checked during Primary Maintenance at SHM/PDPK on 4/6/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	Closing Remarks
APP_REM:@CWCKGP/06-06-2026 20:48-Noted matter informed to BPC issuing station NMP to attend the issue on arrival at NRY/NMP.	APP_REM:@CWBSL/05-06-2026 07:47-CWC 46 ISSUED AND TO BE FORWARD TO PRIMARY DEPOT CWC KGP FOR ATTENTION. ALSO ISSUED TO TRAIN DESTINATION CWC PUNE.@CWCKGP/05-06-2026 10:49-Noted Matter Informed to primary depot SRC to attend the issue on date 8/6/26 during Primary Maintenance.	APP_REM:@CWCONTROL2/03-06-2026 07:28-Please Forward To KGP division for Further Disposal During Maintenance @CWCKGP/03-06-2026 22:33-Already message received from CWC/GNT regarding this matter. Same will be checked during Primary Maintenance at SHM/PDPK on 4/6/26.	APP_REM:@MGSCW/03-06-2026 14:19-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:29-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:58-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:28-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:10-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:27-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	App Remarks
06-06-2026 20:48	05-06-2026 10:49	03-06-2026 22:33	03-06-2026 22:29	03-06-2026 22:28	03-06-2026 22:27	App Remarks Date
06-06-2026 13:57	05-06-2026 05:42	03-06-2026 03:59	03-06-2026 00:42	02-06-2026 23:45	02-06-2026 23:37	Reporting Date

14	CW	OTHER	NBQ	KGP	AYU	AZA	NBQ7340	ABHINANDAN KUMAR SINHA	SGD	08-06-2026	04:46	17/8-9	161	YS	APPUSER	31957	BIUE	UP AZA E-OIL	10-06-26 22:47	KGP	N	DETAIL:BV NO 87022612213 MODIFIED BVCM DOOR KEY AND BP PRESSURE GAGE NOT AVAILABLE BPC NO 50000904739	CLOSE_REM:As per traffic department, TM had not handover the key to YM. when we inquired with the TM, they said that, the incoming TM did not hand over the keys to the departing TM. and as per c&w dept 9:45-Brake van key is not maintained by C&W. Also during BPC issue from HLZ, no modified BP pressure gauge was there in this B/V & Guard fitted his own gauge through quick coupler.	APP_REM:@CWCKGP/09-06-2026 09:45-Brake van key is not maintained by C&W. Also during BPC issue from HLZ, no modified BP pressure gauge was there in this B/V & Guard fitted his own gauge through quick coupler.	09-06-2026 09:45	08-06-2026 10:33
13	CW	OTHER	TDL	KGP	CNBN	TDLN	TDL8763	RITESH KUMAR VERMA	GD	07-06-2026	15:06	460	724	YS	APPUSER	41626	TKDD	AJ 22	09-06-26 13:34	KGP	Y	DETAIL:BPC/No-50000902201Issue/HLZ GM-YD/KGP/SER Issue/DATE-24/05/2026 Brakevan/N-ACL/BVCM/87262310238 आखिर RDSO या अन्य जिम्मेदार संस्थाओं को क्यों नहीं असर हो रहा है कि BVCM ब्रेकवान से अत्यधिक कंपन,तीखी और कर्कश आवाज लगातार आती है जिससे बहरा होना स्वाभाविक है। क्या शोर सहने के सारे नियम को ताक पर रख दिया गया है। ये कौन लोग हैं जो BVCM ब्रेकवान को पास किए हैं। इनको एक इयूटी 10 घंटे की कराई जाए जिससे एक ट्रेन मैनेजर क्या झेलता है इनको पता लगे और यहां से सीधा नियमों में बदलाव के लिए स्वयं पहुंचें और BVZI को उपयुक्त ब्रेकवान स्वीकार करें। मोडिफिकेशन केवल BVZI में ही हो और लोको की तरह लॉग बुक हो जिसमें प्रदत्त सुविधाएं और कमियां नोट किया जाए तथा ब्रेकवान को लावारिस न छोड़कर चाभी द्वारा लॉक किया जाए। मात्र महीने भर के अंदर पंखा, लाइट, सोलर पैनल तथा एपॉक्सी रेसिन की जगह उपयोग में लाई गई प्लास्टिक भी चोरी कर ली जा रही है, ठोस कदम उठाया जाए।	CLOSE_REM:as per C&W dept The concern raised by you is noted. But it is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/09-06-2026 09:39-The concern raised by you is noted. But it is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	09-06-2026 09:39	07-06-2026 15:06
12	CW	OTHER	TPTY	KGP	SMVB	TPTY	TPTY7038	S.VIDYASAGAR	GDM	07-06-2026	10:20			YS	APPUSER	39385	BZAE	12864	08-06-26 09:46	KGP	Y	DETAIL:Guages Calibration overdue	CLOSE_REM:as per C&W dept Noted matter informed to primary depot SRC to attend the issues on date 9/06/26 during night shift	APP_REM:@GTLCDW/07-06-2026 12:34-Pertains To primary Maintenance depot SRC/KGP/SER ,forward to C&W KGP Division.@CWCKGP/08-06-2026 01:27-Noted matter informed to primary depot SRC to attend the issues on date 9/06/26 during night shift	08-06-2026 01:27	07-06-2026 12:25
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLEDBY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
20	CW	OTHER	NMP	KGP	HLZ	HSPG	NMP7457	LALTU BERA	GD	11-06-2026	03:30			YS	APPUSER	43671	KZIL	N/HSPG	11-06-26 22:44	KGP	Y	DETAIL:BV No Ecor 87122310064 T NO N /Hspg B/V Not Clean,Windo Not Working Condition And Commmode Broken.	CLOSE_REM:AS PER C&W DEPT The mentioned brake van was last given fit by HLZ , so matter informed to BPC issuing station HLZ to attend the issue on arrival.	APP_REM:@CWCNTLCKP/11-06-2026 17:38-Culprit BV No. - ECoR 87122310064 BVCM was last examined at HLZ/KGP/SER/50000907964/INT/09.06.26. Please forward the matter to KGP Division/SER.@CWCKGP/11-06-2026 21:32-The mentioned brake van was last given fit by HLZ , so matter informed to BPC issuing station HLZ to attend the issue on arrival.	11-06-2026 21:32	11-06-2026 04:00
21	CW	OTHER	DDUN	KGP	DDUN	CNBN	DDUN7099	RIZWAN JAMSHED KHAN	GD	11-06-2026	07:31	124	460	YS	APPUSER	42104	CNBE	HGJ	12-06-26 07:01	KGP	Y	DETAIL:BPC No.-50000963103Bksc/Adra/Ser BV No.- SECR 86141350969,Bvzi,,R-07/26 1-ब्रेक वैन की कुर्सी 8 से 10 घंटे कार्य करने लायक नहीं है कृपया WAG 12 लोको जैसी Cushioned Chair प्रदान करें। 2-ब्रेक वैन में पंखा व लाइट की व्यवस्था नहीं है तथा ब्रेक वैन में शौचालय हेतु कोई उत्तम व्यवस्था नहीं है यहां तक के एक कमोड तक नहीं लगा है। कृपया पंखा व लाइट सहित, शोरगुल व झटका रहित Modified BVZI ब्रेक वैन प्रदान करें।	CLOSE_REM:AS PER C&W DEPT The Brake Van was last examined at HLZ, but the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/11-06-2026 17:26-Noted matter informed to BPC issuing station HLZ to attend the issues on arrival at HLZ.@kgpuor/11-06-2026 22:39/COMPLY AGAIN.@CWCKGP/11-06-2026 23:09-The Brake Van was last examined at HLZ, but the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	11-06-2026 23:09	11-06-2026 07:37
22	CW	OTHER	CKP	KGP	CKP	NMP	CKP7292	JAWED RASHID	SGD	11-06-2026	10:17			YS	APPUSER	27037	DDUE	BCN/KPGM	11-06-26 22:44	KGP	Y	DETAIL:Working Door Broken	CLOSE_REM:AS PER C&W DEPT - The mentioned brake van ECR 86101065520 BVZI in present in the BPC 50000899169 , NMP, 16/05/26 so matter informed to BPC issuing station NMP to attend the issue on arrival.	APP_REM:@CWCKGP/11-06-2026 21:30-The mentioned brake van ECR 86101065520 BVZI in present in the BPC 50000899169 , NMP, 16/05/26 so matter informed to BPC issuing station NMP to attend the issue on arrival.	11-06-2026 21:30	11-06-2026 10:18
23	CW	OTHER	ASN	KGP	ASN	BCQ	ASN7643	YUGESH KUMAR SHARMA	SGD	11-06-2026	12:30			YS	APPUSER	44062	ASNIL	BCQ	12-06-26 23:31	KGP	Y	DETAIL:In modified Bvan- ER/11582 both pressure Gauge is missing and Bvan lock key not available	CLOSE_REM:AS PER C&W DEPT BPC - 70000110931, I/DT - 07/06/2026, I/STN - NMP/KGP/SER, RAKE - CC RAKE. B/V NO - ER 87022611582 BVCM. Message given to base depot NMP to check the matter & take necessary action, on arrival of rake at NMP.	APP_REM:@ABCW/11-06-2026 13:37- Brake Van Examined By NMP/KGP. not Pertain To C&W, Asansol @CWCKGP/12-06-2026 20:39-BPC - 70000110931, I/DT - 07/06/2026, I/STN - NMP/KGP/SER, RAKE - CC RAKE. B/V NO - ER 87022611582 BVCM. Message given to base depot NMP to check the matter & take necessary action, on arrival of rake at NMP.	12-06-2026 20:39	11-06-2026 13:31

SNO.	24	25	26	
ABN.TYPE	CW	CW	CW	
SUBHEAD	OTHER	OTHER	UNDER FRAME	
REPORTSTTN	DDUN	ANR	ADL	
REPORTDIV	KGP	KGP	KGP	
FROM	CNBN	UDL	HLZ	
TO	DDUN	ANR	ADL	
CREW/CLIID	DDUN7054	ANR7442	ADL7185	
CREW/CUNAME	DURGESH TIWARI	G.P.SANTIKARY	SAIKAT PACHHAL	
DESIG	GD	SGD	SGD	
ABNDATE	13-06-2026	13-06-2026	13-06-2026	
ABN.TIME	03:40	12:00	13:55	
FROMKM	460		HY7/5	
TO KM	124		HY7/4	
STATUS	YS	YS	YS	
FILLED BY	APPUSER	APPUSER	APPUSER	
LOCO	28326	32149	44251	
LOCO SHED	GTLE	BJUE	BNDL	
TRAIN	HP 32	E/NBOX ESSER	N/DSEY	
SMSTO LP	13-06-26 21:34	14-06-26 15:24	13-06-26 21:34	
Div	KGP	KGP	KGP	
RemStts	Y	Y	Y	
Detail	DETAIL:BPC/No-50000903103Issue/ST-BKSC/ADRA/SER Issue/DATE-26/05/2026 Validity -29/06/2026 Brakevan/N-SECR-86141350969 1.ब्रेकवान की वर्किंग कुर्सी पीछे की ओर झुकी है जो 11 घंटे की ड्यूटी के दौरान पीड़ादायक तथा झटको में रिस्की है, कृपया कुर्सी बदल दीजिए। 2.टॉयलेट शीट को इंडियन स्टाइल का बनाइए जिसकी महिला व पुरुष ट्रेन मैनेजर आसानी से उपयोग कर सकें 3.मोडिफिकेशन में पंखा,लाइट सोलर पैनल सब चोरी हो रही है, इसकी जवाबदेही तय करें तथा कोई स्थाई समाधान खोजें। 4.Provide Basic Facilities Like Light Fan Water Pvc Coating Internally And Fully Locked Brakevan With Universal Key. 5.In Modification, As Per Railway Board Letter No. 2013/M(N)/60/10 (E-3320409) New Delhi Dated- 23-04-2025,Train Manager side should be heard. Sound problem is as usual.	DETAIL:Solar System Is Not Working And Out Of Order Fan & Light..BV No-86151108581	DETAIL:There Is No LV Bracket Available In Working Side Of The Brake Van (ECR 67286)	
Closing Remarks	CLOSE_REM:AS PER C&W DEPT The Brake Van was last examined at HLZ, but after that BPC has long turned invalid. Also the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	CLOSE_REM:AS PER C&W DEPT BPC no. 7000010722, ex. NMP, dt. 05/05/26 (CC), rake name - NRY-118 (NEO), containing the mentioned B/V, so message given to base depot NMP to attend the issue on arrival.	CLOSE_REM:AS PER C&W DEPT BPC no. 50000908475, ex HLZ, dated 11/06/25 (Intensive) & B/V no. ECR 86101167286 BVZI. Message given to BPC issuing depot HLZ to attend the issue on arrival.	
App Remarks	APP_REM:@CWCNTLALD/13-06-2026 08:59-Train Running DFCC so Forward To DFCC.@CWCKGP/13-06-2026 14:02-The Brake Van was last examined at HLZ, but after that BPC has long turned invalid. Also the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@NATHCW/14-06-2026 02:38-The Said Nmt Was Last examination Done At Nmp So Complain Forwarded to Cwc/Kgp For necessary Action@CWCKGP/14-06-2026 12:54-BPC no. 7000010722, ex. NMP, dt. 05/05/26 (CC), rake name - NRY-118 (NEO), containing the mentioned B/V, so message given to base depot NMP to attend the issue on arrival.	APP_REM:@CWCKGP/13-06-2026 14:18-BPC no. 50000908475, ex HLZ, dated 11/06/25 (Intensive) & B/V no. ECR 86101167286 BVZI. Message given to BPC issuing depot HLZ to attend the issue on arrival.	
App Remarks Date	13-06-2026 14:02	14-06-2026 12:54	13-06-2026 14:18	
Reporting Date	13-06-2026 08:48	13-06-2026 12:04	13-06-2026 14:02	

SNO.	27	28	29
ABN.TYPE	CW	CW	CW
SUBHEAD	OTHER	OTHER	OTHER
REPORTSTTN	MLDT	MLDT	DDUN
REPORTDIV	KGP	KGP	KGP
FROM	RPH	RPH	DDUN
TO	RPH	RPH	CNBN
CREW/CLIID	MLDT7296	MLDT7296	DDUN7007
CREW/CLNAME	UTTAM KUMAR	UTTAM KUMAR	HIMANSHU SINGH I
DESIG	SGD	SGD	GD
ABNDATE	13-06-2026	13-06-2026	15-06-2026
ABN.TIME	23:00	23:45	09:47
FROMKM			
TO KM			
STATUS	SN	SN	YS
FILLEDBy	APPUSER	APPUSER	APPUSER
LOCO	24675	24675	28616
LOCO SHED	JHSE	JHSE	RTMD
TRAIN	ICDA	ICDA	GZB LH-II
SMSTO LP	14-06-26 15:24	14-06-26 15:24	17-06-26 21:51
Div	KGP	KGP	KGP
RemStts	Y	Y	Y
Detail	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE इस ट्रेन का BPC बनाया गया है और BV से पहला वैगन जिसका पिस्टन टूटा हुआ है जिसका नंबर CNCR 53252510858BLCSA है।BPC बनते समय वैगन को सही तरीके से जाँच नहीं की जाती है हमारे C &W स्टॉफ द्वारा। हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए ताकि BPC बनाते समय वैगन की जाँच सही तरीके से सुनिश्चित हो सके।	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE ब्रेक वन GIPL 87402110018BVCM इस ब्रेकवान में कुर्सी है लेकिन उस पर बैठ के 12 घंटे की झूटी कर पाना बहुत ही मुश्किल है कृपया इस ब्रेकवान के कुर्सी को बदला जाए ताकि रनिंग ट्रेन में झूटी से सही तरीके से हो सके।इस ब्रेकवान में आवाज बहुत ही ज्यादा है हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए और ब्रेकवान BVCM में रनिंग के समय बहुत ही ज्यादा आवाज और आइसोलेशन होता है BVCM ब्रेकवान को बिना आवाज और बिना आइसोलेशन के बनाया जाए जैसा कि BVZI ब्रेकवान होता है।	DETAIL:BPC-50000907796/Premium/BKSC/ADRA/SER Bv-NR87032510042 Dono side ke Chair pe back side me foam nhi lga hua h
Closing Remarks	CLOSE_REM:AS PER C&W DEPT Message given to base depot NMP to attend & rectify during next PME & also to tighten up examination.	CLOSE_REM:AS PER C&W DEPT The concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	CLOSE_REM:AS PER C&W DEPT BPC No-50000907130 Issued By HLZ With T/No-N/Bscs On Dt 07/06/26 With INT BPC, Which Is Valid For One Trip. After that Enroute Brake Van Was Attached With BPC No 50000907796 With Premium BPC. So Informed ADRA For Further Disposal Of Complain And Necessary Attention On Arrival.
App Remarks	APP_REM:@CWCKGP/14-06-2026 12:32-Message given to base depot NMP to attend & rectify during next PME & also to tighten up examination.	APP_REM:@CWCKGP/14-06-2026 12:40-The concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/16-06-2026 11:23-The Rake Was Examined & BPC Issued By BKSC, SoPlease Forward To BPC Issuing Station. BPC Issued On 09/06/26 & Valid Upto 21/06/26@CWCKGP/16-06-2026 11:23-The Rake Was Examined & BPC Issued By BKSC, SoPlease Forward To BPC Issuing Station. BPC Issued On 09/06/26 & Valid Upto 21/06/26@NATHCW/16-06-2026 23:44-The Said Nmt Was Last examination Done At HLZ So Complain Forwarded to CWC/KGP For necessary Action@CWCKGP/17-06-2026 20:44-BPC No-50000907130 Issued By HLZ With T/No-
App Remarks Date	14-06-2026 12:32	14-06-2026 12:40	17-06-2026 20:44
Reporting Date	13-06-2026 23:43	13-06-2026 23:54	15-06-2026 09:49

32	CW	31	30	SNO.
OTHER	CW	OTHER	CW	ABN.TYPE
TATA	OTHER	TATA	OTHER	SUBHEAD
KGP	TATA	KGP	NMP	REPORTSTTN
TATA	KGP	TATA	KGP	REPORTDIV
CKP	CKP	CKP	HDCB	FROM
TATA7506	TATA7506	TATA7506	KGP	TO
VIBHUTI KUMAR	VIBHUTI KUMAR	VIBHUTI KUMAR	NMP7538	CREW/CLIID
GD	GD	GD	SOURAV KUMAR TANTI	CREW/CLNAME
16-06-2026	16-06-2026	16-06-2026	GD	DESIG
10:30	10:30	10:30	15-06-2026	ABNDATE
253	253	253	18:31	ABN.TIME
315	315	315		FROMKM
YS	YS	YS		TO KM
APPUSER	APPUSER	APPUSER	YS	STATUS
24062	24062	24062	APPUSER	FILLED BY
JHSE	JHSE	JHSE	24062	LOCO
HSPG	ME/N/HSPG	ME/N/HSPG	JHSE	LOCO SHED
18-06-26 22:44	18-06-26 22:44	18-06-26 22:44	ME/N/HSPG	TRAIN
KGP	KGP	KGP	16-06-26 15:39	SMSTO LP
Y	Y	Y	KGP	Div
			Y	RemStts
DETAIL:Break Van Working Chair Broken..Bpc-50000908786 HLZ-GM-YD/KGP/SER 12/06/26 INTENSIVE.BVZI-NWR-86111086867(11-26)	DETAIL:Break Van Working Chair Broken..BPC NO-50000908786,HLZ-GM-YD/KGP/SER I/DT-12/06/26 INTENSIVE ..BVZI-NWR(86111086867)(R,11-26)	DETAIL:During Taking Charge From HDCB found Working Side Broken Chair, B/V No. NWR86867 BPC 50000908786 I/DT 12/06/26 I/STN HLZ GM YD. /KGP/SER TYPE END TO END		Detail
CLOSE_REM:AS PER C&W DEPT The mentioned Brake Van is given fit with mentioned BPC from HLZ, so message given to HLZ Depot for necessary action. Also message given to CWC/CKP to attend the matter on arrival at HSPG in their Division.	CLOSE_REM:AS PER C&W DEPT The mentioned Brake Van is given fit with mentioned BPC from HLZ, so message given to HLZ Depot for necessary action. Also message given to CWC/CKP to attend the matter on arrival at HSPG in their Division.	CLOSE_REM:AS PER C&W DEPT Message Given To BPC Issuing Station HLZ To Attend On Arrival.		Closing Remarks
APP_REM:@CWCNTLCKP/16-06-2026 17:43-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/17-06-2026 21:29-Kindly Inform Destination HSPG/ROU/CKP to Attend On Arrival. Also Informed Hlz For Necessary Action.@CWCNTLCKP/18-06-2026 07:58-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/18-06-2026 09:57-Mentioned	APP_REM:@CWCNTLCKP/16-06-2026 17:42-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/17-06-2026 21:28-Kindly Inform Destination HSPG/ROU/CKP to Attend On Arrival. Also Informed Hlz For Necessary Action.@CWCNTLCKP/18-06-2026 07:58-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/18-06-2026 09:57-Mentioned	APP_REM:@CWCKGP/16-06-2026 11:53-Message Given To BPC Issuing Station HLZ To Attend On Arrival.		App Remarks
18-06-2026 09:57	18-06-2026 09:57	16-06-2026 11:53		App Remarks Date
16-06-2026 10:48	16-06-2026 10:38	15-06-2026 18:35		Reporting Date

36	CW	OTHER	TDL	KGP	KRJN	CNBN	TDL9201	BHAGESH KUMAR MEENA	GD	18-06-2026	18:45	849	461	YS	APPUSER	60200	SREE	WDN 166	19-06-26 23:05	KGP	Y	DETAIL:Bpc 50000899569ब्रेकवान में लाइट एंड फैन नॉट वर्किंग B.V.no-ER/87022510533	CLOSE_REM:AS PER C&W ELECT DEPT B/V last examined (before generation of complaint) at HLZ & message given to HLZ depot for necessary action	APP_REM:@CWCKGP/19-06-2026 22:00-B/V last examined (before generation of complaint) at HLZ & message given to HLZ depot for necessary action.	19-06-2026 22:00	19-06-2026 02:29
35	CW	OTHER	ADI	KGP	ADI	ST	ADI7300	MANISH KUMAR KULSHRESTHA	GDM	16-06-2026	23:55	496	296	YS	APPUSER	37235	TATE	12833	17-06-26 22:01	KGP	Y	DETAIL:गाड़ी के REAR SLR में TM के लिये CHAIR नल्ले रुक	CLOSE_REM:as per C&W dept Noted, Matter Informed To Primary Depot To Attend On Arrival. However Additional Provision Of Chair For Perusal Of Guard On Request And Is Locally Arranged And Not Mandatory As Per RDSO design.	APP_REM:@CWCKGP/17-06-2026 21:41 -Noted, Matter Informed To Primary Depot To Attend On Arrival. However Additional Provision Of Chair For Perusal Of Guard On Request And Is Locally Arranged And Not Mandatory As Per RDSO design.	17-06-2026 21:41	16-06-2026 23:58
34	CW	OTHER	BZA	KGP	MBL	GDR	BZA7402	P.NEHRU	GDM	16-06-2026	16:17	136/31	136/29	YS	APPUSER	39512	PADX	12841	17-06-26 21:57	KGP	Y	DETAIL:FIBA activated Rear 4th Coach no SER LS5 255424 Genral. TxR staff attending and not rest, So Isolation condition fit for normal speed with along escort Txr Staff This is information Sir Thank You Sir	CLOSE_REM:as per C&W dept Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	APP_REM:@SSECNWBZA/17-06-2026 12:39-Forward abnormality to PM divn/KGP for thorough checking. Mean while at GDR C&W staff examined and tried to reset the FIBA but unable to reset due to FIBA malfunctioning. Hence isolated and ensured all air springs are inflated condition and allowed the train with normal speed upto destination.@CWCKGP/17-06-2026 19:05-Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	17-06-2026 19:05	16-06-2026 18:42
33	CW	OTHER	BZA	KGP	MBL	GDR	BZA2075	M.S.KUMAR G12	LPM	16-06-2026	15:16	136/8	136/6	YS	APPUSER	39512	PADX	12841	17-06-26 21:57	KGP	Y	DETAIL:FIBA activated in Coach No 255424 same was attended by TXR/GDR given fit For Normal Speed same was Escorted By TXR upto MAS	CLOSE_REM:as per C&W dept Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	APP_REM:@SSECNWBZA/17-06-2026 12:38-Forward abnormality to PM divn/KGP for thorough checking. Mean while at GDR C&W staff examined and tried to reset the FIBA but unable to reset due to FIBA malfunctioning. Hence isolated and ensured all air springs are inflated condition and allowed the train with normal speed upto destination.@CWCKGP/17-06-2026 19:05-Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	17-06-2026 19:05	16-06-2026 19:17
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

40	CW	OTHER	SBC	KGP	JTJ	SMVB	SBC7091	SAHOO RR	GDM	24-06-2026	23:38	214	001	YS	APPUSER	30313	LGDE	22887	25-06-26 13:46	KGP	Y	DETAIL:The TMR WRITING TABLE IS SLANTED And Unable To Write	CLOSE_REM:AS PER C&W DEPT Matter is noted & message given to SRC/PDPK on 26.06.26 & it will be attended on 26/27.06.26 during primary maintenance.	APP_REM:@CNWSBC/25-06-2026 08:58-Message Forwarded To Srdme KGP/SER for Necessary Attention @CWCKGP/25-06-2026 11:47-Matter is noted & message given to SRC/PDPK. Down Train No-22888 will arrive primary depot SRC/PDPK on 26.06.26 & it will be attended on 26/27.06.26 during primary maintenance.	25-06-2026 11:47	25-06-2026 00:10
39	CW	OTHER	TDL	KGP	CNBN	TDLN	TDL9076	ANURAG PRATAP	GD	23-06-2026	16:14	460	724	YS	APPUSER	32118	PTRX	TICD	24-06-26 21:08	KGP	Y	DETAIL:BPC No: 70000112323 (NMP/KGP/SER) I/DATE:- 19/06/2026 VALIDITY :- 18/06/2026 B/VAN No:NFR 87052110222/BVCM RETURN:- 05/30 इस ब्रेक वैन में बहुत ही कर्कश आवाज आ रही है, कृपया उचित सुधार करके , ब्रेक वैन की मूलभूत चीजें जैसे डोर लॉक , लाइट , फैन, सही तरीके की टेबल और पानी की टंकी की सुविधा करे ।	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed To BPC issuing Station NMP/SER to Attend During Examination.	APP_REM:@CWCKGP/24-06-2026 20:12-Noted Matter Informed To BPC issuing Station NMP/SER to Attend During Examination.	24-06-2026 20:12	23-06-2026 16:20
38	CW	OTHER	NMP	KGP	HU	KGP	NMP7611	NAVNEET KUMAR2	GD	21-06-2026	15:02			YS	APPUSER	42071	MLDD	E/N/SSPL	22-06-26 18:13	KGP	Y	DETAIL:While Taking Charge At HIJ BV key Not Received By HIJ/RRI of Modified BRAKE Van No.ER87022613319 BPC NO. 70000110676 I/S. UDL WDD-YD/ASN/ER I/D. 04/06/2026 C.C RAKE	CLOSE_REM:AS PER TRAFFIC DEPT Modified BV Key are not yet supplied to KGP/NMP based TMR.	APP_REM:@CWCKGP/21-06-2026 22:10-Hand over of brake van key is not resposnsibility of C&W, it shall be provided either from CREW/TMR or from yard master.	21-06-2026 22:10	21-06-2026 15:06
37	CW	OTHER	MAS	KGP	MAS	BZA	MAS7327	MUNI KUMAR. Y.S.	GDM	19-06-2026	07:05	5	6	YS	APPUSER	37494	EDE	12842	19-06-26 23:05	KGP	Y	DETAIL:In Bv Equipment Room Door Not Available..... Stretcher,rope Ladder, EL Box Also Not Available ... Kindly Pls Note.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC/PDPK depot to attend the issue during Primary maintenance on 20/21-6-26.	APP_REM:@SSECNWBZA/19-06-2026 09:01-Forward abnormality to PM divn / KGP to look into the matter.@CWCKGP/19-06-2026 21:50-Noted. Message given to SRC/PDPK depot to attend the issue during Primary maintenance on 20/21-6-26.	19-06-2026 21:50	19-06-2026 07:51
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date