

LOCO

8	7	6	5	4	3	2	1	SNO.
LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	ABN.TYPE
CAB2 AC NOT WORKING	CAB1 AC NOT WORKING	SEAT DEFECTIVE	CAB2 AC NOT WORKING	OTHER	CAB1 AC NOT WORKING	OTHER	CAB1 AC NOT WORKING	SUBHEAD
DGHA	SBP	MDP	ANGL	HWHS	TATA	GZB	TLHR	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HWH	KPIG	JAU	SBPY	DGHA	SRC	GZB	KLAG	FROM
DGHA	RAIR	CRJ	JRPD	HWH	TATA	ANVT	TLHR	TO
SRC1762	SBP1863	MDP1175	SBPY1020	SRC2384	SRC2078	DL0079	TLHR2844	CREW/CLIID
EL RAJEN GHOSH C	TIKU CHAND DEHURY	BIKASH BHAGAT	BHISMA KUMAR MAJHI	EL TRIDIB KR MAHAPATRA C	EL BISWAJIT HALDAR C	Raj Kumar MS	SANTOSH YADAV	CREW/CLINAME
LPG	LPG	ALP	LPG	LPP	LPM	Chief Loco Inspector	LPG	DESIG
08-06-2026	07-06-2026	07-06-2026	06-06-2026	05-06-2026	03-06-2026	03-06-2026	01-06-2026	ABNDATE
19:40	03:00	00:30	01:00	00:20	13:00	11:01	20:07	ABN.TIME
01	140			87	01			FROMKM
188	70			01	248			TO KM
YS	YS	YS	YS	YS	YS	YS	YS	STATUS
CREW	CREW	APPUSER	CREW	CREW	CREW	APPUSER	APPUSER	FILLED BY
22398	28575	27918	27534	37010	22896	30762	27227	LOCO
SRCE	KGPE	KGPE	KGPE	SRCE	SRCE	SRCE	KGPE	LOCO SHED
22897	DN/STD BY	EC/DHN	STAND BY	22898	12021	04013	ME/BOBRN(R)	TRAIN
09-06-26 20:57	08-06-26 12:52	08-06-26 12:52	06-06-26 21:23	05-06-26 18:14	04-06-26 14:11	03-06-26 20:50	02-06-26 13:30	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:AC NOT PROVIDED		DETAIL:Please Provide Proper Chair In This Locomotive. There Is No Chair Provided In This Locomotive.	DETAIL:AC NOT FITTED	DETAIL:AC NOT PROVIDED IN CAB,SO VERY UNCOMFORTABLE TO WORK.	DETAIL:BOTH CAB AC NOT WORKING DUE TO AC MCB DEFECTIVE.	DETAIL:Both Cabs & Corridor Both Side Locks Defecient. (Pb)	DETAIL:Both Cab Ac Not Provided	
CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Loco Will Be Send To Home Shed For Attention On Arrival At Kgp Div.	CLOSE_REM:AS PER LOCO DEPT Informed To Shed.	CLOSE_REM:AS PER LOCO DEPT Informed to Shed.	CLOSE_REM:as per loco dept Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Will Be Attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed.	Closing Remarks
APP_REM:@KGPLOCO/09-06-2026 11:58-Informed To Shed	APP_REM:@KGPLOCO/08-06-2026 12:03-Informed To Shed	APP_REM:@KGPLOCO/08-06-2026 12:03-Loco Will Be Send To Home Shed For Attention On Arrival At Kgp Div.	APP_REM:@SBPDPC/06-06-2026 09:13-Forward Message to KGP Div.@KGPLOCO/06-06-2026 12:12-Informed To Shed	APP_REM:@KGPLOCO/05-06-2026 13:26-Informed to Shed	APP_REM:@KGPLOCO/04-06-2026 11:37-Informed To Shed	APP_REM:@KGPLOCO/03-06-2026 18:12-Will Be Attended On Arrival At Srce Shed	APP_REM:@KGPLOCO/02-06-2026 11:12-Informed To Shed	App Remarks
09-06-2026 11:58	08-06-2026 12:03	08-06-2026 12:03	06-06-2026 12:12	05-06-2026 13:26	04-06-2026 11:37	03-06-2026 18:12	02-06-2026 11:12	App Remarks Date
08-06-2026 23:55	07-06-2026 11:26	07-06-2026 05:49	06-06-2026 08:55	05-06-2026 06:12	03-06-2026 13:14	03-06-2026 11:03	01-06-2026 20:09	Reporting Date

15	LOCO	14	13	12	11	10	9	SNO.
CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	OTHER	OTHERS CAB ISSUES	KAVACH	CAB1 AC NOT WORKING	CAB2 AC NOT WORKING	ABN.TYPE SUBHEAD
KGP	SBP	LTT	LTT	SNF	KOTA	BNDM	DDUN	REPORTS/TIN
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	REPORT/DIV
SRC	LPG	ATG	ATG	KZJ	NDLS	BSP	DDUN	FROM
KGP	LPG	ASO	ASO	SNF	KOTA	TATA	CNBN	TO
KGP1009	SBP1863	CSMT5341	CSMT5341	SNF2890	KOTA1045	OKP0128	DDUN1244	CREW/CLID
EL CHANDRA SEKHAR MAITY	TIKU CHAND DEHURY	C B SHIVSHARAN	ROSHAN BABU BADA 6G	ARVIND SINGH	RAJ NATH SINGH	Chief Loco Inspector	SHASHI KANT KUMAR II MUNNU	CREW/CLINAME
LPP	LPG	LPM	LPM	SALP	LPM		LPG	DESIG
12-06-2026	10-06-2026	10-06-2026	10-06-2026	10-06-2026	10-06-2026	09-06-2026	09-06-2026	ABNDATE
18:56	22:00	12:54	12:54	12:00	08:00	17:21	08:30	ABN.TIME
7	24	94/37	94/37	324			00	FROMKM
115	24	86/53	86/53	175			00	TO KM
YS	YS	YS	YS	YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	CREW	CREW	CREW	APPUSER	APPUSER	FILLED BY
30743	28203	39568	39568	27186		30804	28204	LOCO
SRCE	KGPE	SRCE	SRCE	KGPE		SRCE	KGPE	LOCO SHED
22807	STAND BY	13379	13379	KSNK	20452	20821	GPTH	TRAIN
13-06-26 21:01	11-06-26 22:48	10-06-26 22:33	10-06-26 22:48	11-06-26 22:48	12-06-26 15:59	10-06-26 14:21	10-06-26 14:21	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:BOTH SIDE CAB AC NOT PROVIDED		DETAIL:knorr brems display hang/stuckup with message FAULT PENALTY KEEP IN FS but loco responding normal with bp pressure 5.00kg/cm2 upto destination. once malfunctionjed and applied emergency brakes.	DETAIL:Loco seats not suitable for long working hours. ALP desk is extremely congested, there no space left to keep caution order.	DETAIL:NOT AVAILABLE N LOCOMOTIVE	DETAIL:Both cab AC not working loco 20804/SRC	DETAIL:Both Cab AC Not Provided		Detail
CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT - Loco Running In Mis Link , Mis Link Done By CSTM Div. Loco Will Be Attended On Arrival At KGP Div.	CLOSE_REM:AS PER LOCO DEPT Will Be Attended On Arrival At Kgpe Shed. Now Working in S. C. Railway.	CLOSE_REM:AS PER LOCO DEPT Fitting Of KAVACH In Every Loco Is On Progress. It will Be Completed Soon	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	APP_REM:@KGPLOCO/10-06-2026 11:32-Informed To Shed	Closing Remarks
APP_REM:@KGPLOCO/13-06-2026 18:20-Informed To Shed	APP_REM:@SBPDP/11-06-2026 04:10-Forwarded To KGP DIV@KGPLOCO/11-06-2026 18:14-Informed To Shed	APP_REM:@KGPLOCO/10-06-2026 18:26-Loco Running In Mis Link , Mis Link Done By CSTM Div. Loco Will Be Attended On Arrival At KGP Div.	APP_REM:@KGPLOCO/11-06-2026 18:13-Will Be Attended On Arrival At Kgpe Shed. Now Working AS. C. Railway.	APP_REM:@STABN/10-06-2026 21:10-INFORMED TO CTLC/KOTAFOR TAKING NECESSARY ACTION@CNLTRKGP/11-06-2026 12:14-This abnormality does not belong to S&T DEPARTMENT @KGPLOCO/12-06-2026 11:36-Fitting Of KAVACH In Every Loco Is On Progress. It will Be Completed Soon	APP_REM:@KGPLOCO/10-06-2026 11:33-Informed To Shed	APP_REM:@KGPLOCO/10-06-2026 11:32-Informed To Shed		App Remarks
13-06-2026 18:20	11-06-2026 18:14	10-06-2026 18:26	11-06-2026 18:13	12-06-2026 11:36	10-06-2026 11:33	10-06-2026 11:32		App Remarks Date
12-06-2026 20:57	10-06-2026 23:57	10-06-2026 15:41	10-06-2026 18:06	10-06-2026 14:12	09-06-2026 17:23	09-06-2026 20:28		Reporting Date

23	LOCO	20	19	18	17	16	SNO.
CAB2 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	OTHER	OTHERS CAB ISSUES	CAB1 AC NOT WORKING	ABN.TYPE
SBP	RPH	RPH	RPH	APDJ	VSKP	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HATB	NGF	NGF	NGF	NJP	RGDA	KGP	FROM
SSN	TDLE	TDLE	TDLE	MLDT	VSKP	SRC	TO
SBPY1002	RPH3088	RPH3088	RPH3088	APDJ1722	VSKP2172	KGP1009	CREW/CLIID
MANORANJAN MAHARANA	PIJUSH KUMAR GHOSH T MU	PIJUSH KUMAR GHOSH T MU	PIJUSH KUMAR GHOSH T MU	SUVANKAR KOLLEY	LANKA SRINIVASA RAO	EL CHANDRA SEKHAR MAITY	CREW/CLINAME
LPG	SALP	SALP	SALP	SALP	LPM	LPP	DESIG
18-06-2026	17-06-2026	16-06-2026	16-06-2026	15-06-2026	14-06-2026	13-06-2026	ABNDATE
08:00	22:10	11:43	11:40	21:00	06:00	22:00	ABN.TIME
27	0/1				343	115	FROMKM
549	248/8				878	7	TO KM
YS	YS	YS	YS	YS	YS	YS	STATUS
CREW	APPUSER	APPUSER	APPUSER	APPUSER	CREW	APPUSER	FILLEDBY
27161	37070	27439	27572	39094	25051	22385	LOCO
KGPE	SRCE	KGPE	KGPE	SRCE	SRCE	SRCE	LOCO SHED
PT/18303	18005	FKK	FKK	12378	18637	18048	TRAIN
19-06-26 17:46	18-06-26 21:05	16-06-26 22:00	16-06-26 22:00	16-06-26 15:40	15-06-26 15:32	15-06-26 15:32	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:LOCO-27161 AC NOT PROVIDED	DETAIL:VCD ISO AT BDTS SHED REMARK AS PER INCOMEING LP. WHILE TOC BRC INFORM TO TLC BCT	DETAIL:Provide AC In Cab	DETAIL:Provide AC In Cab. Think About The Situation Of Crew In This Summer Time. Almost 55 Degree Temperature In CAB.	DETAIL:Cab2 Alp Side Horn Started Blowing Continuously	DETAIL:WATER LEAKING BADLY FROM CAB1 AC UNIT ABOVE LP HEAD	DETAIL:BOTH SIDE CAB AC NOT WORKING	Detail
CLOSE_REM:as per loco dept Informed To Kgpe Shed	CLOSE_REM:AS PER LOCO DEPT - Loco Working In Mistlink. Same Will Be attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Kgpe Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Kgpe Shed For AC Modifications	CLOSE_REM:AS PRR LOCO DEPT Loco Working In Mislink By NF Railway. Same Will Be Attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Loco Now Working In Mislink By RNC Div. So, It Will Be Attended On Arrival At SRCE Shed.	CLOSE_REM:AS PER LOCO DEPT Informed To Srce Shed	Closing Remarks
APP_REM:@SBPDPC/18-06-2026 20:30-Forward To KGP Division @KGPLOCO/19-06-2026 11:17-Informed To Kgpe Shed	APP_REM:@KGPLOCO/18-06-2026 13:59-Loco Working In Mislink. Same Will Be attended On Arrival At Srce Shed	APP_REM:@KGPLOCO/16-06-2026 16:54-Informed To Kgpe Shed	APP_REM:@KGPLOCO/16-06-2026 16:52-Informed To Kgpe Shed For AC Modifications	APP_REM:@KGPLOCO/16-06-2026 11:46-Loco Working In Mislink By NF Railway. Same Will Be Attended On Arrival At Srce Shed	APP_REM:@VSKPABRLO/14-06-2026 11:13-Forwarded To SRC shed and KGP division for Necessary attention@KGPLOCO/15-06-2026 11:52-Loco Now Working In Mistlink By RNC Div. So, it Will Be Attended On Arrival At SRCE Shed.	APP_REM:@KGPLOCO/15-06-2026 11:46-Informed To Srce Shed	App Remarks
19-06-2026 11:17	18-06-2026 13:59	16-06-2026 16:06	16-06-2026 16:52	16-06-2026 11:46	15-06-2026 11:52	15-06-2026 11:46	App Remarks Date
18-06-2026 19:46	17-06-2026 21:57	16-06-2026 10:31	16-06-2026 11:42	16-06-2026 10:01	14-06-2026 11:11	14-06-2026 11:56	Reporting Date

SNO.	24	25	26	27	28
ABN.TYPE	LOCO	LOCO	LOCO	LOCO	LOCO
SUBHEAD	TM-3 Issolation	BG-2 (Bogie)	OTHER	SPM CAB-1 defective	SEAT DEFECTIVE
REPORTSITTN	ED	CSMT	KYQ	SRC	IGPX
REPORTDIV	KGP	KGP	KGP	KGP	KGP
FROM	ERS	IGP	SGUT	ADRA	BSL
TO	ED	CSMT	KYQ	HWH	IGP
CREW/CLIID	ERS1553	CSMT5413	SGUT1340	ADRA1953	BSL2639
CREW/GLINAME	JOSE.M.A	P K DANDEKAR.	YUBRAJ AMIT D/E	I.K.HIMANSHU	SURAJ V MAHAJAN IN PP
DESIG	LPM	LPM	LPM	LPP	SALP
ABNDATE	18-06-2026	19-06-2026	19-06-2026	22-06-2026	24-06-2026
ABN.TIME	14:36	05:12	19:04	10:20	07:00
FROMKM	00	138	00	283	444
TO KM	305	001	00	1	136
STATUS	YS	YS	YS	YS	YS
FILLED BY	CREW	CREW	SUPConsole	CREW	CREW
LOCO	30754	30731	37023	22566	30699
LOCO SHED	SRCE	SRCE	SRCE	SRCE	SRCE
TRAIN	16378	12810	12506 UP	18628	13379
SMSTO LP	19-06-26 17:46	19-06-26 17:46	19-06-26 23:01	24-06-26 21:02	24-06-26 21:02
Div	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	Y	Y
Detail	DETAIL:TM 3 ISOLATED PREVIOUS REMARK	DETAIL:WHILE TOC BOGIE 2 ISOLATE CONDITION SAME REPITED TO LPC AND WORK UP TO CSMT	DETAIL:CAB-01 FIDE BRECK PIPE IS NOT GOOD CONDITION (P/B)...	DETAIL:DIGITAL SPM NOT WORKING PROPERLY AND ANALOGUE SPM BACKLIGHT GOING OFF ON ITS OWN ALSO WIPER IS DEFFICIENT.	DETAIL:CAB 01 ALP SEAT CUSHION DEFECTIVE. CAUSING BACK PAIN
Closing Remarks	CLOSE_REM:AS PER LOCO DEPT Loco Mis Link By DLI Div. It Will Be Attended On Arrival At Kgp Shed	CLOSE_REM:AS PER LOCO DEPT Loco Will Return Back By 12809 Ex Asper Link. On Arrival Loco Will Be Send To Srce Shed For Attention	CLOSE_REM:AS PER LOCO DEPT Loco Working In RNC Div. Link. So, It Will Be Attended Only When Come To Kgp Div.	CLOSE_REM:AS PER LOCO DEPT Loco Under TR At Srce Shed Due To Spm Defective	CLOSE_REM:AS PER LOCO DEPT Loco Under Mislink By DHN Div. It Will Be Attended When Return To Kgpe Shed
App Remarks	APP_REM:@KG PLOCO/19-06-2026 11:18- Loco Mis Link By DLI Div. It Will Be Attended On Arrival At Kgp Shed	APP_REM:@KG PLOCO/19-06-2026 11:28- Loco Will Return Back By 12809 Ex Asper Link. On Arrival Loco Will Be Send To Srce Shed For Attention	APP_REM:@KG PLOCO/19-06-2026 19:36- Loco Working In RNC Div. Link. So, It Will Be Attended Only When Come To Kgp Div.	APP_REM:@KG PLOCO/24-06-2026 17:04- Loco Under TR At Srce Shed Due To Spm Defective	APP_REM:@KG PLOCO/24-06-2026 17:06- Loco Under Mislink By DHN Div. It Will Be Attended When Return To Kgpe Shed
App Remarks Date	19-06-2026 11:18	19-06-2026 11:28	19-06-2026 19:36	24-06-2026 17:04	24-06-2026 17:06
Reporting Date	18-06-2026 14:50	19-06-2026 08:59	19-06-2026 19:05	22-06-2026 17:03	24-06-2026 11:10