

TRAFFIC

3	2	1	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SUBHEAD
BWN	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
BWN	BWN	NTY	FROM
ADL	ADL	JGM	TO
BWN3181	ADL1133	NMP2107	CREW/CLIID
CHANCHAL DAS DUAL	EL PALLAB CHAKRABORTY	EL SEKHAR MAHATA G12	CREW/CLINAME
ALP	LPG	LPG	DESIG
03-06-2026	03-06-2026	02-06-2026	ABNDATE
21:20	13:09	22:37	ABN.TIME
01		122/11	FROMKM
08		153/25	TO KM
YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	FILLED BY
31216	44131	44370	LOCO
TKDE	CNBE	EDE	LOCO SHED
ME/N/KPPS		E/BOST/ICY	TRAIN
05-06-26 18:12	05-06-26 18:12	04-06-26 09:34	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:We Have Booked C/F - 09/45 O/D -09/15 from BWN To ADL (Lpg - P. K Jha / BWN 2471& ALP - C. Das/BWN 3181). Trn No - ME/N/KPPS Loco No - 31216+31634 . Bwn Dep -11/29 ADL Arr- 19/15 Reliever Came At 20:50 Hrs .After Arriving At ADL We Came To Know That Our Reliever T.O at 21/00 Hrs. We Have Requested ADL PA / TLC KGP/TLC HWH To Relieve Us Quickly As We Have Completed 10 Hrs Duty Already In This Hot Weather & Feel Very Exhausted.But They Have Not Done It , Also We Request For Shutdown As They Have No Reliever But They Also Deny It To Do .	DETAIL:I Was Working Train From Bwn To Adl . After Arrival At Adl At 11.52 Crew Relief At 12.50 Arrived At Andul Panel For Relief Stamp At 13.02 Hrs . After Waiting For 3 Min Andul STATION MASTER refused To Give Stamp At 13.05 And Said He Will Give Stamp At Engine Relief Time. Hence He Did Not Provided Any Stamp To My T34 Tickit	DETAIL:Duty Time 17 Hrs 30 min.What Is The Role Of Long Hrs Monitoring?Why Not Relief In Time?	
CLOSE_REM:as per traffic dept The incoming crew were relieved by outgoing crew at 20:45 hours as there was no shutting TO available at that time.	CLOSE_REM:as per Traffic dept Noted and necessary instructions have been given to on duty staff..	CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	Closing Remarks
APP_REM:@TRAFFICKGP/05-06-2026 13:50-The incoming crew were relieved by outgoing crew at 20:45 hours as there was no shutting TO available at that time.	APP_REM:@TRAFFICKGP/05-06-2026 13:47-Noted and necessary instructions have been given to on duty staff.	APP_REM:@HCHSINGH/04-06-2026 09:07-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	App Remarks
05-06-2026 13:50	05-06-2026 13:47	04-06-2026 09:07	App Remarks Date
03-06-2026 22:04	03-06-2026 13:15	03-06-2026 02:42	Reporting Date

7	6	5	4	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	BRAKE POWER CERTIFICATE	OTHER	OTHER	SUBHEAD
HDCB	KGP	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
ABB	DNT	HDCB	RNTL	FROM
DZK	JER	ADL	BHC	TO
ADL1709	KGP2360	ADL1709	NMP1516	CREW/CLUID
EL RAJ KUMAR RANJAN G12	EL PRAMOD KUMAR DUAL	EL RAJ KUMAR RANJAN G12	EL SUBHAMAY PODDER G12	CREW/CLINAME
SALP	LPG	SALP	LPG	DESIG
08-06-2026	07-06-2026	07-06-2026	06-06-2026	ABNDATE
12:00	10:34	05:15	11:44	ABN.TIME
15	180/2	58		FROMKM
55	180/32	12		TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
33012	70851	42661	33667	LOCO
KJGE	BNDX	AJUE	BJUE	LOCO SHED
EX ABB	DNT ENGG SPL	BTPN-ICB	BFNS/TSIJ	TRAIN
08-06-26 18:43	08-06-26 18:43	08-06-26 18:43	08-06-26 18:36	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	DETAIL:BPC NO.50000830591 ISSUEDATE 07/11/2025 INTENSIVE/INVALIDE CONTINIOUS RUN WITH SCR ORDER NO.	DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	DETAIL:Long Hours Duty of 15 Hrs Plus Performed Though Train Arrived At RNTL 10:20 And Relieved Me 11:45 at RNTL.	Detail
CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TO's of crew.	CLOSE_REM:as per traffic dept 3 BRN(E)/Engineering Spl is being utilised by RE Department for continuous 25 KV mast transferring in a short span of BLDA - DNT - JER - BLDA.	CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew.	Closing Remarks
APP_REM:@TRAFFICKGP/08- 06-2026 13:37-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@CWCKGP/07-06- 2026 22:09-Train running with invalid BPC, is not C&W concern, please forward to the concern department.@TRAFFICKGP/08 -06-2026 18:38-3 BRN(E)/Engineering Spl is being utilised by RE Department for continuous 25 KV mast transferring in a short span of BLDA - DNT - JER - BLDA.	APP_REM:@TRAFFICKGP/08- 06-2026 13:35-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@DTISAFETY/07- 06-2026 15:17-Pertains To KGP Division. @TRAFFICKGP/08-06-2026 13:34-Due to congestion in section and excess put back of TO's of crew.	App Remarks
08-06-2026 13:37	08-06-2026 18:38	08-06-2026 13:35	08-06-2026 13:34	App Remarks Date
08-06-2026 12:05	07-06-2026 17:36	07-06-2026 05:29	06-06-2026 14:26	Reporting Date

11	10	9	8	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	SUBHEAD
BLS	KGP	ADL	TATA	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
BHC	BLS	HDCB	TATA	FROM
NYA	KGP	ADL	NMP	TO
BLS1111	BLS1111	ADL1709	TATA7469	CREW/CLUID
EL SUKESH KUMAR	EL SUKESH KUMAR	EL RAJ KUMAR RANJAN G12	JITENDRA KUMAR	CREW/CLINAME
ALP	ALP	SALP	SGD	DESIG
13-06-2026	11-06-2026	09-06-2026	08-06-2026	ABNDATE
18:05	02:45	10:30	22:34	ABN.TIME
		54		FROMKM
		111		TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSE	FILLED BY
38319	28057	33400	33084	LOCO
AQE	DDUX	LDHE	BNDL	LOCO SHED
JEEP	E/NBOX/E	TCL/BCN/L		TRAIN
15-06-26 19:13	11-06-26 22:38	09-06-26 20:57	09-06-26 20:57	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
Detail				
DETAIL:I GOT RELIVED AFTER 12 HR & SIGN OFF AFTER 17 HR				
CLOSE_REM:AS PER TLC Crew after relief reported long hour tlc , advice sign off at kGP due to nearest cms point but crew not coming kGP then advice pt by 18043 ex-nya to bls due to that time kGP jeep at jgm so jeep not available				
DETAIL:MORE THAN 15 HR DUTY				
CLOSE_REM:AS PER TRAFFIC DEPT -Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.				
DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANANGE BY CONTROLLER.				
CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew.				
DETAIL:TM And Crew .T/O 9:15 , KKQ H/D From 21:40 And Till Now There Is No Any program To Receive Train Or Relief Crew And TM. Train No :-N/MOMG, Bpc No 70000109914, TXR :-NMP/KGP, I/Dt.:-29.05.2026				
CLOSE_REM:as per traffic dept Due to congestion in NMP Yard and crews TO not confirmed at that time.				
Closing Remarks				
App Remarks				
APP_REM:@TRAFFICKGP/15-06-2026 11:56-After relieved advice to long hours TLC for providing JEEP by operating side. JEEP is maintained by TLC/KGP.				
APP_REM:@TRAFFICKGP/11-06-2026 15:35-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.				
APP_REM:@TRAFFICKGP/09-06-2026 13:24-Due to congestion in section and excess put back of TO's of crew.				
APP_REM:@TRAFFICKGP/09-06-2026 18:38-Due to congestion in NMP Yard and crews TO not confirmed at that time.				
App Remarks Date				
Reporting Date				

15	14	13	12	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	SUBHEAD
NMP	BLS	BLS	MLDT	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
ABB	MKO	MKO	RPH	FROM
KGP	MKO	MKO	RPH	TO
ADL1709	NMP1460	NMP1460	MLDT7296	CREW/CLUID
EL RAJ KUMAR RANJAN G12	EL DEBASIS NANDI G12	EL DEBASIS NANDI G12	UTTAM KUMAR	CREW/CLINAME
SALP	LPG	LPG	SGD	DESIG
14-06-2026	13-06-2026	13-06-2026	13-06-2026	ABNDATE
19:20	23:46	23:46	23:00	ABN.TIME
15				FROMKM
115				TO KM
YS	YS	YS	SN	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
41342	28749	28749	24675	LOCO
JHSE	RTMD	RTMD	JHSE	LOCO SHED
CCADL	E/N/DPCB	E/N/DPCB	ICDA	TRAIN
15-06-26 15:34	15-06-26 15:34	15-06-26 15:34	16-06-26 15:36	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:LONG DUTY HOURS DUE TO MISMANAGEMENT BY SECTION CONTROLLER.	DETAIL:TRAIN DETAINED AT MKO JT LINE STR FROM 23-46 TO 05-05 HRS,WE COMPLETED 17+ DUTY	DETAIL:TRAIN DETAINED AT MKO JT LINE STR FROM 23.46 TO 05.05,WE COMPETED 17+ HOURS DUTY	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379 ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE इस ट्रेन में जो VG दिया गया है वो पुराना VG को EMPTY से LOAD कलम से काट कर लिख दिया गया है जो कि सही नहीं है।सही तरीके से VG लोडिंग स्टेशन से नहीं दी जा रही हैं और लोडिंग पेपर भी नहीं दिया रहा है।इसका लोडिंग स्टेशन CTCS हैं। कमर्शियल स्टॉफ द्वारा लोडिंग पेपर भी नहीं दिया गया है। हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए ताकि सभी पेपर ट्रेन मैनेजर को दी जाए जो मिलना चाहिए।और लोडिंग समान क्या है ICDA में वो भी पूछने के बाद नहीं बताया जाता हैं जबकि TM के पास इसकी जानकारी होनी चाहिए।	
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:as per TRAFFIC Dept Necessary instruction has been given to the concerned staff.	Closing Remarks
APP_REM:@TRAFFICKGP/15-06-2026 11:58-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/15-06-2026 11:58-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/15-06-2026 11:57-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/16-06-2026 12:08-Necessary instruction has been given to the concerned staff.	App Remarks
15-06-2026 11:58	15-06-2026 11:58	15-06-2026 11:57	16-06-2026 12:08	App Remarks Date
14-06-2026 20:42	14-06-2026 06:39	14-06-2026 06:35	13-06-2026 23:42	Reporting Date

20	TRAFFIC	19	18	17	16	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	OTHER	OTHER	SUBHEAD
SRC	NMP	ADL	ADL	BLS	TATA	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HWH	HDCB	ABB	ABB	BHC	TATA	FROM
SRC	ADL	ABB	ABB	BLS	KGP	TO
SRC2094	NMP7611	ADL1135	ADL1135	BLS1114	TATA2782	CREW/CLUID
EL RAJESH KUMAR V/B	NAVNEET KUMAR 2	EL SK. KAMARUL ISLAM	EL RAVI MANDAL G12	RAUSHAN KUMAR II(DLXZZU)..D	CREW/CLINAME	
LPG	GD	LPG	ALP	SALP	DESIG	
20-06-2026	19-06-2026	18-06-2026	17-06-2026	14-06-2026	ABNDATE	
01:30	21:54	00:35	12:55	21:15	ABN.TIME	
3		18			FROMKM	
5		17			TO KM	
YS	YS	YS	YS	YS	STATUS	
CREW	APPUSE	CREW	APPUSE	APPUSE	FILLED BY	
70378	31037	60367	38629	70796	LOCO	
BNDX	PTRX	NGPE	NGCD	BNDX	LOCO SHED	
D/S-I	E/BTPN/RCD	N/ACSY	E/N/ATLP	MD/HL/BCN/SV	TRAIN	
21-06-26 13:27	21-06-26 13:28	19-06-26 17:48	18-06-26 21:04	15-06-26 19:13	SMSTO LP	
KGP	KGP	KGP	KGP	KGP	Div	
Y	Y	Y	Y	Y	RemStts	
DETAIL:PERFORM MORE THAN 13 HRS DUTY DUE TO MISMANAGEMENT	DETAIL:Brake Van Key Missing Of Modified BRAKE Van With No. ER87022613432 Bpc No. 50000911032 I/S :- HLZ_BH YD/KGP/SER I/D :- 19/06/2026(intensive)	DETAIL:SM/ABB REFUSED TO STAMP TOTAL SHUNTING TIME,SHUNTING PERFORMED BY CREW I AFTER RECEIVING MEMO,PLACEMENT,& SHUNTING	DETAIL:More than 14 hours of duty from sign on to sign off.	DETAIL:Mis Behave and abusive language By Operating Staff at KGP GODDS YD.		
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Modified BV Key are not yet supplied to KGP/NMP based TMR.	CLOSE_REM:as per traffic dept Necessary instructions have been given to concerned staff.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Necessary instructions have been given to the concerned staff.	Closing Remarks	
APP_REM:@TRAFFICKGP/21-06-2026 12:11-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@CWCKGP/19-06-2026 22:06-B/V key is not maintained by C&W - it is to be handed over by Yard Master or I/C Guard to O/G Guard - so please forward to Operating department.@TRAFFICKGP/21-06-2026 12:14-Modified BV Key are not yet supplied to KGP/NMP based TMR.	APP_REM:@TRAFFICKGP/19-06-2026 11:43-Necessary instructions have been given to concerned staff.	APP_REM:@TRAFFICKGP/18-06-2026 17:48-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@TRAFFICKGP/15-06-2026 17:42-Necessary instructions have been given to the concerned staff.	App Remarks	
21-06-2026 12:11	21-06-2026 12:14	19-06-2026 11:43	18-06-2026 17:48	15-06-2026 17:42	App Remarks Date	
20-06-2026 01:39	19-06-2026 21:58	18-06-2026 01:20	17-06-2026 13:29	14-06-2026 23:57	Reporting Date	

24	23	22	21	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SIGNAL EXCHANGE	SUBHEAD
NMP	SRC	KGP	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
HAUR	SRC	HDCB	KGP	FROM
NMP	SHM	KGP	TATA	TO
ADL1135	SRC1847	ADL1008	KGP0082	CREW/CLUID
EL SK. KAMARUL ISLAM	EL BABU RAM MONDAL	EL MOHAN ADHIKARI G12	BRIHASPATI DAS	CREW/CLINAME
LPG	LPG	LPG	Chief Loco Inspector	DESIG
20-06-2026	20-06-2026	20-06-2026	20-06-2026	ABNDATE
12:30	12:00	05:25	02:34	ABN.TIME
80	11			FROMKM
120	12			TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
34260	70847	38009	37004	LOCO
ROUE	BNDX	SYHE	TATE	LOCO SHED
EX ABB	SHM/PC	BLC/JUNGU	18005	TRAIN
21-06-26 13:27	21-06-26 13:27	21-06-26 13:27	21-06-26 22:35	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:INFORM LONG HRS.@HAU H/S PASS 9HRS DUTY. AS SCR AGREED, HAU ASSURED TO GIVE US WRITTEN PROG,BRING TR TO S/S, WAIT FOR MEMO, NO MEMO CAME THEN HAU REPLY SCR CHANGED MIND, REFUSE TO GIVE PROG. MK ALAM OVER CUG ASSURE REL @MPD/JPR, REL@JPR@9-45,NO TR TO PILOT, DRAINED CREW DUTY HRS APPOX 16HRS.	DETAIL:CREW PERFORMED 13 HOURS DUTY DUE TO NOT RELIEVED WITHIN STIPULATED HOURS.	DETAIL:EXCESSIVE LONG DUTY	DETAIL:All right signal not exchanged from GUD	Detail
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT On duty staff have been exchanged ARS with LP & TMR. However, they have been counselled by SS/GUD to exchange ARS from clear and visible places.	Closing Remarks
APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@OPTGCNTL3/20-06-2026 15:41-This abnormality is not pertaining to CKP division.@TRAFFICKGP/21-06-2026 21:02-On duty staff have been exchanged ARS with LP & TMR. However, they have been counselled by SS/GUD to exchange ARS from clear and visible places.	App Remarks
21-06-2026 12:12	21-06-2026 12:12	21-06-2026 12:12	21-06-2026 21:02	App Remarks Date
20-06-2026 12:33	20-06-2026 13:08	20-06-2026 06:03	20-06-2026 15:25	Reporting Date

27	26	25	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SUBHEAD
BHC	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
BHC	ADL	ADL	FROM
KGP	ADL	KGP	TO
BHC1612	ADL1135	ADL1709	CREW/CLUID
BAJUNATH PRASAD	EL SK. KAMARUL ISLAM	EL RAJ KUMAR RANJAN G12	CREW/CLINAME
SALP	LPG	SALP	DESIG
21-06-2026	21-06-2026	21-06-2026	ABNDATE
23:51	03:55	00:30	ABN.TIME
	12	12	FROMKM
	11	115	TO KM
YS	YS	YS	STATUS
APPUSER	CREW	CREW	FILLED BY
44031	31055	43950	LOCO
WATE	PTRX	KZJL	LOCO SHED
08046	BCN/BEN/GYP	GFMK/CONTAINER	TRAIN
23-06-26 23:26	22-06-26 18:11	21-06-26 13:27	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:Mera To17:00 Hrs Ko Bhadrak to Kharagpur Coaching LR, Train no 08046,Loco no44031 Diya Gaya Mera Duty Off 23:38hrs Ko Hua Main Kgp Running Room Me Gaya to Kaha gaya Ki Bed Nahi hai Aur Kgp Lobby me Kaha gaya Ki 2gante Ke Bad Kgp to Bhc LR Book Kara Kar Chale Jaye Ab Raat me Main Kya Karu?	DETAIL:TR ARRIVAL 03-55, OUTGOING CREW AVAILABLE 21.30/OVERSTAYED. BUT TO 05-00 HRS.	DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	
CLOSE_REM:AS PER KGP RUNNING ROOM IC HIGH OCCUPANCY OF COACHING CREW AT THAT TIME. SO THAT WE CAN NOT PROVIDE BED FOR LR CREW. BUT WE HAD ADVICE TO CREW TO GO TO NMP RUNNING ROOM FOR PROPER REST AS BED WAS AVAILABLE AT NMP RUNNING ROOM.	CLOSE_REM:as per traffic dept Due to excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	Closing Remarks
APP_REM:@TRAFFICKGP/23-06-2026 11:44-It pertains to Electric department.	APP_REM:@TRAFFICKGP/22-06-2026 16:38-Due to excess put back of TO's of crew.	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	App Remarks
23-06-2026 11:44	22-06-2026 16:38	21-06-2026 12:12	App Remarks Date
22-06-2026 00:05	21-06-2026 05:41	21-06-2026 00:31	Reporting Date

29	28	SNO.
TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	BRAKE POWER CERTIFICATE	SUBHEAD
TDL	NMP	REPORTSTTN
KGP	KGP	REPORTDIV
CNBN	TATA	FROM
TDLN	KGP	TO
TDL8730	NMP7549	CREW/CLIID
SHUSHANT UPADHYAY	MD MUSTAQUE	CREW/CLINAME
GD	GD	DESIG
24-06-2026	23-06-2026	ABNDATE
10:59	05:05	ABN.TIME
460		FROMKM
725		TO KM
PN	PN	STATUS
APPUSER	APPUSER	FILLED BY
33780	41117	LOCO
TKDD	TKDE	LOCO SHED
BVH	BTPN HLZ EMPTY	TRAIN
		SMSTO LP
KGP	KGP	Div
Y	Y	RemStts
DETAIL:Bpc 50000911962 Bksc/Adra/Ser Issue 21/06/26 Valid 03/07/26 Brakevan Ecor 87122211033 Bvcm Return 09/26 Bv Ko Bpc Me Mention Ni Kiya Gya H . Bv Ki Chair Bilkul Bekar H N Hath Rkhne Ki Jgh N Moveble . Khidki Ka Glass Tuta Hua H . Bhut Avaj Or Vibration Ho Rha H. Modified Kre To Thik Se Kre Esi Problems N Ho	DETAIL:Bpc Invalid	Detail
		Closing Remarks
APP_REM:@CWCKGP/24-06-2026 20:24-Mentioned Brake Van Is Now Running With Premium BPC And Which Is Valid Upto 03/07/26. However Int BPC Was Issued By Hlz On Dt 16/06/26 And Allowed For Single Trip Upto Destination. So Kindly Inform Upcoming Examination Point For Necessary Action.@TRAFFICKGP/25-06-2026 16:27-Not pertains to operating department, KGP Division.	APP_REM:@CWCKGP/24-06-2026 18:58-As Per TMR BPC No-50000901054 Issues By NJPT/KIR/NFR on Dt-21/05/26, Which Was Invalid On Dt 19/06/2026. Running Of Train Maintained By Optg Dept. So Kindly Advice To Provide Thevrake At Upcoming C&W Point For Examination.@TRAFFICKGP/25-06-2026 16:20-Since BTPN(E) rakes are not now examined at HLZ depot. Hence, after expiry of BPC the rake send to VZP base depot for C&W examination as per HQ instruction.	App Remarks
25-06-2026 16:27	25-06-2026 16:20	App Remarks Date
24-06-2026 11:03	23-06-2026 05:20	Reporting Date