

CW

SNO.	1	2	3	4	5	ABN.TYPE	OTHER	UDL	KGP	UDL	BWN	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
	CW	CW	CW	CW	CW							UDL7921	CHANDRASHEKHAR SAH	GD	01-06-2026	12:40			YS	APPUSER	60218	SREE	C/CONT	03-06-26 21:09	KGP	N	DETAIL:Modified Brave Van No ER 87022611834 BVCM Return Date 08/30 In This Brake Van Doors Key Missing Same Brake Van Of BPC BPC No 70000108198 Cc Rake Issue Date 14/05/2026 NMP/KGP/SER	CLOSE_REM:As per C&W Department, TM Chandrashekhar Sah (Mobile No.: 9046243632) stated that the keys to the brake van at UDL were not handed over to him by the previous TM. We referred the matter back to HWH for further action; however, HWH repeatedly sends us back without providing any concrete reason. The C&W/TFC Department at HWH is failing to take appropriate action; they are merely stalling the matter.	APP_REM:@CWCKGP/02-06-2026 14:23-As per TM CHANDRASHEKHAR SAH Mobile No 9046243632 Brake Van Key Was not handed over to him by last TM at UDL.This is not a C&W Issue.Kindly informed to Concern department.	02-06-2026 14:23	01-06-2026 12:45
	OTHER	OTHER	OTHER	DOORS								NGP7337	SAPAN R. POTBHARE	GDM	01-06-2026	13:30	446/03	837/24	YS	APPUSER	37007	AQE	12859	02-06-26 11:01	KGP	Y	DETAIL:No Chair In LWLRRM SER221587 EX CSTM TO HWH .It Is Very Difficult To Work Without Chair . There Is Not a Single Chair For Sitting In Entire LWLRRM SER 221587 .Not For Train Manager & Not For Power Car Staff.Please Arrange Atleast One Chair For Train Manager For Smooth Working.	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed to primary depot SRC/PDPK to attend the issue on date 02/06/26 during Primary Maintenance.	APP_REM:@CWCKGP/02-06-2026 02:21-Noted Matter Informed to primary depot SRC/PDPK to attend the issue on date 02/06/26 during Primary Maintenance.	02-06-2026 02:21	01-06-2026 13:58
	PRYJ	PRYJ	BZA	PRYJ								BZA7721	CHESWARA RAO	GDM	02-06-2026	17:06	61/30	61/28	YS	APPUSER	30429	TKDE	12864	04-06-26 06:53	KGP	Y	DETAIL:BP Suddenly Dropped And Recreated Between RCG - KHT at 61/30 Km (17.06-17.09 Hrs)	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to check rake during Primary Maintenance on 04/06/26.	APP_REM:@GTLCDW/02-06-2026 23:09-Forward to PM depot SRC/KGP division SER@CWCKGP/03-06-2026 22:13-Noted. Message given to SRC Depot to check rake during Primary Maintenance on 04/06/26.	03-06-2026 22:13	02-06-2026 17:36
	KGP	KGP	KGP	KGP								PRYJ7793	DINESH KUMAR II	SGD	02-06-2026	23:25			YS	APPUSER	37492	BLEE	22858	04-06-26 06:53	KGP	Y	DETAIL:Corridor door is defective. LS5A No. SER 255413	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:08-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:24-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	03-06-2026 22:24	02-06-2026 23:27
	DDU	DDU	KHT	DDU								PRYJ7793	DINESH KUMAR II	SGD	02-06-2026	23:30			YS	APPUSER	37492	BLEE	22858	04-06-26 06:53	KGP	Y	DETAIL:Working / Writing table is very small, please provide standered size working table. LWLRRM No. SR 195422	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:08-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:25-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	03-06-2026 22:25	02-06-2026 23:32

11	10	9	8	7	6	SNO.
CW	CW	CW	CW	CW	CW	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	OTHER	OTHER	SUBHEAD
DDUN	NGP	BZA	PRYJ	PRYJ	PRYJ	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
DDU	NGP	GNT	PRYJ	PRYJ	PRYJ	FROM
CNBN	BSL	NBR	DDU	DDU	DDU	TO
DDUN7081	NGP7581	NDL1030	PRYJ7793	PRYJ7793	PRYJ7793	CREW/CLIID
SHYAM SUNDAR YADAV	AVADHESH KU. TIWARI	K.SATISH KUMAR	DINESH KUMAR II	DINESH KUMAR II	DINESH KUMAR II	CREW/CLINAME
SGD	GDM	LPM	SGD	SGD	SGD	DESIG
06-06-2026	05-06-2026	03-06-2026	03-06-2026	02-06-2026	02-06-2026	ABNDATE
06:38	00:15	02:20	00:40	23:45	23:35	ABN.TIME
125	000	05/30				FROMKM
459	000	05/32				TO KM
YS	YS	YS	YS	YS	YS	STATUS
APPUSER	APPUSER	CREW	APPUSER	APPUSER	APPUSER	FILLED BY
44395	37763	37598	37492	37492	37492	LOCO
DDUE	TATE	LGDE	BLEE	BLEE	BLEE	LOCO SHED
MJPJ	12222	18048	22858	22858	22858	TRAIN
06-06-26 21:23	05-06-26 13:26	04-06-26 06:50	04-06-26 06:50	04-06-26 06:50	04-06-26 06:53	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	RemStts
DETAIL:Revolving Chair OF BRAKE VAN Is Not Moving AND IS Fixed In Wrong Direction .kindly Fix It. B/VAN NO. ECOR 87122010247 BVCM R-10/2029 TRAIN NO. MJPJ LOCO NO 44395 BPC NO 50000898300 I /DATE-13/05/2026 NMP /KGP/SER CCR	DETAIL:ECOR 196768LWLRRM में डोंग बॉक्स की ऊंचाई ज्यादा होने से विंडो आधे से ज्यादा ढक गई है जो सुरक्षित परिचालन के लिए ठीक नहीं है।कृपया डोंग बॉक्स की ऊंचाई रेलवे बोर्ड के मानक के अनुसार कम करें।	DETAIL:FDU ACTEDON COACH NO 196610 B2,WHILE RESET OBSERVED NO INDICATION FDU	DETAIL:Demand of pest control. LWLRRM No. SR195422	DETAIL:Hand break rounding stopper rod not provide. LWLRRM No. SR 195422	DETAIL:All window glass is very dirty and cabin cleaning is not satisfactory. LWLRRM No. SR 195422	
CLOSE_REM:AS PER C&W DEPT Noted matter informed to BPC issuing station NMP to attend the issue on arrival at NRY/NMP.	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed to primary depot SRC to attend the issue on date 8/6/26 during Primary Maintenance.	CLOSE_REM:AS PER C&W DEPT Already message received from CWC/GNT regarding this matter. Same will be checked during Primary Maintenance at SHM/PDPK on 4/6/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	Closing Remarks
APP_REM:@CWCKGP/06-06-2026 20:48-Noted matter informed to BPC issuing station NMP to attend the issue on arrival at NRY/NMP.	APP_REM:@CWBSL/05-06-2026 07:47-CWC 46 ISSUED AND TO BE FORWARD TO PRIMARY DEPOT CWC KGP FOR ATTENTION. ALSO ISSUED TO TRAIN DESTINATION CWC PUNE.@CWCKGP/05-06-2026 10:49-Noted Matter Informed to primary depot SRC to attend the issue on date 8/6/26 during Primary Maintenance.	APP_REM:@CWCONTROL2/03-06-2026 07:28-Please Forward To KGP division for Further Disposal During Maintenance @CWCKGP/03-06-2026 22:33-Already message received from CWC/GNT regarding this matter. Same will be checked during Primary Maintenance at SHM/PDPK on 4/6/26.	APP_REM:@MGSCW/03-06-2026 14:19-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:29-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:58-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:28-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	APP_REM:@MGSCW/03-06-2026 14:10-Primary Depot is SRC/KGP@CWCKGP/03-06-2026 22:27-Noted. Message given to SRC Depot to attend the issue during Primary Maintenance on 04/06/26.	App Remarks
06-06-2026 20:48	05-06-2026 10:49	03-06-2026 22:33	03-06-2026 22:29	03-06-2026 22:28	03-06-2026 22:27	App Remarks Date
06-06-2026 13:57	05-06-2026 05:42	03-06-2026 03:59	03-06-2026 00:42	02-06-2026 23:45	02-06-2026 23:37	Reporting Date

14	CW	OTHER	NBQ	KGP	AYU	AZA	NBQ7340	ABHINANDAN KUMAR SINHA	SGD	08-06-2026	04:46	17/8-9	161	YS	APPUSER	31957	BIUE	UP AZA E-OIL	10-06-26 22:47	KGP	N	DETAIL:BV NO 87022612213 MODIFIED BVCM DOOR KEY AND BP PRESSURE GAGE NOT AVAILABLE BPC NO 50000904739	CLOSE_REM:As per traffic department, TM had not handover the key to YM. when we inquired with the TM, they said that, the incoming TM did not hand over the keys to the departing TM. and as per c&w dept 9:45-Brake van key is not maintained by C&W. Also during BPC issue from HLZ, no modified BP pressure gauge was there in this B/V & Guard fitted his own gauge through quick coupler.	APP_REM:@CWCKGP/09-06-2026 09:45-Brake van key is not maintained by C&W. Also during BPC issue from HLZ, no modified BP pressure gauge was there in this B/V & Guard fitted his own gauge through quick coupler.	09-06-2026 09:45	08-06-2026 10:33
13	CW	OTHER	TDL	KGP	CNBN	TDLN	TDL8763	RITESH KUMAR VERMA	GD	07-06-2026	15:06	460	724	YS	APPUSER	41626	TKDD	AJ 22	09-06-26 13:34	KGP	Y	DETAIL:BPC/No-50000902201Issue/HLZ GM-YD/KGP/SER Issue/DATE-24/05/2026 Brakevan/N-ACL/BVCM/87262310238 आखिर RDSO या अन्य जिम्मेदार संस्थाओं को क्यों नहीं असर हो रहा है कि BVCM ब्रेकवान से अत्यधिक कंपन,तीखी और कर्कश आवाज लगातार आती है जिससे बहरा होना स्वाभाविक है। क्या शोर सहने के सारे नियम को ताक पर रख दिया गया है। ये कौन लोग हैं जो BVCM ब्रेकवान को पास किए हैं। इनको एक इयूटी 10 घंटे की कराई जाए जिससे एक ट्रेन मैनेजर क्या झेलता है इनको पता लगे और यहां से सीधा नियमों में बदलाव के लिए स्वयं पहुंचें और BVZI को उपयुक्त ब्रेकवान स्वीकार करें। मोडिफिकेशन केवल BVZI में ही हो और लोको की तरह लॉग बुक हो जिसमें प्रदत्त सुविधाएं और कमियां नोट किया जाए तथा ब्रेकवान को लावारिस न छोड़कर चाभी द्वारा लॉक किया जाए। मात्र महीने भर के अंदर पंखा, लाइट, सोलर पैनल तथा एपॉक्सी रेसिन की जगह उपयोग में लाई गई प्लास्टिक भी चोरी कर ली जा रही है, ठोस कदम उठाया जाए।	CLOSE_REM:as per C&W dept The concern raised by you is noted. But it is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/09-06-2026 09:39-The concern raised by you is noted. But it is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	09-06-2026 09:39	07-06-2026 15:06
12	CW	OTHER	TPTY	KGP	SMVB	TPTY	TPTY7038	S.VIDYASAGAR	GDM	07-06-2026	10:20			YS	APPUSER	39385	BZAE	12864	08-06-26 09:46	KGP	Y	DETAIL:Guages Calibration overdue	CLOSE_REM:as per C&W dept Noted matter informed to primary depot SRC to attend the issues on date 9/06/26 during night shift	APP_REM:@GTLCDW/07-06-2026 12:34-Pertains To primary Maintenance depot SRC/KGP/SER ,forward to C&W KGP Division.@CWCKGP/08-06-2026 01:27-Noted matter informed to primary depot SRC to attend the issues on date 9/06/26 during night shift	08-06-2026 01:27	07-06-2026 12:25
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
20	CW	OTHER	NMP	KGP	HLZ	HSPG	NMP7457	LALTU BERA	GD	11-06-2026	03:30			YS	APPUSER	43671	KZIL	N/HSPG	11-06-26 22:44	KGP	Y	DETAIL:BV No Ecor 87122310064 T NO N /Hspg B/V Not Clean,Windo Not Working Condition And Commmode Broken.	CLOSE_REM:AS PER C&W DEPT The mentioned brake van was last given fit by HLZ , so matter informed to BPC issuing station HLZ to attend the issue on arrival.	APP_REM:@CWCNTLCKP/11-06-2026 17:38-Culprit BV No. - ECoR 87122310064 BVCM was last examined at HLZ/KGP/SER/50000907964/INT/09.06.26. Please forward the matter to KGP Division/SER.@CWCKGP/11-06-2026 21:32-The mentioned brake van was last given fit by HLZ , so matter informed to BPC issuing station HLZ to attend the issue on arrival.	11-06-2026 21:32	11-06-2026 04:00
21	CW	OTHER	DDUN	KGP	DDUN	CNBN	DDUN7099	RIZWAN JAMSHED KHAN	GD	11-06-2026	07:31	124	460	YS	APPUSER	42104	CNBE	HGJ	12-06-26 07:01	KGP	Y	DETAIL:BPC No.-50000963103Bksc/Adra/Ser BV No.- SECR 86141350969,Bvzi,,R-07/26 1-ब्रेक वैन की कुर्सी 8 से 10 घंटे कार्य करने लायक नहीं है कृपया WAG 12 लोको जैसी Cushioned Chair प्रदान करें। 2-ब्रेक वैन में पंखा व लाइट की व्यवस्था नहीं है तथा ब्रेक वैन में शौचालय हेतु कोई उत्तम व्यवस्था नहीं है यहां तक के एक कमोड तक नहीं लगा है। कृपया पंखा व लाइट सहित, शोरगुल व झटका रहित Modified BVZI ब्रेक वैन प्रदान करें।	CLOSE_REM:AS PER C&W DEPT The Brake Van was last examined at HLZ, but the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/11-06-2026 17:26-Noted matter informed to BPC issuing station HLZ to attend the issues on arrival at HLZ.@kgpuor/11-06-2026 22:39/COMPLY AGAIN.@CWCKGP/11-06-2026 23:09-The Brake Van was last examined at HLZ, but the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	11-06-2026 23:09	11-06-2026 07:37
22	CW	OTHER	CKP	KGP	CKP	NMP	CKP7292	JAWED RASHID	SGD	11-06-2026	10:17			YS	APPUSER	27037	DDUE	BCN/KPGM	11-06-26 22:44	KGP	Y	DETAIL:Working Door Broken	CLOSE_REM:AS PER C&W DEPT - The mentioned brake van ECR 86101065520 BVZI in present in the BPC 50000899169 , NMP, 16/05/26 so matter informed to BPC issuing station NMP to attend the issue on arrival.	APP_REM:@CWCKGP/11-06-2026 21:30-The mentioned brake van ECR 86101065520 BVZI in present in the BPC 50000899169 , NMP, 16/05/26 so matter informed to BPC issuing station NMP to attend the issue on arrival.	11-06-2026 21:30	11-06-2026 10:18
23	CW	OTHER	ASN	KGP	ASN	BCQ	ASN7643	YUGESH KUMAR SHARMA	SGD	11-06-2026	12:30			YS	APPUSER	44062	ASNLI	BCQ	12-06-26 23:31	KGP	Y	DETAIL:In modified Bvan- ER/11582 both pressure Gauge is missing and Bvan lock key not available	CLOSE_REM:AS PER C&W DEPT BPC - 70000110931, I/DT - 07/06/2026, I/STN - NMP/KGP/SER, RAKE - CC RAKE. B/V NO - ER 87022611582 BVCM. Message given to base depot NMP to check the matter & take necessary action, on arrival of rake at NMP.	APP_REM:@ABCW/11-06-2026 13:37- Brake Van Examined By NMP/KGP. not Pertain To C&W, Asansol @CWCKGP/12-06-2026 20:39-BPC - 70000110931, I/DT - 07/06/2026, I/STN - NMP/KGP/SER, RAKE - CC RAKE. B/V NO - ER 87022611582 BVCM. Message given to base depot NMP to check the matter & take necessary action, on arrival of rake at NMP.	12-06-2026 20:39	11-06-2026 13:31

26	CW	25	24	SNO.
UNDERFRAME	CW	OTHER	CW	ABN.TYPE
ADL	ANR	ANR	OTHER	SUBHEAD
KGP	KGP	KGP	DDUN	REPORTSTTN
HLZ	UDL	UDL	KGP	REPORTDIV
ADL	ANR	ANR	CNBN	FROM
ADL7185	ANR7442	ANR7442	DDUN	TO
SAIKAT PACHHAL	G.P.SANTIKARY	G.P.SANTIKARY	DDUN7054	CREW/CLIID
SGD	SGD	SGD	DURGESH TIWARI	CREW/CLINAME
13-06-2026	13-06-2026	13-06-2026	GD	DESIG
13:55	12:00	12:00	13-06-2026	ABNDATE
HY7/5			03:40	ABN.TIME
HY7/4			460	FROMKM
YS	YS	YS	124	TO KM
APPUSER	APPUSER	APPUSER	YS	STATUS
44251	32149	32149	APPUSER	FILLEDBY
BNDL	BJUE	BJUE	28326	LOCO
N/DSEY	E/NBOX ES SER	E/NBOX ES SER	GTLE	LOCO SHED
13-06-26 21:34	14-06-26 15:24	14-06-26 15:24	HP 32	TRAIN
KGP	KGP	KGP	13-06-26 21:34	SMSTO LP
Y	Y	Y	KGP	Div
			Y	RemStts
DETAIL:There Is No LV Bracket Available In Working Side Of The Brake Van (ECR 67286)	DETAIL:Solar System Is Not Working And Out Of Order Fan & Light..BV No-86151108581	DETAIL:BPC/No-50000903103Issue/ST-BKSC/ADRA/SER Issue/DATE-26/05/2026 Validity -29/06/2026 Brakevan/N-SECR-86141350969 1.ब्रेकवान की वर्किंग कुर्सी पीछे की ओर झुकी है जो 11 घंटे की ड्यूटी के दौरान पीड़ादायक तथा झटको में रिस्की है, कृपया कुर्सी बदल दीजिए। 2.टॉयलेट शीट को इंडियन स्टाइल का बनाइए जिसकी महिला व पुरुष ट्रेन मैनेजर आसानी से उपयोग कर सकें 3.मोडिफिकेशन में पंखा,लाइट सोलर पैनल सब चोरी हो रही है, इसकी जवाबदेही तय करें तथा कोई स्थाई समाधान खोजें। 4.Provide Basic Facilities Like Light Fan Water Pvc Coating Internally And Fully Locked Brakevan With Universal Key. 5.In Modification, As Per Railway Board Letter No. 2013/M(N)/60/10 (E-3320409) New Delhi Dated- 23-04-2025,Train Manager side should be heard. Sound problem is as usual.		
CLOSE_REM:AS PER C&W DEPT BPC no. 50000908475, ex HLZ, dated 11/06/25 (Intensive) & B/V no. ECR 86101167286 BVZI. Message given to BPC issuing depot HLZ to attend the issue on arrival.	CLOSE_REM:AS PER C&W DEPT BPC no. 7000010722, ex. NMP, dt. 05/05/26 (CC), rake name - NRY-118 (NEO), containing the mentioned B/V, so message given to base depot NMP to attend the issue on arrival.	CLOSE_REM:AS PER C&W DEPT The Brake Van was last examined at HLZ, but after that BPC has long turned invalid. Also the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.		
APP_REM:@CWCKGP/13-06-2026 14:18-BPC no. 50000908475, ex HLZ, dated 11/06/25 (Intensive) & B/V no. ECR 86101167286 BVZI. Message given to BPC issuing depot HLZ to attend the issue on arrival.	APP_REM:@NATHCW/14-06-2026 02:38-The Said Nmt Was Last examination Done At Nmp So Complain Forwarded to Cwc/Kgp For necessary Action@CWCKGP/14-06-2026 12:54-BPC no. 7000010722, ex. NMP, dt. 05/05/26 (CC), rake name - NRY-118 (NEO), containing the mentioned B/V, so message given to base depot NMP to attend the issue on arrival.	APP_REM:@CWCNTLALD/13-06-2026 08:59-Train Running DFCC so Forward To DFCC.@CWCKGP/13-06-2026 14:02-The Brake Van was last examined at HLZ, but after that BPC has long turned invalid. Also the concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.		
13-06-2026 14:18	14-06-2026 12:54	13-06-2026 14:02		App Remarks Date
13-06-2026 14:02	13-06-2026 12:04	13-06-2026 08:48		Reporting Date

29	CW	OTHER	DDUN	KGP	DDUN	CNBN	DDUN7007	HIMANSHU SINGH I	GD	15-06-2026	09:47		YS	APPUSER	28616	RTMD	GZB LH-II	17-06-26 21:51	KGP	Y	DETAIL:BPC- 50000907796/Premium/BKSC/ADRA/SER Bv- NR87032510042 Dono side ke Chair pe back side me foam nhi lga hua h	CLOSE_REM:AS PER C&W DEPT BPC No-50000907130 Issued By HLZ With T/No-N/Bscs On Dt 07/06/26 With INT BPC, Which Is Valid For One Trip. After that Enroute Brake Van Was Attached With BPC No 50000907796 With Premium BPC. So Informed ADRA For Further Disposal Of Complain And Necessary Attention On Arrival.	APP_REM:@CWCKGP/16-06-2026 11:23-The Rake Was Examined & BPC Issued By BKSC, SoPlease Forward To BPC Issuing Station. BPC Issued On 09/06/26 & Valid Upto 21/06/26@CWCKGP/16-06-2026 11:23-The Rake Was Examined & BPC Issued By BKSC, SoPlease Forward To BPC Issuing Station. BPC Issued On 09/06/26 & Valid Upto 21/06/26@NATHCW/16-06-2026 23:44-The Said Nmt Was Last examination Done At HLZ So Complain Forwarded to CWC/KGP For necessary Action@CWCKGP/17-06-2026 20:44- BPC No-50000907130 Issued By HLZ With T/No-	17-06-2026 20:44	15-06-2026 09:49	
28	CW	OTHER	MLDT	KGP	RPH	RPH	MLDT7296	UTTAM KUMAR	SGD	13-06-2026	23:45		SN	APPUSER	24675	JHSE	ICDA	14-06-26 15:24	KGP	Y	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE ब्रेक वन GIPL 87402110018BVCM इस ब्रेकवान में कुर्सी है लेकिन उस पर बैठ के 12 घंटे की ड्यूटी कर पाना बहुत ही मुश्किल हैं कृपया इस ब्रेकवान के कुर्सी को बदला जाए ताकि रनिंग ट्रेन में ड्यूटी से सही तरीके से हो सके।इस ब्रेकवान में आवाज बहुत ही ज्यादा है हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए और ब्रेकवान BVCM में रनिंग के समय बहुत ही ज्यादा आवाज और आइसोलेशन होता हैं BVCM ब्रेकवान को बिना आवाज और बिना आइसोलेशन के बनाया जाए जैसा कि BVZI ब्रेकवान होता है।	CLOSE_REM:AS PER C&W DEPT The concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	APP_REM:@CWCKGP/14-06-2026 12:40-The concern raised by you is a design issue & not a maintenance issue. Matter will be highlighted to concerned authorities through proper channel.	14-06-2026 12:40	13-06-2026 23:54	
27	CW	OTHER	MLDT	KGP	RPH	RPH	MLDT7296	UTTAM KUMAR	SGD	13-06-2026	23:00		SN	APPUSER	24675	JHSE	ICDA	14-06-26 15:24	KGP	Y	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE इस ट्रेन का BPC बनाया गया है और BV से पहला वैगन जिसका पिस्टन टूटा हुआ है जिसका नंबर CNCR 53252510858BLCSA है।BPC बनते समय वैगन को सही तरीके से जाँच नहीं की जाती हैं हमारे C &W स्टॉफ द्वारा। हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए ताकि BPC बनाते समय वैगन की जाँच सही तरीके से सुनिश्चित हो सके।	CLOSE_REM:AS PER C&W DEPT Message given to base depot NMP to attend & rectify during next PME & also to tighten up examination.	APP_REM:@CWCKGP/14-06-2026 12:32-Message given to base depot NMP to attend & rectify during next PME & also to tighten up examination.	14-06-2026 12:32	13-06-2026 23:43	
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

32	CW	31	30	SNO.
OTHER	CW	OTHER	CW	ABN.TYPE
TATA	OTHER	TATA	OTHER	SUBHEAD
KGP	TATA	KGP	NMP	REPORTSTTN
TATA	KGP	TATA	KGP	REPORTDIV
CKP	CKP	CKP	HDCB	FROM
TATA7506	TATA7506	TATA7506	KGP	TO
VIBHUTI KUMAR	VIBHUTI KUMAR	VIBHUTI KUMAR	NMP7538	CREW/CLIID
GD	GD	GD	SOURAV KUMAR TANTI	CREW/CLNAME
16-06-2026	16-06-2026	16-06-2026	GD	DESIG
10:30	10:30	10:30	15-06-2026	ABNDATE
253	253	253	18:31	ABN.TIME
315	315	315		FROMKM
YS	YS	YS		TO KM
APPUSER	APPUSER	APPUSER	YS	STATUS
24062	24062	24062	APPUSER	FILLED BY
JHSE	JHSE	JHSE	24062	LOCO
HSPG	ME/N/HSPG	ME/N/HSPG	JHSE	LOCO SHED
18-06-26 22:44	18-06-26 22:44	18-06-26 22:44	ME/N/HSPG	TRAIN
KGP	KGP	KGP	16-06-26 15:39	SMSTO LP
Y	Y	Y	KGP	Div
			Y	RemStts
DETAIL:Break Van Working Chair Broken..Bpc-50000908786 HLZ-GM-YD/KGP/SER 12/06/26 INTENSIVE.BVZI-NWR-86111086867(11-26)	DETAIL:Break Van Working Chair Broken..BPC NO-50000908786,HLZ-GM-YD/KGP/SER I/DT-12/06/26 INTENSIVE ..BVZI-NWR(86111086867)(R,11-26)	DETAIL:During Taking Charge From HDCB found Working Side Broken Chair, B/V No. NWR86867 BPC 50000908786 I/DT 12/06/26 I/STN HLZ GM YD. /KGP/SER TYPE END TO END		Detail
CLOSE_REM:AS PER C&W DEPT The mentioned Brake Van is given fit with mentioned BPC from HLZ, so message given to HLZ Depot for necessary action. Also message given to CWC/CKP to attend the matter on arrival at HSPG in their Division.	CLOSE_REM:AS PER C&W DEPT The mentioned Brake Van is given fit with mentioned BPC from HLZ, so message given to HLZ Depot for necessary action. Also message given to CWC/CKP to attend the matter on arrival at HSPG in their Division.	CLOSE_REM:AS PER C&W DEPT Message Given To BPC Issuing Station HLZ To Attend On Arrival.		Closing Remarks
APP_REM:@CWCNTLCKP/16-06-2026 17:43-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/17-06-2026 21:29-Kindly Inform Destination HSPG/ROU/CKP to Attend On Arrival. Also Informed Hlz For Necessary Action.@CWCNTLCKP/18-06-2026 07:58-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/18-06-2026 09:57-Mentioned	APP_REM:@CWCNTLCKP/16-06-2026 17:42-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/17-06-2026 21:28-Kindly Inform Destination HSPG/ROU/CKP to Attend On Arrival. Also Informed Hlz For Necessary Action.@CWCNTLCKP/18-06-2026 07:58-Culprit BV No.- NWR 86111086867 BVZI was last examined at HLZ/KGP/SER/50000908786/INT/12.0 6.26. Please forward the matter to KGP Division/SER.@CWCKGP/18-06-2026 09:57-Mentioned	APP_REM:@CWCKGP/16-06-2026 11:53-Message Given To BPC Issuing Station HLZ To Attend On Arrival.		App Remarks
18-06-2026 09:57	18-06-2026 09:57	16-06-2026 11:53		App Remarks Date
16-06-2026 10:48	16-06-2026 10:38	15-06-2026 18:35		Reporting Date

36	CW	OTHER	TDL	KGP	KRJN	CNBN	TDL9201	BHAGESH KUMAR MEENA	GD	18-06-2026	18:45	849	461	YS	APPUSER	60200	SREE	WDN 166	19-06-26 23:05	KGP	Y	DETAIL:Bpc 50000899569ब्रेकवान में लाइट एंड फैन नॉट वर्किंग B.V.no-ER/87022510533	CLOSE_REM:AS PER C&W ELECT DEPT B/V last examined (before generation of complaint) at HLZ & message given to HLZ depot for necessary action	APP_REM:@CWCKGP/19-06-2026 22:00-B/V last examined (before generation of complaint) at HLZ & message given to HLZ depot for necessary action.	19-06-2026 22:00	19-06-2026 02:29
35	CW	OTHER	ADI	KGP	ADI	ST	ADI7300	MANISH KUMAR KULSHRESTHA	GDM	16-06-2026	23:55	496	296	YS	APPUSER	37235	TATE	12833	17-06-26 22:01	KGP	Y	DETAIL:गाड़ी के REAR SLR में TM के लिये CHAIR नल्ले रुक	CLOSE_REM:as per C&W dept Noted, Matter Informed To Primary Depot To Attend On Arrival. However Additional Provision Of Chair For Perusal Of Guard On Request And Is Locally Arranged And Not Mandatory As Per RDSO design.	APP_REM:@CWCKGP/17-06-2026 21:41 -Noted, Matter Informed To Primary Depot To Attend On Arrival. However Additional Provision Of Chair For Perusal Of Guard On Request And Is Locally Arranged And Not Mandatory As Per RDSO design.	17-06-2026 21:41	16-06-2026 23:58
34	CW	OTHER	BZA	KGP	MBL	GDR	BZA7402	P.NEHRU	GDM	16-06-2026	16:17	136/31	136/29	YS	APPUSER	39512	PADX	12841	17-06-26 21:57	KGP	Y	DETAIL:FIBA activated Rear 4th Coach no SER LS5 255424 Genral. TxR staff attending and not rest, So Isolation condition fit for normal speed with along escort Txr Staff This is information Sir Thank You Sir	CLOSE_REM:as per C&W dept Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	APP_REM:@SSECNWBZA/17-06-2026 12:39-Forward abnormality to PM divn/KGP for thorough checking. Mean while at GDR C&W staff examined and tried to reset the FIBA but unable to reset due to FIBA malfunctioning. Hence isolated and ensured all air springs are inflated condition and allowed the train with normal speed upto destination.@CWCKGP/17-06-2026 19:05-Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	17-06-2026 19:05	16-06-2026 18:42
33	CW	OTHER	BZA	KGP	MBL	GDR	BZA2075	M.S.KUMAR G12	LPM	16-06-2026	15:16	136/8	136/6	YS	APPUSER	39512	PADX	12841	17-06-26 21:57	KGP	Y	DETAIL:FIBA activated in Coach No 255424 same was attended by TXR/GDR given fit For Normal Speed same was Escorted By TXR upto MAS	CLOSE_REM:as per C&W dept Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	APP_REM:@SSECNWBZA/17-06-2026 12:38-Forward abnormality to PM divn/KGP for thorough checking. Mean while at GDR C&W staff examined and tried to reset the FIBA but unable to reset due to FIBA malfunctioning. Hence isolated and ensured all air springs are inflated condition and allowed the train with normal speed upto destination.@CWCKGP/17-06-2026 19:05-Noted Matter Informed To Primary Depot SRC to Attend The Issue During Primary Maintenance.	17-06-2026 19:05	16-06-2026 19:17
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

40	CW	OTHER	SBC	KGP	JTJ	SMVB	SBC7091	SAHOO RR	GDM	24-06-2026	23:38	214	001	YS	APPUSER	30313	LGDE	22887	25-06-26 13:46	KGP	Y	DETAIL:The TMR WRITING TABLE IS SLANTED And Unable To Write	CLOSE_REM:AS PER C&W DEPT Matter is noted & message given to SRC/PDPK on 26.06.26 & it will be attended on 26/27.06.26 during primary maintenance.	APP_REM:@CNWSBC/25-06-2026 08:58-Message Forwarded To Srdme KGP/SER for Necessary Attention @CWCKGP/25-06-2026 11:47-Matter is noted & message given to SRC/PDPK. Down Train No-22888 will arrive primary depot SRC/PDPK on 26.06.26 & it will be attended on 26/27.06.26 during primary maintenance.	25-06-2026 11:47	25-06-2026 00:10
39	CW	OTHER	TDL	KGP	CNBN	TDLN	TDL9076	ANURAG PRATAP	GD	23-06-2026	16:14	460	724	YS	APPUSER	32118	PTRX	TICD	24-06-26 21:08	KGP	Y	DETAIL:BPC No: 70000112323 (NMP/KGP/SER) I/DATE:- 19/06/2026 VALIDITY :- 18/06/2026 B/VAN No:NFR 87052110222/BVCM RETURN:- 05/30 इस ब्रेक वैन में बहुत ही कर्कश आवाज आ रही है, कृपया उचित सुधार करके , ब्रेक वैन की मूलभूत चीजें जैसे डोर लॉक , लाइट , फैन, सही तरीके की टेबल और पानी की टंकी की सुविधा करे ।	CLOSE_REM:AS PER C&W DEPT Noted Matter Informed To BPC issuing Station NMP/SER to Attend During Examination.	APP_REM:@CWCKGP/24-06-2026 20:12-Noted Matter Informed To BPC issuing Station NMP/SER to Attend During Examination.	24-06-2026 20:12	23-06-2026 16:20
38	CW	OTHER	NMP	KGP	HU	KGP	NMP7611	NAVNEET KUMAR2	GD	21-06-2026	15:02			YS	APPUSER	42071	MLDD	E/N/SSPL	22-06-26 18:13	KGP	Y	DETAIL:While Taking Charge At HIJ BV key Not Received By HIJ/RRI of Modified BRAKE Van No.ER87022613319 BPC NO. 70000110676 I/S. UDL WDD-YD/ASN/ER I/D. 04/06/2026 C.C RAKE	CLOSE_REM:AS PER TRAFFIC DEPT Modified BV Key are not yet supplied to KGP/NMP based TMR.	APP_REM:@CWCKGP/21-06-2026 22:10-Hand over of brake van key is not resposnsibility of C&W, it shall be provided either from CREW/TMR or from yard master.	21-06-2026 22:10	21-06-2026 15:06
37	CW	OTHER	MAS	KGP	MAS	BZA	MAS7327	MUNI KUMAR. Y.S.	GDM	19-06-2026	07:05	5	6	YS	APPUSER	37494	EDE	12842	19-06-26 23:05	KGP	Y	DETAIL:In Bv Equipment Room Door Not Available..... Stretcher,rope Ladder, EL Box Also Not Available Kindly Pls Note.	CLOSE_REM:AS PER C&W DEPT Noted. Message given to SRC/PDPK depot to attend the issue during Primary maintenance on 20/21-6-26.	APP_REM:@SSECNWBZA/19-06-2026 09:01-Forward abnormality to PM divn / KGP to look into the matter.@CWCKGP/19-06-2026 21:50-Noted. Message given to SRC/PDPK depot to attend the issue during Primary maintenance on 20/21-6-26.	19-06-2026 21:50	19-06-2026 07:51
SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLNAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date

ELECTCOACH

SNO.	1	2	3	4	5	6
ABN.TYPE	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH
SUBHEAD	TRAIN LIGHTING	OTHER	TRAIN LIGHTING	OTHER	OTHER	OTHER
REPORTSTTN	ADI	KGP	PRYJ	JSG	NGP	TATA
REPORTDIV	KGP	KGP	KGP	KGP	KGP	KGP
FROM	ADI	HWH	PRYJ	TIG	BSL	JSG
TO	BHUJ	KGP	DDU	JSG	NGP	TATA
CREW/CLUID	AD17421	KGP7524	PRYJ7793	JSG7062	NGP7168	TATA7046
CREW/CLNAME	SUMER CHAND MEENA	AJAY KUMAR	DINESH KUMAR II	DHARMENDRA GARDIA	MAYAKANT CHOUDHARY	J. P. SAH
DESIG	SGDP	GDM	SGD	GDM	GDM	GDM
ABNDATE	01-06-2026	02-06-2026	02-06-2026	04-06-2026	04-06-2026	05-06-2026
ABN.TIME	15:50	12:09	23:40	05:55	13:51	11:15
FROMKM		01				
TO KM		115				
STATUS	YS	YS	YS	YS	YS	YS
FILLED BY	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER
LOCO	37291	30804	37492	37162	37472	37290
LOCO SHED	TATE	SRCE	BLEE	SRCE	AQE	TATE
TRAIN	22830	22887	22858	12872	12859	22862
SMSTO LP	02-06-26 21:53	02-06-26 21:53	05-06-26 13:25	05-06-26 13:26	05-06-26 13:26	07-06-26 21:15
Div	KGP	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	Y	Y	Y
Detail	DETAIL:Both Side LWLRRM SER 191425/LSLRD NR 216173, ETL BOX NOT PROVIDED , PLEASE ATTEND THIS ON ARRIVAL BASE DEPPPO	DETAIL:R/LWLRRM/SER/193712 AC is not working	DETAIL:Side lamp glass is not available . LWLRRM No. SR 195422	DETAIL:AC OF LWLRRM SE 241703 IS NOT WORKING,SUFFOCATION FEELING INSIDE,NO PC STAFFS ARE RESPONDING TILL NOW	DETAIL:In R/LRM no. SER 202303 AC not Working and body Flasher lamp also not working;. Maintenance is very poor. Now heat wave is going on. Very difficult to work.	DETAIL:A/C of R/Lwlrrm No.Ser 178859 Not Working
Closing Remarks	CLOSE_REM:AS PER C&W ELECT DEPT At present ETL box is not available at electrical store, once it available, it will be provided.	CLOSE_REM:AS PER C&W ELECT DEPT We have informed to SSEE/ SRC to attend this issue during primary maintenance on arrival on 05.06.2026	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC On Arrival 07/06/2026	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC On Arrival Today.	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC On Arrival Today.	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE /SRC To Attend This Issue During Primary Maintenance On Arrival Today
App Remarks	APP_REM:@CNWELECT/02-06-2026 19:24-At present ETL box is not available at electrical store, once it available, it will be provided.	APP_REM:@CWCKGP/02-06-2026 13:13-AC under ELECTRICAL Gen. Department. Kindly Inform them. @CNWELECT/02-06-2026 19:26-We have informed to SSEE/ SRC to attend this issue during primary maintenance on arrival on 05.06.2026.@CNWELECT/02-06-2026 19:26-We have informed to SSEE/ SRC to attend this issue during primary maintenance on arrival on 05.06.2026.	APP_REM:@CNWELECT/05-06-2026 12:36-We Have Informed To SSEE/SRC On Arrival 07/06/2026	APP_REM:@CNWELECT/05-06-2026 12:37-We Have Informed To SSEE/SRC On Arrival Today.	APP_REM:@CNWELECT/05-06-2026 12:38-We Have Informed To SSEE/SRC On Arrival Today.	APP_REM:@CNWELECT/07-06-2026 20:55-We Have Informed To SSEE/SRC To Attend This Issue During Primary Maintenance On Arrival Today
App Remarks Date	02-06-2026 19:24	02-06-2026 19:26	02-06-2026 12:36	05-06-2026 12:37	05-06-2026 12:38	07-06-2026 20:55
Reporting Date	01-06-2026 17:05	02-06-2026 12:11	02-06-2026 23:41	04-06-2026 08:30	04-06-2026 13:51	05-06-2026 12:24

12	11	10	9	8	7	SNO.
ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ABN.TYPE
TRAINLIGHTING	OTHER	OTHER	OTHER	ACP	GENERAL POWER	SUBHEAD
TATA	RJY	TPTY	VSKP	VSKP	TATA	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
TATA	VSKP	SMVB	KUR	VZM	JSG	FROM
BBN	BZA	TPTY	VSKP	VZM	TATA	TO
TATA7059	RJY7571	TPTY7038	VSKP7161	VSKP7169	TATA7046	CREW/CLIID
RAJESH KUMAR	PRASHANT KUMAR JHA	S.VIDYASAGAR	CHEPURI RAMAMOHANA RAO	GIDJALA GANESH KUMAR	J. P. SAH	CREW/CLINAME
GDM	GDM	GDM	GDM	GDM	GDM	DESIG
07-06-2026	07-06-2026	07-06-2026	06-06-2026	05-06-2026	05-06-2026	ABNDATE
17:17	11:28	10:20	07:05	16:54	11:31	ABN.TIME
				818/22		FROMKM
				818/20		TO KM
YS	YS	YS	YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	FILLED BY
22398	30681	39385	30760	30804	37290	LOCO
SRCE	BZAE	BZAE	SRCE	SRCE	TATE	LOCO SHED
12021/12023	18045	12864	12863	22850	E/22862	TRAIN
08-06-26 12:51	08-06-26 22:36	08-06-26 18:37	08-06-26 18:37	08-06-26 12:50	07-06-26 21:15	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	N	Y	RemStts
DETAIL:Body Lamp not Flashing of LRRM no SCR 227116 and LSLRD no SE245949 of Tr No 12021/12022	DETAIL:AC is Not Working Properly. WLRRM No. SER 178856	DETAIL:LWLRRM No. 194720, Body Tail Lamp Red Lens dislodged	DETAIL:That sounds rough — working in a closed LWLRRM lobby with no AC gets unbearable fast. LWLRRM = Train Manager Room coach. Because it's a closed circuit room no AC means heat builds up quickly and it's a safety issue too.	DETAIL:Ac Not Working In Coach No NFR224553	DETAIL:A/C Of R/Lwlrrm SE278859 Not Working	Detail
CLOSE_REM:AS PER C&W ELECT DEPT We Informed To SSEE/SRC To Attend This Issue During Primary Maintenance On Arrival 09/06/26	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSE/SRC To Attend The Issue During Primary Maintenance On Arrival 10.06.2026	CLOSE_REM:AS PER C&W ELECT DEPT We have inform to SSEE/SRC to attend & rectify this issue during Primary Maintenance at SRC on arrival today.	CLOSE_REM:AS PER C&W ELECT DEPT We have inform to SSEE/SRC to attend & rectify this issue during Primary Maintenance at SRC on arrival on 10.6.26.	CLOSE_REM:AS PER C&W ELECT DEPT Coach no NFR 224553 LWACCW marked electrical sick on arrival 06/06/26 at SHM	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE /SRC To Attend This Issue During Primary Maintenance On Arrival Today	Closing Remarks
APP_REM:@CNWELECT/08-06-2026 11:48-We Informed To SSEE/SRC To Attend This Issue During Primary Maintenance On Arrival 09/06/26	APP_REM:@CNWELECT/08-06-2026 21:11-We Have Informed To SSE/SRC to Attend The Issue During Primary Maintenance On Arrival 10.06.2026	APP_REM:@GTLICWD/07-06-2026 14:24-Pertains To primary Maintenance depot SRC/KGP/SER ,forward to ELE KGP Division.@CWCKGP/07-06-2026 22:01-Tail lamp is not C&W concern, please forward to concern department.@CNWELECT/08-06-2026 14:46-We have inform to SSEE/SRC to attend & rectify this issue during Primary Maintenance at SRC on arrival today.	APP_REM:@VSKPABRELC/07-06-2026 19:30-Please Forward To Concern Primary Depot. Depot Is SRC@CNWELECT/08-06-2026 14:48-We have inform to SSEE/SRC to attend & rectify this issue during Primary Maintenance at SRC on arrival on 10.6.26.	APP_REM:@VSKPABRELC/07-06-2026 19:28-Sir Please Forward To Concern Primary Depot.	APP_REM:@CNWELECT/07-06-2026 20:56-We Have Informed To SSEE /SRC To Attend This Issue During Primary Maintenance On Arrival Today	App Remarks
08-06-2026 17:22	08-06-2026 21:11	08-06-2026 14:46	08-06-2026 14:48	07-06-2026 19:28	07-06-2026 20:56	App Remarks Date
07-06-2026	07-06-2026 11:29	07-06-2026 12:35	06-06-2026 12:11	05-06-2026 21:42	05-06-2026 15:35	Reporting Date

SNO.	13	14	15	16	17
ABN.TYPE	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH
SUBHEAD	OTHER	TRAIN LIGHTING	TRAIN LIGHTING	OTHER	OTHER
REPORT/TTN	BSL	PRYJ	PRYJ	CSMT	NGP
REPORTDIV	KGP	KGP	KGP	KGP	KGP
FROM	IGP	KYT	CNB	CSMT	BSL
TO	BSL	CAR	PRYJ	IGP	NGP
CREW/CLUID	BSL7258	PRYJ7824	PRYJ7824	CSMT7765	NGP7057
CREW/CLINAME	AJAY KUMAR RAY	SHER BAHADUR VERMA	SHER BAHADUR VERMA	NEMCHAND MEENA	SUNIL KUMAR
DESIG	GDM	SGD	SGD	GDM	GDM
ABNDATE	08-06-2026	09-06-2026	10-06-2026	12-06-2026	12-06-2026
ABN.TIME	12:21	06:46	01:40	06:48	13:49
FROMKM	136/10	695/09		01	
TO KM	440/10	695/09		136	
STATUS	YS	YS	YS	YS	YS
FILLED BY	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER
LOCO	37105	30516	30516	37533	37533
LOCO SHED	CNBE	TKDE	TKDE	GMOE	GMOE
TRAIN	12859	22857	22858	12859 Dn	12859
SMSTO LP	12-06-26 23:26	11-06-26 22:40	11-06-26 22:40	14-06-26 21:35	14-06-26 21:36
Div	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	N	N
Detail	DETAIL:Air conditioning system of rear LWLRRM no SER/202303 of train no 12859 is not functioning,so that staff as well as working train manager facing acute hotness please take appropriate action.	DETAIL:ETL box Not Available In Working Train Manager,s Cabin. LSLRD NO.SWR 202205 BPC no. 221914/SRC/SER dated- 08.06.2026	DETAIL:ETL box Not Available In Working Train Manager,s Cabin.LWLRRM NO. SR 195422 BPC NO. 221915/SRC/SER dated- 08.06.2026	DETAIL:LWLRRM SER 202303 of 12859 Dn / 12.6.2026 "As usual", the Substandard Maintenance of the SRC based coach. 1. Body TL Not Blinking. 2. Switch of Body TL is Combined with the Lights of Luggage Room. 3. Airconditioning is inaffective 4. Washroom Flush is Not Working properly. Flush Handle and Jet Spray is Not Available. 5. Ceiling Panel inside Power Car is Leaking when Rain. Primary Maintenance SRC / SER	DETAIL:Cooling System Not Working In Lwrrm No SER202303 Of Tn No 12859,please Fix This Problem .
Closing Remarks	CLOSE_REM:as per c&w Elect dept The issue was reported by the BSL crew to the BSL Division on 08-06-2026. However, BSL referred it to the HWH division, and the HWH Division referred it to us four days later (12-06-2026). Therefore, the issue remained pending with the other division for more than 72 hours. We have informed the SSE/PowerCar/SRC to address this issue during on-arrival maintenance today, 12/06/2026.	CLOSE_REM:AS PER C&W ELECT DEPT At Present ET L Box Is Not Available At Electrical Store, Once It Will Available,Will Be Provided.	CLOSE_REM:AS PER C&W ELECT DEPT At Present ET L Box Is Not Available At Electrical Store, Once It Will Available,Will Be Provided.	CLOSE_REM:AS PER C&W DEPT Regarding defective fittings in the washroom, message has been given to SRC Depot to attend same during Primary maintenance on 14/06/26. & C&W ELECT DEPT We informed to SSEE /SRC to attend this issue during primary maintenance on arrival 14/06/2026	CLOSE_REM:AS PER C&W ELECT DEPT We informed to SSEE /SRC to attend this issue during primary maintenance on arrival 14/06/2026
App Remarks	APP_REM:@CNWELECT/12-06-2026 16:18-We Have Informed To SSE/Powercar /Src To Attend This Issue During Maintenance On Arrival Today 12/06	APP_REM:@ELECG/09-06-2026 13:17-Sir, Train Related To SER KGP Division.@CNWELECT/11-06-2026 11:46- At Present ETL Box Not Available At Electrical Store. Once It Is Available, It Will Be Provided.	APP_REM:@ELECG/10-06-2026 14:38-Sir, Train Related To SER KGP Division.@CNWELECT/11-06-2026 16:50- At Present ET L Box Is Not Available At Electrical Store, Once It Will Available,Will Be Provided.	APP_REM:@CWBB/12-06-2026 11:08- Please Forward To KGP SER@CWCKGP/12-06-2026 19:54-Most of the issues in the complaint pertains to Electrical department (except point no. 4). Regarding defective fittings in the washroom, message has been given to SRC Depot to attend same during Primary maintenance on 14/06/26. For rest of the issues forward complaint to Electrical (G) Control/KGP.	
App Remarks Date	12-06-2026 16:18	11-06-2026 11:46	11-06-2026 16:50	12-06-2026 19:54	
Reporting Date	08-06-2026 12:25	09-06-2026 06:56	10-06-2026 01:42	12-06-2026 06:50	12-06-2026 13:52

22	ELECTCOACH	21	20	19	18	SNO.
OTHER	ELECTCOACH	OTHER	TRAINLIGHTING	ELECTCOACH	ELECTCOACH	ABN.TYPE
KGP	TATA	TATA	NGP	BS	JSG	SUBHEAD
KGP	KGP	KGP	KGP	KGP	KGP	REPORTSTTN
KUR	TATA	NGP	NGP	NGP	TIG	REPORTDIV
KGP	HWH	BSL	BSL	BS	JSG	FROM
KGP7443	TATA7046	NGP7317	NGP7317	BS7425	JSG7062	TO
SURJA KANTA DAS	J. P. SAH	RABESH KUMAR MISHRA	SUJIT MANDAL	DHARMENDRA GARDIA	CREW/CLUID	CREW/CLNAME
GDM	GDM	GDM	GDM	GDM	GDM	DESIG
14-06-2026	13-06-2026	12-06-2026	12-06-2026	12-06-2026	12-06-2026	ABNDATE
09:01	11:01	23:23	23:23	20:19	15:00	ABN.TIME
1111						FROMKM
1452						TO KM
YS	YS	YS	YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	FILLED BY
30687	12859	39481	39481	37533	30776	LOCO
TATE	GOC	HWHE	HWHE	GMOE	TATE	LOCO SHED
18046	37533	12262	12262	12859	18006	TRAIN
16-06-26 22:06	15-06-26 19:15	14-06-26 21:30	14-06-26 21:30	14-06-26 21:30	14-06-26 21:32	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	N	N	N	N	N	RemStts
DETAIL:DG staff Jitendra Kumar of train no-18046 arrived at door when the train was starting at SORO station and tried to enter in to train on run not introducing him self.also he was not in uniform ,on being asked he said do whatever you can. we do like this. This is for your information and necessary action please.	DETAIL:A/C Of LWLRRM S.E.202303 Not Working Train No.12859	DETAIL:SR 261159 LWLRRM ONLY ONE TUBELIGHT WORKING . Writing Table Side Tube Light Not Working. Difficult to Write in dim Light.	DETAIL:AC Is Not Working In LRRM SER 202303.As It Is Air Tight Compartment Feeling Like trapped and difficult to Breathe. Plz Rectify It.	DETAIL:AC Of LWLRRM SE 168860 IS NOT WORKING AT ALL, FEELING SUFFOCATED INSIDE AND UNABLE TO WORK PROPERLY AND SAFELY, RECTIFY IMMEDIATELY		
CLOSE_REM:AS PER C&W ELECT DEPT For your kind information, both of us are Railway employees, and our common goal is to provide better service to passengers. We can achieve this only by working together. If obstacles are created , passenger services may be adversely affected and the image of the Railways may suffer. (As informed by Jitender, he was in proper uniform.) Therefore, you are requested not to create any hindrance for the Electrical staff while they are performing their official duties.	CLOSE_REM:AS PER C&W ELECT DEPT Informed to SSEE/SRC to attend this issue during Primary maintenance on arrival 17/06/26	CLOSE_REM:AS PER C&W ELECT DEPT We have informed to SSEE/SRC to attend this issue during primary maintenance on arrival 15/06/2026	CLOSE_REM:AS PER C&W ELECT DEPT We informed to SSEE /SRC to attend this issue during primary maintenance on arrival 14/06/2026	CLOSE_REM:AS PER C&W ELECT DEPT We informed to SSEE/SRC to attend this issue during primary maintenance on arrival 15/06/2026.		
APP_REM:@CNWELECT/16-06-2026 16:19-For your kind information, both of us are Railway employees, and our common goal is to provide better service to passengers. We can achieve this only by working together. If obstacles are created , passenger services may be adversely affected and the image of the Railways may suffer. (As informed by Jitender, he was in proper uniform.) Therefore, you are requested not to create any hindrance for the Electrical staff while they are performing their official duties.			APP_REM:@SVSATYA/13-06-2026 13:40-Primary Maintenance Depot SRC, Forward To KGP Divn SER@CWCKGP/13-06-2026 14:07-Matter pertains to Electrical (G). Please forward accordingly.			
16-06-2026 16:19	13-06-2026 11:06	12-06-2026 23:29	13-06-2026 14:07	12-06-2026 20:23	12-06-2026 16:15	App Remarks Date
14-06-2026 16:11						Reporting Date

27	ELECTCOACH GENERAL POWER	26	25	24	23	SNO.
		ELECTCOACH	ELECTCOACH	ELECTCOACH	ELECTCOACH	ABN.TYPE
		OTHER	TRAIN LIGHTING	TRAIN LIGHTING	OTHER	SUBHEAD
	TATA	CSMT	BSL	ST	KGp	REPORT/STTN
	KGp	KGp	KGp	KGp	KGp	REPORTDIV
	BBN	IGP	IGP	BSL	KUR	FROM
	TATA	CSMT	BSL	ST	KGp	TO
	TATA7321	CSMT8325	BSL7329	ST7176	KGp7443	CREW/CLID
	ARUN KUMAR	V N GHANVAT	C. N. DICKSON	DHARMENDRA KUMAR YADAV	SURJA KANTA DAS	CREW/CLNAME
	GDM	GDM	GDM	GDM	GDM	DESIG
	19-06-2026	18-06-2026	16-06-2026	16-06-2026	14-06-2026	ABNDATE
	14:57	11:15	09:00	04:30	09:01	ABN.TIME
		137	136		1111	FROMKM
		00	444		1452	TO KM
	YS	YS	YS	YS	YS	STATUS
	APPUSER	APPUSER	APPUSER	APPUSER	SUPConsole	FILLED BY
	22502	37263	39326	37235	30687	LOCO
	SRCE	TATE	AQE	TATE	TATE	LOCO SHED
	12022 EXP.	12262	12859	12834	18046	TRAIN
	20-06-26 19:15	20-06-26 19:15	16-06-26 22:06	16-06-26 22:06	16-06-26 22:06	SMSTO LP
	KGp	KGp	KGp	KGp	KGp	Div
	Y	Y	Y	Y	Y	RemStts
	DETAIL:The AC of LWRRM SE 196599 of train number 12021/12022 exp. totally not working, creating suffocation as well as continuous sweating, hard to work which may hamper proper safety work, already reported by several concern staff on previous days	DETAIL:SR 261159 LWLRRM AC Not Working Properly And Blower Wkg Second Cab Light Blinking, Vestibule Doors Not Closing Purpose Primary Maintenance SRC	DETAIL:The AC and Flashing Tail Lamp are not Working.	DETAIL:When I have Taken Charge at BSL ETL Box Not Available In R/LSLRD No SER 245569	DETAIL:DG STAFF JITENDRA KUMAR OF TRAIN NO 18046 ARRIVED AT DOOR WHEN THE TRAIN WAS STARTING AT SFO AND TRIED TO ENTER IN TO TRAIN ON RUN NOT INTRODUCING HIMSELF .ALSO HE WAS NOT IN UNIFORM ,ON BEING ASKED HE SAID DO WHATEVER YOU CAN.WE DO LIKE THIS.	
	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC To Attend This Issue During Maintenance At Depot On Arrival Today.	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC To Attend The AC And Light Issue During Maintenance At Depot On 21 .06.2026.	CLOSE_REM:AS PER C&W ELECT DEPT We Have Informed To SSEE/SRC To Attend This Issue During Primary Maintenance On Arrival 17.06.26	CLOSE_REM:AS PER C&W ELECT DEPT Presently ETL Box Is Not Available At Electrical Store ,Once It Will Available,It Willbe Provided.	CLOSE_REM:AS PER C&W ELECT DEPT For your kind information, both of us are Railway employees, and our common goal is to provide better service to passengers. We can achieve this only by working together. If obstacles are created , passenger services may be adversely affected and the image of the Railways may suffer. (As informed by Jitender, he was in proper uniform.) Therefore, you are requested not to create any hindrance for the Electrical staff while they are performing their official duties.	
	APP_REM:@CNWELECT/20-06-2026 16:57-We Have Informed To SSEE/SRC To Attend This Issue During Maintenance At Depot On Arrival Today.	APP_REM:@ETLBBCR/18-06-2026 11:30-Train Pertains To SER SRC@CNWELECT/20-06-2026 16:56-We Have Informed To SSEE/SRC To Attend The AC And Light Issue During Maintenance At Depot On 21 .06.2026.	APP_REM:@CNWELECT/16-06-2026 15:55-We Have Informed To SSEE/SRC to Attend This Issue During Primary Maintenance On Arrival 17.06.26	APP_REM:@CNWELECT/16-06-2026 15:53-Presently ETL Box Is Not Available At Electrical Store ,Once It Will Available,It Willbe Provided.	APP_REM:@CNWELECT/16-06-2026 16:20-For your kind information, both of us are Railway employees, and our common goal is to provide better service to passengers. We can achieve this only by working together. If obstacles are created , passenger services may be adversely affected and the image of the Railways may suffer. (As informed by Jitender, he was in proper uniform.) Therefore, you are requested not to create any hindrance for the Electrical staff while they are performing their official duties.	
	20-06-2026 16:57	20-06-2026 16:56	16-06-2026 15:55	16-06-2026 15:53	16-06-2026 16:20	App Remarks Date
	19-06-2026 14:59	18-06-2026 11:19	16-06-2026 09:15	16-06-2026 06:10	14-06-2026 17:55	Reporting Date

30	ELECTCOACH	29	28	SNO.
OTHER	ELECTCOACH	OTHER	ELECTCOACH	ABN.TYPE
BSP	BSL	BSL	IGP	SUBHEAD
KGP	KGP	KGP	KGP	REPORTSTTN
BSP	IGP	IGP	IGP	REPORTDIV
CKP	BSL	BSL	BSL	FROM
BSP7425	BSL7329	BSL7329	IGP7029	TO
SUJIT MANDAL	C. N. DICKSON	C. N. DICKSON	SD SALUNKE	CREW/CLNAME
GDM	GDM	GDM	GDM	DESIG
24-06-2026	21-06-2026	21-06-2026	21-06-2026	ABNDATE
23:49	20:00	20:00	01:20	ABN.TIME
	136	136	136	FROMKM
	444	444	445	TO KM
YS	YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	APPUSER	FILLED BY
37124	37060	37060	37647	LOCO
GZBE	TATE	TATE	BZAE	LOCO SHED
18029	12261	12261	18029	TRAIN
25-06-26 13:50	23-06-26 23:21	23-06-26 23:21	23-06-26 23:21	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
Detail: LWWRM No SER 202303, AC Is Not Working as it is Air Tight Compartment Filling exhausted And Fill Like Difficult To Breath.				
Detail: AC IS NOT WORKING IN SER 226935 LWLRRM. ACTUALLY IN ALL TRAINS FROM HOWRAH.				
Detail: Three Persons Sleeping In The Power Car No. SER 242439 बहुत थंडा कर रहा है कम करने के लिये बोलने पर भी कम नहीं कर रहे हैं। थंडा के कारण मेरा सर दर्द हो रहा है। और सर्दी जुकाम हो रहा है।				
Closing Remarks: AS PER C&W ELECT DEPT We Have Informed SSEE/SRC To Attend This Issue During Maintenance At Depot On Arrival 27.06.26				
Closing Remarks: AS PER C&W ELECT We Have Informed To SSEE/SRC To Attend This Issue During Primary Maintenance At Depot On Arrival.				
Closing Remarks: AS PER C&W ELECT DEPT We Have Informed To Power Car Staff To Attend.				
App Remarks: @CNWELECT/25-06-2026 13:09-We Have Informed SSEE/SRC To Attend This Issue During Maintenance At Depot On Arrival 27.06.26				
App Remarks: @CNWELECT/23-06-2026 19:08-We Have Informed To SSEE/SRC To Attend This Issue During Primary Maintenance At Depot On Arrival. @CNWELECT/23-06-2026 19:08-We Have Informed To SSEE/SRC To Attend This Issue During Primary Maintenance At Depot On Arrival.				
App Remarks: @CNWELECT/23-06-2026 19:05-We Have Informed To Power Car Staff To Attend.				
25-06-2026 13:09	23-06-2026 19:08	23-06-2026 19:05	App Remarks Date	
24-06-2026 23:59	21-06-2026 20:43	21-06-2026 02:04	Reporting Date	

EMU

SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLUID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLED BY	LOCO	LOCO SHED	TRAIN	SMSTO LP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
1	EMU	OTHER	HWHS	KGP	KGP	HWH	TPKR1189	SUJOY KUMAR BISWAS	MMAN	04-06-2026	13:40			YS	CREW	108678	TPKR	38812	07-06-26 08:53	KGP	Y	DETAIL:SUN PROTECTOR OF WIND SCREEN IS TO BE PROVIDED ASAP	CLOSE_REM:as per EMU dept THE RAKE WILL BE ATTENDED ON ARRIVAL OF RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/06-06-2026 23:38-THE RAKE WILL BE ATTENDED ON ARRIVAL OF RAKE AT CARSHED AS SOON AS POSSIBLE	06-06-2026 23:38	04-06-2026 13:41
2	EMU	OTHER	HWHS	KGP	HWHS	KGP	TPKR1015	SANJAY BHUIYA	MMAN	07-06-2026	07:15			YS	CREW	198561	TPKR	38807	09-06-26 08:48	KGP	Y	DETAIL:CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:12-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	08-06-2026 23:12	07-06-2026 14:28
3	EMU	OTHER	HWHS	KGP	KGP	HWHS	TPKR1015	SANJAY BHUIYA	MMAN	07-06-2026	11:00			YS	CREW	108746	TPKR	38812	09-06-26 08:48	KGP	Y	DETAIL:CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:13-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	08-06-2026 23:13	07-06-2026 14:29
4	EMU	OTHER	HWHS	KGP	MCA	HWHS	TPKR1365	S.K.BAR	MMAN	08-06-2026	19:03	58	00	YS	CREW			38056	09-06-26 08:48	KGP	Y	DETAIL:ACP AT SEL 4TH FROM HWHEND.TM TRIED TO RE SET BUT UNSUCCESSFULL.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	APP_REM:@KBBAR/08-06-2026 23:13-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AS SOON AS POSSIBLE	08-06-2026 23:13	08-06-2026 19:16
5	EMU	BRAKE BINDING	HWHS	KGP	BVA	CGA	TPKR1322	SANJOY MANNA	MMAN	09-06-2026	08:03			YS	CREW				10-06-26 14:23	KGP	Y	DETAIL:MECHANICAL BRAKE BINDING BU6/DTC/248476 FOUND AT08.03HR,THEN REALESE AND TR STAT AT 09.30 HR	CLOSE_REM:AS PER EMU DEPT AFTER ARRIVAL OF THE RAKE AT CARSHED ON 09.06.26 , FOUND MARTENSITE ISSUE AT WHEEL NO 7 OF BU6 DTC. BOTH BRAKE BLOCK REPLACED	APP_REM:@KBBAR/10-06-2026 10:52-AFTER ARRIVAL OF THE RAKE AT CARSHED ON 09.06.26 , FOUND MARTENSITE ISSUE AT WHEEL NO 7 OF BU6 DTC. BOTH BRAKE BLOCK REPLACED	10-06-2026 10:52	09-06-2026 16:11
6	EMU	BRAKE BINDING	HWHS	KGP	MCA	KIG	TPKR1278	SUMAN CHOWDHURY	MMAN	10-06-2026	16:30	58	57	YS	CREW	198800	TPKR	38438	11-06-26 22:41	KGP	Y	DETAIL:UNIT 800 DTC BRAKE BINDING ,RELEASE AND ISOLATE ICA EPIC BIC BOTH.	CLOSE_REM:AS PER EMU DEPT ON 11.06.26 - FOUND RELATED WIRE OF EP BRAKE SHOWING EARTHED. SAME REPLACED	APP_REM:@KBBAR/11-06-2026 15:27-ON 11.06.26 - FOUND RELATED WIRE OF EP BRAKE SHOWING EARTHED. SAME REPLACED	11-06-2026 15:27	10-06-2026 18:43
7	EMU	OTHER	TPKR	KGP	KGP	TPKR	KGP1771	KAMALESH RAY	MMAN	11-06-2026	01:00			YS	CREW	198348	JAJ	38830	11-06-26 22:41	KGP	Y	DETAIL:TR NO 38830 , U/NO-198351/350/349/348 , CAB AC NOT WORKING	CLOSE_REM:AS PER EMU DEPT CAB AC WILL BE ATTENDED AFTER ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/11-06-2026 15:30-CAB AC WILL BE ATTENDED AFTER ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	11-06-2026 15:30	11-06-2026 02:43
8	EMU	OTHER	TPKR	KGP	HWH	KGP	KGP0059	KARTIK SARKAR	Chief Loco Inspector	14-06-2026	05:46	0.1	116	YS	APPUSER	108693	TPKR	38703	15-06-26 22:59	KGP	Y	DETAIL:Unit No: 108693 (KGP End) Guard Side Seat Is Too Low.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/15-06-2026 22:56-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	15-06-2026 22:56	14-06-2026 05:48
9	EMU	OTHER	AMTA	KGP	HWHS	AMZ	TPKR1015	SANJAY BHUIYA	MMAN	14-06-2026	20:15			YS	CREW	248480	TPKR	38919	16-06-26 11:06	KGP	Y	DETAIL:BU-1 MAC ICON YELLOW& CAB AC NOT WORKING.	CLOSE_REM:AS PER EMU DEPT AFTER FAULT RESET , MAC ICON BECAME NORMAL. REGARDING CAB AC SAME WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/16-06-2026 09:11-AFTER FAULT RESET , MAC ICON BECAME NORMAL. REGARDING CAB AC SAME WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	16-06-2026 09:11	14-06-2026 22:25
10	EMU	OTHER	TPKR	KGP	KGP	HWH	KGP0059	KARTIK SARKAR	Chief Loco Inspector	15-06-2026	08:31	116	0.1	YS	APPUSER	189278	TPKR	38810	16-06-26 11:06	KGP	Y	DETAIL:Unit No: 189278 HWH End Guard Side Look Glass To Be Change . Observe The Condition Of Look Out Glass In Picture.	CLOSE_REM:AS PER EMU WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	APP_REM:@KBBAR/15-06-2026 22:59-WILL BE ATTENDED ON ARRIVAL OF THE RAKE AT CARSHED AS SOON AS POSSIBLE	15-06-2026 22:59	15-06-2026 08:36

16	EMU	OTHER	15	14	13	12	11	SNO.
EMU	OTHER	HWHS	TPKR	KGK	KGK	TPKR	KGK	ABN.TYPE
BWN	KGK	PKU	KGK	KGK	KGK	TPKR	CAB1 AC NOT WORKING	SUBHEAD
MSAE	HWHS	TPKR	TPKR	TPKR	TPKR	TPKR	BNDM	REPORTSTTN
BWN1956	TPKR1320	TPKR	TPKR	TPKR	TPKR	TPKR	KGK	REPORTDIV
S.C.MONDAL ELEC	UTPAL DAN	KAMALESH RAY	SUNIL KUMAR SHAW	SRC7239	TPKR1363	CKP0128	CBSA	FROM
MMAN	MMAN	MMAN	SGDP	MMAN	MMAN	Chief Loco Inspector	TATA	TO
23-06-2026	21-06-2026	20-06-2026	17-06-2026	17-06-2026	17-06-2026	17-06-2026	RAJ/NATH SINGH	CREW/CLUID
16:10	03:45	07:00	12:46	11:30	08:57	08:57	08:57	DESIG
00/1	70							ABN.TIME
71/31	00							FROMKM
PN	YS	YS	YS	YS	YS	YS	YS	TO KM
APPUSER	CREW	CREW	APPUSER	APPUSER	CREW	APPUSER	APPUSER	STATUS
258001	10661	108678	238881	238881	238881	238881	238306	FILLED BY
KGPECS	BTECS	TPKR	TPKR	TPKR	TPKR	KGPECS	KGPECS	LOCO
68121	38406	38708	38501	38501	38501	68126	68126	LOCO SHED
	21-06-26 22:34	21-06-26 10:44	18-06-26 21:13	18-06-26 21:13	18-06-26 21:13	19-06-26 18:48	19-06-26 18:48	TRAIN
KGK	KGK	KGK	KGK	KGK	KGK	KGK	KGK	SMSTO LP
N	Y	Y	Y	Y	Y	Y	Y	Div
DETAIL:Unit number 258001/ TPKR /SER Tr No 68121 ,Talk Back not working UP and DN Both Directions ,Please do Needful action.	DETAIL:HWH END MOTORMAN SIDE CAB FAN NOT WORKING.	DETAIL:UNIT NO 678/677/676/675, TRAIN NO 38708 HORN SOMETIME NOT SOUNDING LOUDLY....	DETAIL:Ac Not Working , In Both Cab. Tr No 38501 , Unit No 238881/82/83/84,	DETAIL:U.NO-238881 AND U.NO-238884 BOTH CAB A/C NOT WORKING	DETAIL:AC of BU 238306 not working			RemStts
	CLOSE_REM:as per EMU dept ATTENDED ON 21.06.26 and RECTIFIED.	CLOSE_REM:AS PER EMU DEPT AT PKU NIGHT STABLING ON 21.06.26 - CHEKED AND FOUND OKAY	CLOSE_REM:AS PER EMU DEPT BOTH THE CAB ACS ARE UNDER MEDHAS WARRANTY. THOSE WILL BE ATTENDED ON PHASED MANNER.	CLOSE_REM:AS PER EMU DEPT BOTH THE CAB ACS ARE UNDER MEDHA's WARRANTY. THOSE WILL BE CHANGED IN PHASED MANNER.	CLOSE_REM:AS PER EMU DEPT WILL BE ATTENDED AT MEMU CARSHED/ KGP AFTER ARRIVAL OF THE RAKE AS SOON AS POSSIBLE			Closing Remarks
	APP_REM:@KBBAR/21-06-2026 17:13- ATTENDED ON 21.06.26	APP_REM:@KBBAR/21-06-2026 06:58-AT PKU NIGHT STABLING ON 21.06.26 - CHEKED AND FOUND OKAY	APP_REM:@KBBAR/18-06-2026 10:46-BOTH THE CAB ACS ARE UNDER MEDHAS WARRANTY. THOSE WILL BE ATTENDED ON PHASED MANNER.	APP_REM:@KBBAR/18-06-2026 10:42-BOTH THE CAB ACS ARE UNDER MEDHA's WARRANTY. THOSE WILL BE CHANGED IN PHASED MANNER.	APP_REM:@KBBAR/19-06-2026 18:00-WILL BE ATTENDED AT MEMU CARSHED/ KGP AFTER ARRIVAL OF THE RAKE AS SOON AS POSSIBLE			App Remarks
	21-06-2026 17:13	21-06-2026 06:58	18-06-2026 10:46	18-06-2026 10:42	19-06-2026 18:00			App Remarks Date
23-06-2026 19:39	21-06-2026 06:30	20-06-2026 11:11	17-06-2026 18:48	17-06-2026 18:44	17-06-2026 08:59			Reporting Date

ENGG

6	5	4	3	2	1	SNO.
ENGG	ENGG	ENGG	ENGG	ENGG	ENGG	ABN.TYPE
ENGG BOARDS	ENGG BOARDS	ENGG BOARDS	ENGG BOARDS	ENGG BOARDS	SIGNAL VISIBILITY	SUBHEAD
KGP	KGP	KGP	KGP	KGP	KGP	REPORT/STTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORT/DIV
VKD	GII	ROP	ROP	KGP	KGP	FROM
VKD	JGM	ROP	ROP	TATA	TATA	TO
KGP0078	KGP0079	KGP0039	KGP0027	KGP0043	KGP0043	CREW/CLUID
ANUP MANNA	SAGAR CHANDRA PAL	DL C.VENKATESHWAR RAO	EL B.K.BHOI	SHYAMAL KR DEY	SHYAMAL KR DEY	CREW/CLINAME
Chief Loco Inspector	Chief Loco Inspector	Chief Loco Inspector	Chief Loco Inspector	Chief Loco Inspector	Chief Loco Inspector	DESIG
03-06-2026	03-06-2026	03-06-2026	02-06-2026	01-06-2026	01-06-2026	ABNDATE
13:14	10:51	08:45	01:47	15:30	14:34	ABN.TIME
145/03	161/02	06		115	115	FROMKM
145/05	160/26	115		249	249	TO KM
YS	YS	YS	YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	APPUSER	FILLED/DBY
45031	235705	19002	30527	60117	60114	LOCO
NGCD			BLEE	SREE	SREE	LOCO SHED
12510	20898	D/SPIC	12837		Bohr E	TRAIN
04-06-26 06:55	04-06-26 06:55	04-06-26 20:30	02-06-26 21:58	02-06-26 21:58	02-06-26 21:58	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	RemStts
DETAIL:No C/I/B and Tp/Tg Bd found of 30CD.	DETAIL:As per DCO-45 CD but 30 Speed Board Provide	DETAIL:PSR at Km No-54/37X-55/25X at KIG UP LINE But Speed Indicator Provided at 55/23X	DETAIL:ROP JN YARD: UP Main Line CD 20 kmph from 212/03 to 214/13 for newly inserted Points 101B & 130A. & all Engineering Boards are Provided. But Observe One Speed Indicator Board for 30 kmph provided in between 20 CD zone & not mention in Caution Order	DETAIL:No cross over clear board cku - kkpr joint line	DETAIL:GII UP HOME SIGNAL AT KM 168/9 . obstruction by Trees	
CLOSE_REM:AS PER ENGG DEPT CD HAS CANCELLED AT 14.05 HRS.	CLOSE_REM:AS PER ENGG DEPT Complied At 9.00 Hrs. As Per Pwi Jgm.	CLOSE_REM:As per Engg dept Ci Board Was In Correct Position. As Per IRPWM. As Per Pwi Kig.	CLOSE_REM:as per engg dept 30 Cd Has Been Cancelled & Board Removed.	CLOSE_REM:AS PER ENGG DEPT Pwi Attended & Complied on 02-06-2026. As Per Pwi Gii.	CLOSE_REM:AS PER ENGG DEPT SSE SIGNAL CKU INFORMED TO JE PWAY CKU FOR TRIMMING OF TREE BRANCHES. Comlied By 10.30 Hrs On 02.06.26.as Per Pwi Gii.	Closing Remarks
APP_REM:@ENGGKGP/03-06-2026 21:39-CD HAS CANCELLED AT 14.05 HRS.	APP_REM:@ENGGKGP/03-06-2026 21:41-Complied At 9.00 Hrs. As Per Pwi Jgm.	APP_REM:@ENGGKGP/03-06-2026 21:48-Ci Board Was In Correct Position. As Per IRPWM. As Per Pwi Kig.	APP_REM:@ENGGKGP/02-06-2026 07:35-30 Cd Has Been Cancelled & Board Removed.	APP_REM:@ENGGCNTLCKP/01-06-2026 23:38-Not Pertains To CKP DIV @ENGGKGP/02-06-2026 15:37-Pwi Attended & Complied. As Per Pwi Gii.	APP_REM:@STCNTLCKP1/01-06-2026 16:17-The matter is not related to CKP Division. The same has been informed to KGP/Testroom@CNLTRKGP/01-06-2026 18:25-SSE SIGNAL CKU INFORMED TO JE PWAY CKU FOR TRIMMING OF TREE BRANCHES. @ CMS UJJAL also informed to ENGG DEPARTMENT @ENGGKGP/02-06-2026 15:38-Comlied By 10.30 Hrs On 02.06.26.as Per Pwi Gii.	App Remarks
03-06-2026 21:39	03-06-2026 21:41	03-06-2026 21:48	02-06-2026 07:35	02-06-2026 15:37	02-06-2026 15:38	App Remarks Date
03-06-2026 13:18	03-06-2026 10:55	03-06-2026 10:52	02-06-2026 03:49	01-06-2026 15:31	01-06-2026 14:36	Reporting Date

[illegible]

25	24	23	SNO.
ENG	ENG	ENG	ABN.TYPE
ENG BOARDS	ENG BOARDS	ENG BOARDS	SUBHEAD
KGP	NMP	PURI	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
JGM	NSI	BTS	FROM
KKQ	DNT	ROP	TO
KGP0084	NMP1599	KUR2751	CREW/CLUID
UDAY GIRI DAS	EL SUMAN BHOWMIK G12	SUNANDA CHANDRA RANA	CREW/CLINAME
Chief Loco Inspector	LPG	LPM	DESIG
23-06-2026	22-06-2026	21-06-2026	ABNDATE
16:36	07:55	18:45	ABN.TIME
147/12	162/23	212/03	FROMKM
131/02	162/25	212/05	ТО KM
YS	YS	YS	STATUS
APPUSER	APPUSER	SUPConsole	FILLED BY
20074	42408	39100	LOCO
NGCD	MLDD	SRCE	LOCO SHED
68024	E/BOST/TSIJ	12821	TRAIN
23-06-26 23:22	22-06-26 13:17	22-06-26 13:17	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
Detail:Speed Restrictions For elephant Corridor Of 50 Kmph Of Km No 147/12 To 142/02 Km No 135/02 To 131/02 For Both The Spot TP & TG Board not In Proper Place, Should Follow Engg Distance			
CLOSE_REM:AS PER ENGG DEPT All Boards Are Provided As Per Norms. As Per Pwi Jgm.			
APP_REM:@ENGKGP/23-06-2026 21:33-All Boards Are Provided As Per Norm's. As Per Pwi Jgm.			
23-06-2026 21:33			
23-06-2026 16:56			
Detail:NO SPEED BOARD OF 45 AT KMNO-212/03-05 HAS BETWEEN BTS-ROP.			
CLOSE_REM:AS PER ENGG DEPT Provided on 22-06-2026 08:00 hrs.. As Per Pwi Const.			
APP_REM:@ENGKGP/22-06-2026 09:12-Provided. As Per Pwi Const.			
22-06-2026 09:12			
21-06-2026 21:55			
Detail:No Caution Indicator And Speed Board are provided			
CLOSE_REM:AS PER ENGG DEPT Short Duration Of Work. Cd Will Be Canceled By 11.00 Hrs. As Per Pwi Dnt.			
APP_REM:@ENGKGP/22-06-2026 09:08-Short Duration Of Work. Cd Will Be Canceled By 11.00 Hrs. As Per Pwi Dnt.			
22-06-2026 09:08			
22-06-2026 08:23			
Closing Remarks			
App Remarks			
App Remarks Date			
Reporting Date			

LOCO

8	7	6	5	4	3	2	1	SNO.
LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	LOCO	ABN.TYPE
CAB2 AC NOT WORKING	CAB1 AC NOT WORKING	SEAT DEFECTIVE	CAB2 AC NOT WORKING	OTHER	CAB1 AC NOT WORKING	OTHER	CAB1 AC NOT WORKING	SUBHEAD
DGHA	SBP	MDP	ANGL	HWHS	TATA	GZB	TLHR	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HWH	KPIG	JAU	SBPY	DGHA	SRC	GZB	KLAG	FROM
DGHA	RAIR	CRJ	JRPD	HWH	TATA	ANVT	TLHR	TO
SRC1762	SBP1863	MDP1175	SBPY1020	SRC2384	SRC2078	DL0079	TLHR2844	CREW/CLIID
EL RAJEN GHOSH C	TIKU CHAND DEHURY	BIKASH BHAGAT	BHISMA KUMAR MAJHI	EL TRIDIB KR MAHAPATRA C	EL BISWAJIT HALDAR C	Raj Kumar MS	SANTOSH YADAV	CREW/CLINAME
LPG	LPG	ALP	LPG	LPP	LPM	Chief Loco Inspector	LPG	DESIG
08-06-2026	07-06-2026	07-06-2026	06-06-2026	05-06-2026	03-06-2026	03-06-2026	01-06-2026	ABNDATE
19:40	03:00	00:30	01:00	00:20	13:00	11:01	20:07	ABN.TIME
01	140			87	01			FROMKM
188	70			01	248			TO KM
YS	YS	YS	YS	YS	YS	YS	YS	STATUS
CREW	CREW	APPUSER	CREW	CREW	CREW	APPUSER	APPUSER	FILLED BY
22398	28575	27918	27534	37010	22896	30762	27227	LOCO
SRCE	KGPE	KGPE	KGPE	SRCE	SRCE	SRCE	KGPE	LOCO SHED
22897	DN/STD BY	EC/DHN	STAND BY	22898	12021	04013	ME/BOBRN(R)	TRAIN
09-06-26 20:57	08-06-26 12:52	08-06-26 12:52	06-06-26 21:23	05-06-26 18:14	04-06-26 14:11	03-06-26 20:50	02-06-26 13:30	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:AC NOT PROVIDED		DETAIL:Please Provide Proper Chair In This Locomotive. There Is No Chair Provided In This Locomotive.	DETAIL:AC NOT FITTED	DETAIL:AC NOT PROVIDED IN CAB,SO VERY UNCOMFORTABLE TO WORK.	DETAIL:BOTH CAB AC NOT WORKING DUE TO AC MCB DEFECTIVE.	DETAIL:Both Cabs & Corridor Both Side Locks Defecient. (Pb)	DETAIL:Both Cab Ac Not Provided	
CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Loco Will Be Send To Home Shed For Attention On Arrival At Kgp Div.	CLOSE_REM:AS PER LOCO DEPT Informed To Shed.	CLOSE_REM:AS PER LOCO DEPT Informed to Shed.	CLOSE_REM:as per loco dept Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Will Be Attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed.	Closing Remarks
APP_REM:@KGPLOCO/09-06-2026 11:58-Informed To Shed	APP_REM:@KGPLOCO/08-06-2026 12:03-Informed To Shed	APP_REM:@KGPLOCO/08-06-2026 12:03-Loco Will Be Send To Home Shed For Attention On Arrival At Kgp Div.	APP_REM:@SBPDPC/06-06-2026 09:13-Forward Message to KGP Div.@KGPLOCO/06-06-2026 12:12-Informed To Shed	APP_REM:@KGPLOCO/05-06-2026 13:26-Informed to Shed	APP_REM:@KGPLOCO/04-06-2026 11:37-Informed To Shed	APP_REM:@KGPLOCO/03-06-2026 18:12-Will Be Attended On Arrival At Srce Shed	APP_REM:@KGPLOCO/02-06-2026 11:12-Informed To Shed	App Remarks
09-06-2026 11:58	08-06-2026 12:03	08-06-2026 12:03	06-06-2026 12:12	05-06-2026 13:26	04-06-2026 11:37	03-06-2026 18:12	02-06-2026 11:12	App Remarks Date
08-06-2026 23:55	07-06-2026 11:26	07-06-2026 05:49	06-06-2026 08:55	05-06-2026 06:12	03-06-2026 13:14	03-06-2026 11:03	01-06-2026 20:09	Reporting Date

15	LOCO	14	13	12	11	10	9	SNO.
CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	OTHER	OTHERS CAB ISSUES	KAVACH	CAB1 AC NOT WORKING	CAB2 AC NOT WORKING	ABN.TYPE
KGp	SBP	LTT	LTT	SNF	KOTA	BNDM	DDUN	REPORTS/TTN
KGp	KGp	KGp	KGp	KGp	KGp	KGp	KGp	REPORT/DIV
SRC	LPG	ATG	ATG	KZJ	NDLS	BSP	DDUN	FROM
KGp	LPG	ASO	ASO	SNF	KOTA	TATA	CNBN	TO
KGp1009	SBP1863	CSMT5341	CSMT5341	SNF2890	KOTA1045	OKP0128	DDUN1244	CREW/CLID
EL CHANDRA SEKHAR MAITY	TIKU CHAND DEHURY	C B SHIVSHARAN	C B SHIVSHARAN	ROSHAN BABU BADA GG	ARVIND SINGH	RAJ NATH SINGH	SHASHI KANT KUMAR II MUNNU	CREW/CLNAME
LPP	LPG	LPM	LPM	SALP	LPM	Chief Loco Inspector	LPG	DESIG
12-06-2026	10-06-2026	10-06-2026	10-06-2026	10-06-2026	10-06-2026	09-06-2026	09-06-2026	ABNDATE
18:56	22:00	12:54	12:54	12:00	08:00	17:21	08:30	ABN.TIME
7	24	94/37	94/37	324			00	FROMKM
115	24	86/53	86/53	175			00	TO KM
YS	YS	YS	YS	YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	CREW	CREW	CREW	APPUSER	APPUSER	FILLED BY
30743	28203	39568	39568	27186		30804	28204	LOCO
SRCE	KGPE	SRCE	SRCE	KGPE		SRCE	KGPE	LOCO SHED
22807	STAND BY	13379	13379	KSNK	20452	20821	GPTH	TRAIN
13-06-26 21:01	11-06-26 22:48	10-06-26 22:33	10-06-26 22:48	11-06-26 22:48	12-06-26 15:59	10-06-26 14:21	10-06-26 14:21	SMSTO LP
KGp	KGp	KGp	KGp	KGp	KGp	KGp	KGp	Div
Y	Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:BOTH SIDE CAB AC NOT PROVIDED		DETAIL:knorr brems display hang/stuckup with message FAULT PENALTY KEEP IN FS but loco responding normal with bp pressure 5.00kg/cm2 upto destination. once malfunctionjed and applied emergency brakes.	DETAIL:Loco seats not suitable for long working hours. ALP desk is extremely congested, there no space left to keep caution order.	DETAIL:NOT AVAILABLE N LOCOMOTIVE	DETAIL:Both cab AC not working loco 20804/SRC	DETAIL:Both Cab AC Not Provided		Detail
CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT - Loco Running In Mis Link , Mis Link Done By CSTM Div. Loco Will Be Attended On Arrival At KGP Div.	CLOSE_REM:AS PER LOCO DEPT Will Be Attended On Arrival At Kgpe Shed. Now Working in S. C. Railway.	CLOSE_REM:AS PER LOCO DEPT Fitting Of KAVACH In Every Loco Is On Progress. It will Be Completed Soon	CLOSE_REM:AS PER LOCO DEPT Informed To Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Shed		Closing Remarks
APP_REM:@KGPLOCO/13-06-2026 18:20-Informed To Shed	APP_REM:@SBPDP/11-06-2026 04:10-Forwarded To KGP DIV@KGPLOCO/11-06-2026 18:14-Informed To Shed	APP_REM:@KGPLOCO/10-06-2026 18:26-Loco Running In Mis Link , Mis Link Done By CSTM Div. Loco Will Be Attended On Arrival At KGP Div.	APP_REM:@KGPLOCO/11-06-2026 18:13-Will Be Attended On Arrival At Kgpe Shed. Now Working AS. C. Railway.	APP_REM:@STABN/10-06-2026 21:10-INFORMED TO CTLC/KOTAFOR TAKING NECESSARY ACTION@CNLTRKGP/11-06-2026 12:14-This abnormality does not belong to S&T DEPARTMENT @KGPLOCO/12-06-2026 11:36-Fitting Of KAVACH In Every Loco Is On Progress. It will Be Completed Soon	APP_REM:@KGPLOCO/10-06-2026 11:33-Informed To Shed	APP_REM:@KGPLOCO/10-06-2026 11:32-Informed To Shed		App Remarks
13-06-2026 18:20	11-06-2026 18:14	10-06-2026 18:26	11-06-2026 18:13	12-06-2026 11:36	10-06-2026 11:33	10-06-2026 11:32		App Remarks Date
12-06-2026 20:57	10-06-2026 23:57	10-06-2026 15:41	10-06-2026 18:06	10-06-2026 14:12	09-06-2026 17:23	09-06-2026 20:28		Reporting Date

23	LOCO	20	19	18	17	16	SNO.
CAB2 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	CAB1 AC NOT WORKING	OTHER	OTHERS CAB ISSUES	CAB1 AC NOT WORKING	ABN.TYPE
SBP	RPH	RPH	RPH	APDJ	VSKP	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HATB	NGF	NGF	NGF	NJP	RGDA	KGP	FROM
SSN	TDLE	TDLE	TDLE	MLDT	VSKP	SRC	TO
SBPY1002	RPH3088	RPH3088	RPH3088	APDJ1722	VSKP2172	KGP1009	CREW/CLIID
MANORANJAN MAHARANA	PIJUSH KUMAR GHOSH T MU	PIJUSH KUMAR GHOSH T MU	PIJUSH KUMAR GHOSH T MU	SUVANKAR KOLLEY	LANKA SRINIVASA RAO	EL CHANDRA SEKHAR MAITY	CREW/CLINAME
LPG	SALP	SALP	SALP	SALP	LPM	LPP	DESIG
18-06-2026	17-06-2026	17-06-2026	16-06-2026	15-06-2026	14-06-2026	13-06-2026	ABNDATE
08:00	22:10	11:43	11:40	21:00	06:00	22:00	ABN.TIME
27	0/1				343	115	FROMKM
549	248/8				878	7	TO KM
YS	YS	YS	YS	YS	YS	YS	STATUS
CREW	APPUSER	APPUSER	APPUSER	APPUSER	CREW	APPUSER	FILLED BY
27161	37070	27439	27572	39094	25051	22385	LOCO
KGPE	SRCE	KGPE	KGPE	SRCE	SRCE	SRCE	LOCO SHED
PT/18303	18005	FKK	FKK	12378	18637	18048	TRAIN
19-06-26 17:46	18-06-26 21:05	16-06-26 22:00	16-06-26 22:00	16-06-26 15:40	15-06-26 15:32	15-06-26 15:32	SMSTO LP
KGP	KGP	KGP	KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	Y	Y	Y	RemStts
DETAIL:LOCO-27161 AC NOT PROVIDED	DETAIL:VCD ISO AT BDTS SHED REMARK AS PER INCOMEING LP. WHILE TOC BRC INFORM TO TLC BCT	DETAIL:Provide AC In Cab	DETAIL:Provide AC In Cab. Think About The Situation Of Crew In This Summer Time. Almost 55 Degree Temperature In CAB.	DETAIL:Cab2 Alp Side Horn Started Blowing Continuously	DETAIL:WATER LEAKING BADLY FROM CAB1 AC UNIT ABOVE LP HEAD	DETAIL:BOTH SIDE CAB AC NOT WORKING	Detail
CLOSE_REM:as per loco dept Informed To Kgpe Shed	CLOSE_REM:AS PER LOCO DEPT - Loco Working In Mistlink. Same Will Be attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Kgpe Shed	CLOSE_REM:AS PER LOCO DEPT Informed To Kgpe Shed For AC Modifications	CLOSE_REM:AS PRR LOCO DEPT Loco Working In Mislink By NF Railway. Same Will Be Attended On Arrival At Srce Shed	CLOSE_REM:AS PER LOCO DEPT Loco Now Working In Mislink By RNC Div. So, It Will Be Attended On Arrival At SRCE Shed.	CLOSE_REM:AS PER LOCO DEPT Informed To Srce Shed	Closing Remarks
APP_REM:@SBPDPC/18-06-2026 20:30-Forward To KGP Division @KGPLOCO/19-06-2026 11:17-Informed To Kgpe Shed	APP_REM:@KGPLOCO/18-06-2026 13:59-Loco Working In Mislink. Same Will Be attended On Arrival At Srce Shed	APP_REM:@KGPLOCO/16-06-2026 16:54-Informed To Kgpe Shed	APP_REM:@KGPLOCO/16-06-2026 16:52-Informed To Kgpe Shed For AC Modifications	APP_REM:@KGPLOCO/16-06-2026 11:46-Loco Working In Mislink By NF Railway. Same Will Be Attended On Arrival At Srce Shed	APP_REM:@VSKPABRLO/14-06-2026 11:13-Forwarded To SRC shed and KGP division for Necessary attention@KGPLOCO/15-06-2026 11:52-Loco Now Working In Mistlink By RNC Div. So, it Will Be Attended On Arrival At SRCE Shed.	APP_REM:@KGPLOCO/15-06-2026 11:46-Informed To Srce Shed	App Remarks
19-06-2026 11:17	18-06-2026 13:59	16-06-2026 16:06	16-06-2026 16:52	16-06-2026 11:46	15-06-2026 11:52	15-06-2026 11:46	App Remarks Date
18-06-2026 19:46	17-06-2026 21:57	16-06-2026 11:43	16-06-2026 11:42	16-06-2026 10:01	14-06-2026 11:11	14-06-2026 11:56	Reporting Date

SNO.	24	25	26	27	28
ABN.TYPE	LOCO	LOCO	LOCO	LOCO	LOCO
SUBHEAD	TM-3 Issolation	BG-2 (Bogie)	OTHER	SPM CAB-1 defective	SEAT DEFECTIVE
REPORTSITTN	ED	CSMT	KYQ	SRC	IGPX
REPORTDIV	KGP	KGP	KGP	KGP	KGP
FROM	ERS	IGP	SGUT	ADRA	BSL
TO	ED	CSMT	KYQ	HWH	IGP
CREW/GLIID	ERS1553	CSMT5413	SGUT1340	ADRA1953	BSL2639
CREW/GLINAME	JOSE.M.A	P K DANDEKAR.	YUBRAJ AMIT D/E	I.K.HIMANSHU	SURAJ V MAHAJAN IN PP
DESIG	LPM	LPM	LPM	LPP	SALP
ABNDATE	18-06-2026	19-06-2026	19-06-2026	22-06-2026	24-06-2026
ABN.TIME	14:36	05:12	19:04	10:20	07:00
FROMKM	00	138	00	283	444
TO KM	305	001	00	1	136
STATUS	YS	YS	YS	YS	YS
FILLED BY	CREW	CREW	SUPConsole	CREW	CREW
LOCO	30754	30731	37023	22566	30699
LOCO SHED	SRCE	SRCE	SRCE	SRCE	SRCE
TRAIN	16378	12810	12506 UP	18628	13379
SMSTO LP	19-06-26 17:46	19-06-26 17:46	19-06-26 23:01	24-06-26 21:02	24-06-26 21:02
Div	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	Y	Y
Detail	DETAIL:TM 3 ISOLATED PREVIOUS REMARK	DETAIL:WHILE TOC BOGIE 2 ISOLATE CONDITION SAME REPITED TO LPC AND WORK UP TO CSMT	DETAIL:CAB-01 FIDE BRECK PIPE IS NOT GOOD CONDITION (P/B)...	DETAIL:DIGITAL SPM NOT WORKING PROPERLY AND ANALOGUE SPM BACKLIGHT GOING OFF ON ITS OWN ALSO WIPER IS DEFFICIENT.	DETAIL:CAB 01 ALP SEAT CUSHION DEFECTIVE. CAUSING BACK PAIN
Closing Remarks	CLOSE_REM:AS PER LOCO DEPT Loco Mis Link By DLI Div. It Will Be Attended On Arrival At Kgp Shed	CLOSE_REM:AS PER LOCO DEPT Loco Will Return Back By 12809 Ex Asper Link. On Arrival Loco Will Be Send To Srce Shed For Attention	CLOSE_REM:AS PER LOCO DEPT Loco Working In RNC Div. Link. So, It Will Be Attended Only When Come To Kgp Div.	CLOSE_REM:AS PER LOCO DEPT Loco Under TR At Srce Shed Due To Spm Defective	CLOSE_REM:AS PER LOCO DEPT Loco Under Mislink By DHN Div. It Will Be Attended When Return To Kgpe Shed
App Remarks	APP_REM:@KGPLOCO/19-06-2026 11:18- Loco Mis Link By DLI Div. It Will Be Attended On Arrival At Kgp Shed	APP_REM:@KGPLOCO/19-06-2026 11:28- Loco Will Return Back By 12809 Ex Asper Link. On Arrival Loco Will Be Send To Srce Shed For Attention	APP_REM:@KGPLOCO/19-06-2026 19:36- Loco Working In RNC Div. Link. So, It Will Be Attended Only When Come To Kgp Div.	APP_REM:@KGPLOCO/24-06-2026 17:04- Loco Under TR At Srce Shed Due To Spm Defective	APP_REM:@KGPLOCO/24-06-2026 17:06- Loco Under Mislink By DHN Div. It Will Be Attended When Return To Kgpe Shed
App Remarks Date	19-06-2026 11:18	19-06-2026 11:28	19-06-2026 19:36	24-06-2026 17:04	24-06-2026 17:06
Reporting Date	18-06-2026 14:50	19-06-2026 08:59	19-06-2026 19:05	22-06-2026 17:03	24-06-2026 11:10

MISC

SNO.	ABN.TYPE	SUBHEAD	REPORTSTTN	REPORTDIV	FROM	TO	CREW/CLIID	CREW/CLINAME	DESIG	ABNDATE	ABN.TIME	FROMKM	TO KM	STATUS	FILLEDBY	LOCO	LOCO SHED	TRAIN	SMSTOLP	Div	RemStts	Detail	Closing Remarks	App Remarks	App Remarks Date	Reporting Date
2	MISC	OTHER	DDJ	KGP	BLN	ADL	DDJ2813	SUSANTA KUMAR GANGULY	LPG	13-06-2026	21:00			YS	APPUSER	28710	RTMD	JNPT CONTAINER	15-06-26 19:15	KGP	N	DETAIL:My T.O at DDJ at 12:30 and O.D at 12:00 on 13.06.2026. I spared to BLN by EMU and working from BLN to ADL via BTNG and off duty at ADL at 18:00. I deposit my CTR to on duty ATFR/ADL after off duty for update my working details but CMS staff Sri Somnath Paul wrongly update my working details in CMS from DDJ to ADL. He also wrongly update on another day my CTR on 12.05.2026	CLOSE_REM:AS PER ADL CC/IC The CMS outsourcing staff failed to enter the PT details ex DDJ to BLN and working ex BLN to ADL. Instead of this he entered the whole duty as Working resulting which 120 Km mileage generated in CMS. The CMS staff is already counselled not to make such mistakes in future otherwise serious action will be taken.			14-06-2026 07:31
1	MISC	OTHER	HWHS	KGP	JLI	MJH	TPKR1015	SANJAY BHUIYA	MMAN	06-06-2026	09:25	32/12	32/11	YS	CREW	128248		38910	07-06-26 21:17	KGP	N	DETAIL:CATTLE RUN OVER .STOPPED & CHECKED NO ABNORMALITY.U/GEAR TO BE CHECKED.	CLOSE_REM:AS PER SECURITY DEPT after receiving information from SCNL/KGP regarding cattle run over inbetween JLI- Manju on 06.06.2026, myself SI/G.K.Adhikari enquired the matter & came to know that one cattle was run over by T/ No-38910 on 06.06.2026 at KM No-HA 32/15- 16 inbetween JLI- Manju. The body was removed by engineering staff at about 10.30 hrs. For this incident T/No-38910 suffered detention for 10 minutes & T/ No-38907 was issued caution order. This is for favour of kind information			06-06-2026 11:51

OHE

1	SNO.	
OHE	ABN.TYPE	
OTHER	SUBHEAD	
KGP	REPORTSTTN	
KGP	REPORTDIV	
MKO	FROM	
SORO	TO	
KGP0079	CREW/CLIID	
SAGAR CHANDRA PAL	CREW/CLINAME	
Chief Loco Inspector	DESIG	
11-06-2026	ABNDATE	
09:11	ABN.TIME	
267/30	FROMKM	
267/28	TO KM	
YS	STATUS	
APPUSER	FILLED BY	
39481	LOCO	
HWHE	LOCO SHED	
12842	TRAIN	
13-06-26 20:56	SMSTO LP	
KGP	Div	
Y	RemStts	
DETAIL:Sigma Board provide before Gate Inner Dist/Gate Sig- GS-6	Detail	
CLOSE_REM:AS PER OHE DEPT Sigma Board position shifted at proper place at 16:45 hrs on 13.06.26	Closing Remarks	
APP_REM:@CNLTRKGP/11-06- 2026 19:07-Sigma board is not concerned to S&T department. @TPCTRD/13-06-2026 16:57- Sigma Board position shifted at proper place at 16:45 hrs on 13.06.26	App Remarks	
13-06-2026 16:57	App Remarks Date	
11-06-2026 09:19	Reporting Date	

SECURITY

SNO.	1	2	3	4	5
ABN.TYPE	SECURITY	SECURITY	SECURITY	SECURITY	SECURITY
SUBHEAD	ACP	OTHER	RUN OVER	ACP	ACP
REPORTSTTN	KGP	KGP	KGP	SRC	SRC
REPORTDIV	KGP	KGP	KGP	KGP	KGP
FROM	BHC	SEL	GII	KIG	HAUR
TO	KGP	ADL	CKU	DTE	PKU
CREW/CLIID	KGP2177	KGP2086	KGP1130	KGP3349	SRC1501
CREW/CLINAME	EL VIKASH KUMAR IG12	EL SADHAN DAS	EL SIDDHARTHA SARATHI RAKSHIT	EL MANOJ KUMAR ROY	EL SWAPAN BANERJEE C
DESIG	LPG	LPG	LPM	LPP	LPP
ABNDATE	01-06-2026	01-06-2026	03-06-2026	03-06-2026	06-06-2026
ABN.TIME	00:58	12:51	05:06	19:50	00:34
FROMKM	233/06	14/SLL/28	174/13	51/10	71/02
TO KM	233/04	14/SLL/26	174/15	51/08	71/04
STATUS	YS	YS	YS	YS	YS
FILLED BY	SUPConsole	APPUSER	SUPConsole	CREW	CREW
LOCO	32049	30764	39039	22800	37263
LOCO SHED	AQE	SRCE	GZBE	EDDX	TATE
TRAIN	18022	18029	12801	06075	12840
SMSTO LP	02-06-26 13:33	02-06-26 13:33	05-06-26 22:47	06-06-26 09:30	06-06-26 09:30
Div	KGP	KGP	KGP	KGP	KGP
RemStts	Y	Y	Y	Y	Y
Detail	DETAIL:NYA IB/S FOUND RED AT 00/37,THEN STOP THE TRAIN THEN IB/S OFF AT 00/51 SUDD. PRESSURE DROP INFORM TO TMR AND ALP GO TO CHECK ACP.ACP FOUND FROM NEXT TO B/VAN THEN RESET BUT NOT RESET THEN ALP ISOLATE THE COACH IN PRESENCE OF TMR SAME REPORT TO O/D SM/BPE AND TLC/KGP.M.NASIMUDIN START 01:30.	DETAIL:ACP at Coach No. SE188108 , B-2 And Reset by TMR	DETAIL:ONE FEMALE WEARING RED SAREE SUDDENLY CAME ON TRACK AND DASHED WITH TRAIN AND KNOCK DOWN.	DETAIL:ACP FROM COACH NO - 118247 SER S-3 ,RESET BY ALP. TRAIN STARTED AT 19/58.	DETAIL:ACP AT PKU STATION AT 00.34.COACH NO.193665 S1.ISOLATE BY ALP AT 00.38.RESTART AT 00.43
Closing Remarks	CLOSE_REM:AS PER SECURITY DEPT In this regard a case vide No.463/26 dated 01.06.26 U/S 141 Railway Act has been registered at RPF/Post/HIJLI against arrested person namely Bimal Das, A/A-33 yrs, S/O- Banamali Das, R/O- Banpatna, P.S-Kharagpur (Local), Dist-Paschim Medinipur, W.B.	CLOSE_REM:AS PER SECURITY DEPT In this connection a case vide No. 1438/2026 dtd. 01.06.2026 U/S- 141 Rly Act was registered at RPF/POST/SRC-G against arrested person namely Loko Khurail, Male, aged about 25 years, S/O Pran Khurail, R/O Hawapada, Sankrail, P.S. Sankrail, Dist. Howrah(WB).	CLOSE_REM:AS PER SECURITY DEPT In this connection a case vide no.195/26 dated 03.06.26 u/s 141 Railway Act 1989 has been registered at RPF Post JGM against the arrested person namely Abu Rahaman A/A-35 S/o-Lt Rafikul Rahaman, R/oParihati, P.S-Jamboni,Dist-Jhargram (W.B).	CLOSE_REM:AS PER SECURITY DEPT In this connection SMR/DTE made a DE No.818 dated 03.06.2026. On basis of SMR/DTE DE No a case vide No 537/26 dated 06.06.2026 U/S 141 RA against the unknown.	CLOSE_REM:AS PER SECURITY DEPT In this connection a case vide No.1195/2026. Date 06-06-2026 U/S 141 RLY Act registered at RPF-Post/PKU against the arrested person. Sounak Hait, A/A-23yrs,S/O-Sushanta Hait,R/O-Mangalduari, Ratulia,PS-Mangalduari, Ratulia,PS-Panskura,Dist-Purba Medinipur.E.O.
App Remarks	APP_REM:@SECUKGP/02-06-2026 11:53-In this regard a case vide No.463/26 dated 01.06.26 U/S 141 Railway Act has been registered at RPF/Post/HIJLI against arrested person namely Bimal Das, A/A-33 yrs, S/O-Banamali Das, R/O- Banpatna, P.S-Kharagpur (Local), Dist-Paschim Medinipur, W.B.	APP_REM:@SECUKGP/02-06-2026 11:54-In this connection a case vide No. 1438/2026 dtd. 01.06.2026 U/S- 141 Rly Act was registered at RPF/POST/SRC-G against arrested person namely Loko Khurail, Male, aged about 25 years, S/O Pran Khurail, R/O Hawapada, Sankrail, P.S. Sankrail, Dist. Howrah(WB).	APP_REM:@SECUKGP/05-06-2026 19:29-In this connection a case vide no.195/26 dated 03.06.26 u/s 141 Railway Act 1989 has been registered at RPF Post JGM against the arrested person namely Abu Rahaman A/A-35 S/o-Lt Rafikul Rahaman, R/oParihati, P.S-Jamboni,Dist-Jhargram (W.B).	APP_REM:@SECUKGP/06-06-2026 08:07-In this connection SMR/DTE made a DE No.818 dated 03.06.2026. On basis of SMR/DTE DE No a case vide No 537/26 dated 06.06.2026 U/S 141 RA against the unknown.	APP_REM:@SECUKGP/06-06-2026 08:02-In this connection a case vide No.1195/2026. Date 06-06-2026 U/S 141 RLY Act registered at RPF-Post/PKU against the arrested person. Sounak Hait, A/A-23yrs,S/O-Sushanta Hait,R/O-Mangalduari, Ratulia,PS-Panskura,Dist-Purba Medinipur.E.O. A.K.Mohapatra
App Remarks Date	02-06-2026 11:53	02-06-2026 11:54	05-06-2026 19:29	06-06-2026 08:07	06-06-2026 08:02
Reporting Date	02-06-2026 11:36	02-06-2026 10:58	04-06-2026 11:39	03-06-2026 23:05	06-06-2026 05:21

8	7	6	SNO.
SECURITY	SECURITY	SECURITY	ABN.TYPE
RUN OVER	ACP	OTHER	SUBHEAD
BLS	KGP	SRC	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
RIKL	CKP	HAUR	FROM
BWO	HUJ	BCK	TO
BLS1010	KGP1722	SRC7200	CREW/CLIID
DL SURESH K. SINGH	EL SUMIT MURMU	RAHUL DUTTA	CREW/CLINAME
LPP	LPM	SGDP	DESIG
12-06-2026	12-06-2026	09-06-2026	ABNDATE
04:18	03:37	03:51	ABN.TIME
74/08	212/12	80.5	FROMKM
75/07		91	TO KM
YS	YS	YS	STATUS
APPUSER	SUPConsole	CREW	FILLEDBY
39198	37446	37901	LOCO
WATE	WATE	NGCD	LOCO SHED
18401	15478	12510	TRAIN
13-06-26 10:46	13-06-26 10:46	11-06-26 22:57	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	N	RemStts
DETAIL:While working Train no. 18401 Ex BGY a Male Person got Knock Down and Run Over at Km.No. RB75/08-07 Between Rajaloka and Buramara section. Man was lying On the railway track.	DETAIL:ACP BY PASSENGER AT KM 212/12 (03:37-03:46), RESET BY TMR.	DETAIL:A MALE PASSENGER AGE ABOUT 40YRS FELL DOWN FROM RUNNING TRAIN KM 90/5X UTS TICKET NO 51728632.AS ADVISED BY SM/BCK INJURED PERSON HANDED OVER TO SM/KGP AFTER GIVING FIRST AID BY ME.	
CLOSE_REM:AS PER SECURITY DEPT In this regard GRPS/Balasore has been registered a UD Case vides No.51/2026 Dated: 12.06.2026 and case is under investigation of GRPS/Balasore and I.O. of the case is ASI/S. K. Gadnaik of GRPS/Baripada. In this regard, SMR/Bhanjpur provided form-01 vides no VZR/7321487/KGP/SER/ 2026/ June/01, Dated: 12.06.2026 and RPF/Post/Baripada has registered a UTI Case vide Serial No.04/2026 Dated: 12.06.2026 and enquiry in to the case allotted to ASI/Jyoti Prakash Sahoo of RPF/P	CLOSE_REM:AS PER SECURITY DEPT The offender person snatched a mobile from a passenger and to catch the offender the victim passenger pulled alarm chain..	CLOSE_REM:AS PER SECURITY DEPT On 09-06-2026 at about 05.13 Hrs received information by RPF/Post/PKU Vide M.No-196 dated.09-6-26 regarding one male person fallen down by T/No-12510. then ACP from 03.51 hrs to 04.03 hrs in Coach No-NFR-217979 GS by Unknown passenger after first aid given by TMR on the spot and allowed in Guard Compartment of 12510 Exp for further treatment at KGP Railway main hospital. Immediately ASI/R.K.Jha of RPF/BCK(OP) along with HC-D.Kumar attend the Kharagpur Railway main hospital	
APP_REM:@SECUKGP/13-06-2026 03:27-In this regard GRPS/Balasore has been registered a UD Case vides No.51/2026 Dated: 12.06.2026 and case is under investigation of GRPS/Balasore and I.O. of the case is ASI/S. K. Gadnaik of GRPS/Baripada. In this regard, SMR/Bhanjpur provided form-01 vides no VZR/7321487/KGP/SER/ 2026/ June/01, Dated: 12.06.2026 and RPF/Post/Baripada has registered a UTI Case vide Serial No.04/2026 Dated: 12.06.2026 and enquiry in to the case allotted to ASI/Jyoti Prakash Sahoo of RPF/P	APP_REM:@SECUKGP/13-06-2026 03:25-The offender person snatched a mobile from a passenger and to catch the offender the victim passenger pulled alarm chain.		
13-06-2026 03:27	13-06-2026 03:25		App Remarks Date
12-06-2026 09:33	12-06-2026 11:07	09-06-2026 08:08	Reporting Date

11	SECURITY	10	9	SNO.
OTHER	SECURITY	SECURITY	OTHER	ABN.TYPE
TATA	RUN OVER	OTHER	OTHER	SUBHEAD
KGP	KGP	KGP	KGP	REPORTSTTN
JGM	KGP	KGP	KGP	REPORTDIV
GII	PKU	FLR	FLR	FROM
SRC7133	HAUR	ULB	ULB	TO
DEBABRATA DUTTA	KGP2602	KGP2975	KGP2975	CREW/CLIID
GDM	DL ADHIR KUMAR MANDAL	SURAJIT BHATTACHARYA	SURAJIT BHATTACHARYA	CREW/CLINAME
14-06-2026	LPP	MMAN	MMAN	DESIG
09:14	13-06-2026	12-06-2026	12-06-2026	ABNDATE
164/09	16:55	12:30	12:30	ABN.TIME
164/11	76/12			FROMKM
YS	76/14			TO KM
CREW	YS	YS	YS	STATUS
39527	SUPConsole	CREW	CREW	FILLED BY
SRCE	37801			LOCO
22861	BIAE			LOCO SHED
15-06-26 11:19	18030	38815	38815	TRAIN
KGP	15-06-26 11:19	13-06-26 10:46	13-06-26 10:46	SMSTO LP
Y	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:R/OVER TN SOPPED 0914 HRS STRT 09.18 HRS ONE MALE TRANSPASSER AGE ABOUT 40 TO 45 YRS ROVER BODY LEFT IN SIDE THE TRACK AND HEAD OUT SIDE TN	DETAIL:ONE UNKNOWN MALE PERSON KNOCK DOWN BY TRAIN ENGINE AT KM NO 76/12-14 BETWEEN SECTION PKU-HAUR TRAIN IS STOP AT 76/28 AND INFORM TO TMR HE CHECKED AND FOUND THEN START TRAIN AT 16:59 HRS .AGAIN STOP AT HAUR STATION TMR MEMO GIVEN TO SMR/HAUR AT 17:07 HRS.	DETAIL:AS PER PASSENGER INFORMATION A WOMAN FALL INTO RIVER FROM THE FIRST COMPARTMENT OF TR NO 38815 JUST BEFORE THE ULB H/S FROM THE BRIDGE.INFORMATION GIVEN TO THE ULB SM...AND MEMO IS GIVEN BY TM AT MCA	DETAIL:AS PER PASSENGER INFORMATION A WOMAN FALL INTO RIVER FROM THE FIRST COMPARTMENT OF TR NO 38815 JUST BEFORE THE ULB H/S FROM THE BRIDGE.INFORMATION GIVEN TO THE ULB SM...AND MEMO IS GIVEN BY TM AT MCA	
CLOSE_REM:AS PER SECURITY DEPT In this regard GRPS/JGM registered an UD case vide No 09/2026 dated 14.06.2026 against the above said deceased person. Further SI M.M.Singh made co-operation with on duty SMR/GII and obtained extract copy of SMR GII vide DE No 319 dated 14.06.2026,and SMR JGM issued UIN No-GII/07319239/KGP/SER/2026/06/03 Dtd:- 14.06.2026 Dtd:- 14.06.2026.At present the case is under investigation of SI Samual Nayak of GRPs/Jhargram & PC/RPF/JGM registered a UTI Case no-14/26 dt 14.06.202	CLOSE_REM:AS PER SECURITY DEPT GRPS/PKU registered an UD case no vide no. 27/26 dtd 13.06.2026. During investigation no journey ticket or travelling authority found from body or nearby area. In this connection SMR/PKU made D. E. vide No. 120 and issue form-I vide UIN No. HAU/0732/402/KGP/2026/June/02, Date: - 13-6-2026 and On the basis of Form-I, an UTI Case vide No. 46(6)2026, Date: - 13-6-2026 was registered at RPF Post, Panskura.	CLOSE_REM:AS PER SECURITY DEPT The injured woman was brought to BZN station by the ALP. ASI S.K. Das along with RPF and station staff attended her, provided first aid, and sent her to SCC Medical College Hospital, Uluberia for treatment. She was admitted in Female Surgical Ward under treatment. No railway ticket was found and her identity could not be established. Due to the incident, Train No. 12883 was detained for 19 minutes and Train No. 38807 for 10 minutes. Form-I was issued by SMR/BZN.	CLOSE_REM:AS PER SECURITY DEPT The injured woman was brought to BZN station by the ALP. ASI S.K. Das along with RPF and station staff attended her, provided first aid, and sent her to SCC Medical College Hospital, Uluberia for treatment. She was admitted in Female Surgical Ward under treatment. No railway ticket was found and her identity could not be established. Due to the incident, Train No. 12883 was detained for 19 minutes and Train No. 38807 for 10 minutes. Form-I was issued by SMR/BZN.	
APP_REM:@SECUKGP/15-06-2026 03:17-In this regard GRPS/JGM registered an UD case vide No 09/2026 dated 14.06.2026 against the above said deceased person. Further SI M.M.Singh made co-operation with on duty SMR/GII and obtained extract copy of SMR GII vide DE No 319 dated 14.06.2026,and SMR JGM issued UIN No-GII/07319239/KGP/SER/2026/06/03 Dtd:- 14.06.2026 Dtd:- 14.06.2026.At present the case is under investigation of SI Samual Nayak of GRPs/Jhargram & PC/RPF/JGM registered a UTI Case no-14/26 dt 14.06.202	APP_REM:@SECUKGP/15-06-2026 03:15-GRPS/PKU registered an UD case no vide no. 27/26 dtd 13.06.2026. During investigation no journey ticket or travelling authority found from body or nearby area. In this connection SMR/PKU made D. E. vide No. 120 and issue form-I vide UIN No. HAU/0732/402/KGP/2026/June/02, Date: - 13-6-2026 and On the basis of Form-I, an UTI Case vide No. 46(6)2026, Date: - 13-6-2026 was registered at RPF Post, Panskura.	APP_REM:@SECUKGP/13-06-2026 03:29- The injured woman was brought to BZN station by the ALP. ASI S.K. Das along with RPF and station staff attended her, provided first aid, and sent her to SCC Medical College Hospital, Uluberia for treatment. She was admitted in Female Surgical Ward under treatment. No railway ticket was found and her identity could not be established. Due to the incident, Train No. 12883 was detained for 19 minutes and Train No. 38807 for 10 minutes. Form-I was issued by SMR/BZN. E.O.: A	APP_REM:@SECUKGP/13-06-2026 03:29- The injured woman was brought to BZN station by the ALP. ASI S.K. Das along with RPF and station staff attended her, provided first aid, and sent her to SCC Medical College Hospital, Uluberia for treatment. She was admitted in Female Surgical Ward under treatment. No railway ticket was found and her identity could not be established. Due to the incident, Train No. 12883 was detained for 19 minutes and Train No. 38807 for 10 minutes. Form-I was issued by SMR/BZN. E.O.: A	
15-06-2026 03:17	15-06-2026 03:15	13-06-2026 03:29	13-06-2026 03:29	App Remarks Date
14-06-2026 11:15	14-06-2026 18:14	12-06-2026 14:41	12-06-2026 14:41	Reporting Date

15	SECURITY	14	13	12	SNO.
ACP	SECURITY	SECURITY	SECURITY	SECURITY	ABN.TYPE
SRC	ACP	ACP	DGHA	OTHER	SUBHEAD
KGP	DGHA	KGP	KGP	SRC	REPORTSTTN
RMRB	KGP	DSPN	DSPN	KGP	REPORTDIV
KATI	DSPN	KATI	KATI	JGM	FROM
SRC1760	KATI	SRC1760	SRC1760	GII	TO
EL CROMTON GHOSH C	SRC1760	EL CROMTON GHOSH C	EL CROMTON GHOSH C	SRC7133	CREW/CLIID
LPP	LPP	LPP	LPP	GDM	CREW/CLINAME
17-06-2026	17-06-2026	17-06-2026	17-06-2026	14-06-2026	DESIG
20:06	09:02	09:02	09:02	09:14	ABDATE
59/14	19/10	19/10	19/10	164/09	ABN.TIME
59/13	19/11	19/11	19/11	164/11	FROMKM
YS	YS	YS	YS	YS	TO KM
CREW	CREW	CREW	CREW	APPUSER	STATUS
22501	22502	22502	22502	39527	FILLED BY
SRCE	SRCE	SRCE	SRCE	SRCE	LOCO
22898	12857	12857	12857	22861 UP	LOCO SHED
19-06-26 23:00	19-06-26 22:58	19-06-26 22:58	19-06-26 22:58	16-06-26 22:03	TRAIN
KGP	KGP	KGP	KGP	KGP	SMSTO LP
N	N	N	N	Y	Div
DETAIL:ACP IN COACH D1,RESET BY TMR . INFORM TO TLC/KGP MR D K BEHERA .	DETAIL:ACP IN COACH NO SE 255409. RESET BY TMR	DETAIL:ACP I	DETAIL:One Male Trespasser Age About 40 To 45 Yrs R/Over Between Km164/09 - 164/11 (JGM-GII). Body Lying Inside The Track And Lying Outside The Track. Tn Stopped At 09.14 Hrs And Strt 09.18 Hrs. Wearing Black S/ Pant . Informed CNL/KGP and LP Surved Memo To SMR GII.		RemStts
CLOSE_REM:AS PER SECURITY DEPT SI R.P.Yadav of RPF /Post /Digha conducted enquiry and it could be learnt from the on duty TTE of the said train that one Bonafide female passenger having Ticket No-F-77841314, Sit No-29 Coach No -D-1 , as namely Lipika Baidya aged about 42 years, W/O-Subhash Baidya R/O-Rania Nabaranpur, P.S-Sonarpur, Dist- South 24 Parganas, West Bengal, suddenly feeling unwell in the meantime co-passenger of the said train made ACP for wash her head with the water in the toilet. After was	CLOSE_REM:AS PER SECURITY DEPT 10.40 hrs dt 17/06/26 U/S 179(ii) RA for committing an offence punishable U/S 141 RA. In this regard as per order of PC /RPF/TMZ a case vide no 1185/26 dt 02.04.26 U/S 141 Rly act has been registered against arrested person at RPF Post Tamluk. EO- Ravindra Kumar, ASI/RPF/Tamluk	CLOSE_REM:AS PER SECURITY DEPT 10.40 hrs dt 17/06/26 U/S 179(ii) RA for committing an offence punishable U/S 141 RA. In this regard as per order of PC /RPF/TMZ a case vide no 1185/26 dt 02.04.26 U/S 141 Rly act has been registered against arrested person at RPF Post Tamluk. EO- Ravindra Kumar, ASI/RPF/Tamluk	CLOSE_REM:AS PER SECURITY DEPT In this regard GRPS/JGM registered an UD case vide No 09/2026 dated 14.06.2026 against the above said deceased person. Further SI M.M.Singh made co-operation with on duty SMR/GII and obtained extract copy of SMR GII vide DE No 319 dated 14.06.2026,and SMR JGM issued UIN No-GII/07319239/KGP/SER/2026/06/03 Dtd:- 14.06.2026 Dtd:-14.06.2026.At present the case is under investigation of SI Samual Nayak of GRPs/Jhargram & PC/RPF/JGM registered a UTI Case no-14/26 dt 14.06.202	CLOSE_REM:@SECUKGP/16-06-2026 17:51-In this regard GRPS/JGM registered an UD case vide No 09/2026 dated 14.06.2026 against the above said deceased person. Further SI M.M.Singh made co-operation with on duty SMR/GII and obtained extract copy of SMR GII vide DE No 319 dated 14.06.2026,and SMR JGM issued UIN No-GII/07319239/KGP/SER/2026/06/03 Dtd:- 14.06.2026 Dtd:-14.06.2026.At present the case is under investigation of SI Samual Nayak of GRPs/Jhargram & PC/RPF/JGM registered a UTI Case no-14/26 dt 14.06.202	
					App Remarks
				16-06-2026 17:51	App Remarks Date
18-06-2026 01:20	17-06-2026 10:27	17-06-2026 10:24		14-06-2026 11:57	Reporting Date

SNO.	16	17	18	19
ABN.TYPE	SECURITY	SECURITY	SECURITY	SECURITY
SUBHEAD	RUN OVER	RUN OVER	ACP	ACP
REPORTSTTN	BLS	BBS	KGP	SRC
REPORTDIV	KGP	KGP	KGP	KGP
FROM	VZR	KGP	HWH	BOP
TO	KUCE	BBS	KGP	MCA
CREW/CLIID	BLS1010	KGP1432	KGP7132	KGP2752
CREW/CLINAME	DL SURESH K. SINGH	DL PRABIR KR.MONDAL	KHETRA BEHERA	EL SAGRAM HANSDAH DUAL
DESIG	LPP	LPM	GDM	LPG
ABNDATE	18-06-2026	18-06-2026	21-06-2026	23-06-2026
ABN.TIME	00:57	17:23	09:18	23:57
FROMKM	62/02	215/15	HWH20	58/30
TO KM	62/03	215/17	HWH-22	58/20
STATUS	YS	YS	YS	YS
FILLED BY	APPUSER	SUPConsole	CREW	CREW
LOCO	37446	37591	39100	22349
LOCO SHED	WATE	SRCE	SRCE	SRCE
TRAIN	18402	12073	12704	22856
SMSTO LP	20-06-26 22:28	21-06-26 10:39	23-06-26 12:58	24-06-26 21:01
Div	KGP	KGP	KGP	KGP
RemStts	N	Y	Y	Y
Detail	DETAIL:A Female Aged About 60yrs. Knocked Down And Dead With Head Injury. Dead Body Lying Inside The Track.	DETAIL:ONE UNKNOWN MAN AGE APPROXIMATELY 40yrs. KNOCKED DOWN AND INJURED,RESCUE AT BLS AND HAND OVER TO SS/BLS ON DUTY.		DETAIL:ACP AT MCA YD RESET BY TMR
Closing Remarks	CLOSE_REM:AS PER SECURITY DEPT In this regard, SMR/Bangriposi provided form-01 vide no- BGY/7321492/KGP/SER/2026/June/01 Dated:- 18.06.2026 and RPF/Post/Baripada has registered a UTI Case vide Serial No.06/2026 Dated: 18.06.2026 and enquiry in to the case allotted to ASI/Bijoy Kumar Ram of RPE/Post/Barinada	CLOSE_REM:AS PER SECURITY DEPT In this regard on duty SM/Haldipada made a diary vide no-758 dated -18.06.26 and no form 01 was issued by the above SM. Hence no UTI case has been register at RPF/Post/ROP. Further obtaining will be intimate shortly.	CLOSE_REM:AS PER SECURITY DEPT During enquiry, the officials of RPF Post/South Howrah informed that no ACP incident had occurred in Train No. 12704 at Platform No. 22, Howrah Railway Station. They further stated that no case in this regard had been registered at RPF Post/South Howrah.	CLOSE_REM:AS PER SECURITY DEPT In this regard a case vide no.1693/2026 dated 24.06.2026 U/S 141 of Railway act has been registered at RPF/Post/MCA against unknown.
App Remarks		APP_REM:@SECURITY/20-06-2026 01:36- Matter Pertains to KGP Division @SECUKGP/21-06-2026 03:40-On 18.06.2026, as per information received from SM/Haldipada vide D/E No. 758 dated 18.06.2026, the Train Manager of Train No. 12073 reported that at about 17:09 hrs the train struck an unidentified male person (aged about 42 years) while trespassing at Km No. 215/15-17 between Rupsa and Haldipada. The injured person was carried in Coach No. D-10 and the train departed at 17:17 hrs. On arrival at Balasore statio	APP_REM:@SECUKGP/23-06-2026 03:05- During enquiry, the officials of RPF Post/South Howrah informed that no ACP incident had occurred in Train No. 12704 at Platform No. 22, Howrah Railway Station. They further stated that no case in this regard had been registered at RPF Post/South Howrah.	APP_REM:@SECUKGP/24-06-2026 13:26-In this regard a case vide no.1693/2026 dated 24.06.2026 U/S 141 of Railway act has been registered at RPF/Post/MCA against unknown.
App Remarks Date		21-06-2026 03:40	23-06-2026 03:05	24-06-2026 13:26
Reporting Date	18-06-2026 12:22	18-06-2026 21:43	21-06-2026 11:32	24-06-2026 03:27

ST

3	2	1	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL NO PLATE	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
KUR	KGP	KGP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
KUR	ULB	ROP	FROM
KGP	ULB	BTS	TO
KUR1729	KGP0025	KGP1388	CREW/CLIID
V SRINIVASA RAO I D	EL H. MURMU	EL KAMAL KANTI NATH	CREW/CLINAME
LPP	Chief Loco Inspector	LPM	DESIG
04-06-2026	01-06-2026	01-06-2026	ABNDATE
09:11	20:28	14:19	ABN.TIME
455		207/14	FROMKM
116		207/12	TO KM
YS	YS	YS	STATUS
APPUSER	APPUSER	CREW	FILLEDBY
39594	30743	37263	LOCO
SGUD	SRCE	TATE	LOCO SHED
15607	22841	22852	TRAIN
06-06-26 21:20	04-06-26 14:10	02-06-26 21:54	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:There is no IB Marker plate provided on IB signal at km.no.260/8-10 between SFO and BNBR.A White Circular Board With Black Letters IB to be provided on the iIBH Sigal post.	DETAIL:ULB UP MAIN STARTER SIGNAL GREEN TO DANGER FOR FEW SECONDS THAN GREEN	DETAIL:ROP IB SIGNAL ON APPROACH GREEN TO RED.TRAIN STOPPED IN REAR OF IB SIGNAL BY APPLYING EMERGENCY	
CLOSE_REM:AS PER S&T DEPT As per JE/SIG/SFO- IB Marker provided on 6/6/26 at 10:15 hrs. At km 260/8--10.	CLOSE_REM:as per S&T dept As per through monitoring of data logger report observed that when signal aspect change from double yellow to green of signal no S-1 at BSBP this failure was happened. Resistance and capacitor replaced of both aspect (yellow and double yellow) replaced of signal no S-1 at BSBP and rectified.	CLOSE_REM:AS PER S&T DEPPT As per DL report it has been noticed that DD ACPR drop 14:17 to14:23. For that reason DN IB signal go back to danger and relowered at 14:23hrs when DDACPR clear. Circuit kept under observation. Suspected reason for Dropping of DD ACPR is the working of CNST staff for commissioning of New SSDAC installation.	Closing Remarks
APP_REM:@CNLTRKGP/06-06-2026 14:51-As per JE/SIG/SFO- IB Marker provided on 6/6/26 at 10:15 hrs. At km 260/8--10.	APP_REM:@CNLTRKGP/04-06-2026 12:38-As per through monitoring of data logger report observed that when signal aspect change from double yellow to green of signal no S-1 at BSBP this failure was happened. Resistance and capacitor replaced of both aspect (yellow and double yellow) replaced of signal no S-1 at BSBP and rectified.	APP_REM:@CNLTRKGP/02-06-2026 16:46-As per DL report it has been noticed that DD ACPR drop 14:17 to14:23. For that reason DN IB signal go back to danger and relowered at 14:23hrs when DDACPR clear. Circuit kept under observation. Suspected reason for Dropping of DD ACPR is the working of CNST staff for commissioning of New SSDAC installation.	App Remarks
06-06-2026 14:51	04-06-2026 12:38	02-06-2026 16:46	App Remarks Date
04-06-2026 20:22	01-06-2026 20:31	01-06-2026 16:43	Reporting Date

6	5	4	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL BULB	SUBHEAD
KGP	KGP	KUR	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
ROP	ROP	KGP	FROM
BTS	BTS	KUR	TO
KGP1075	KGP3358	KGP1075	CREW/CLIID
DL SURESH PRASAD PANDEY	EL SUVENDU SUR	DL SURESH PRASAD PANDEY	CREW/CLINAME
LPP	LPP	LPP	DESIG
06-06-2026	06-06-2026	05-06-2026	ABNDATE
10:52	07:06	02:47	ABN.TIME
209/10	209/16		FROMKM
209/08	209/14		TO KM
YS	YS	YS	STATUS
CREW	CREW	SUPConsole	FILLEDBY
	25031	22815	LOCO
	SRCE	SPJD	LOCO SHED
22832	18044	18047	TRAIN
08-06-26 18:52	08-06-26 18:52	05-06-26 22:49	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:ROP IB DISTANT SIGNAL SHOWING ONE YELLOW	DETAIL:ROP IB DISTANT FOUND ONE YELLOW	DETAIL:BLS G/S FOUND NO LIGHT IN BLS/STN.	Detail
CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:as per S&T dept 630mA fuse for S-1 HG blown off. Same replaced, again blown off. Later S-1 HG Cable tested from Relay Room to Gate Home Location via L-5 and found Cable from L-5 to UP Gate Home Location, i.e 4 Core Cable carrying S-1 HG Suspect low insulation. Same Shifted to Spare Core and failure rectified.	Closing Remarks
APP_REM:@CNLTRKGP/08-06- 2026 18:45-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@CNLTRKGP/08-06- 2026 18:44-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@fault/05-06-2026 12:28- Not pertain to KUR Divn.Please forward to KGP Divn.@CNLTRKGP/05-06-2026 18:55-630mA fuse for S-1 HG blown off. Same replaced, again blown off. Later S-1 HG Cable tested from Relay Room to Gate Home Location via L-5 and found Cable from L-5 to UP Gate Home Location, i.e 4 Core Cable carrying S-1 HG Suspect low insulation. Same Shifted to Spare Core and failure rectified	App Remarks
08-06-2026 18:45	08-06-2026 18:44	05-06-2026 18:55	App Remarks Date
06-06-2026 13:06	06-06-2026 11:40	05-06-2026 09:42	Reporting Date

9	8	7	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
HWHS	KGP	ADL	REPORTSTIN
KGP	KGP	KGP	REPORTDIV
DSNR	ROP	RGA	FROM
TPKR	BTS	TMZ	TO
TPKR1417	BLS1086	KGP0066	CREW/CLIID
EL RATHINDRANATH BISWAS	EL NITESH KHAITAN	SAMBHUNATH MAITY	CREW/CLNAME
LPG	LPG	Chief Loco Inspector	DESIG
08-06-2026	07-06-2026	06-06-2026	ABNDATE
10:12	05:55	12:10	ABN.TIME
3/28X	209/16		FROMKM
3/26	209/14		TO KM
YS	YS	YS	STATUS
CREW	CREW	APPUSER	FILLED BY
108675	38274	238789	LOCO
	RPDX		LOCO SHED
38103	E/N/B/E	38053	TRAIN
11-06-26 08:36	08-06-26 18:52	07-06-26 21:16	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:DN MAIN TPKR HOME SIGNAL SHOW RED AND ONE YELLOW AT A TIME FOR FEW TIME, THEN SHOW ONE YELLOW ONLY	DETAIL:DOUBLE DISTANT SECTION WITH ROP IB DIS ASPECT ONE YELLOW MESSAGE CONVEYED TO ROP BUT NO RESPONSE	DETAIL:GS-1 SUDDEN SUDDEN PUT BACK TO RED FROM YELLOW AND STEADY. RAISED TO YELLOW AGAIN.THEN PUT BACK TO RED AND STEADY	Detail
CLOSE_REM:as per S&T dept As per the Datalogger report, relay 2HR picked up at 10:11:54.921 hrs, followed by the pick-up of relay 2HECR at 10:11:55.546 hrs. Subsequently, relay 2RECR dropped at 10:12:13.031 hrs. Thus, relays 2HECR and 2RECR remained in the picked-up condition simultaneously for approximately 18 seconds. Latter, circuit and operation of signal S2 checked several times but the above situation was not reoccurred. As a precautionary measure, both the Red and Bottom Yellow LED units	CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:AS PER S&T DEPT AS PER SSE/TMZ/INCH , UP LINE T/C 108BT FAILED FROM 12:11 TO 12:12HRS. LATER CHECKED THOROUGHLY FOUND NO FAULT. CCT KEPT UNDER OBSERVATION. AS PER D/L- 108BTTPR FAILED FROM 12:10:08:812 TO 12:12:20:109HRS.	Closing Remarks
APP_REM:@CNLTRKGP/11-06-2026 00:23-As per the Datalogger report, relay 2HR picked up at 10:11:54.921 hrs, followed by the pick-up of relay 2HECR at 10:11:55.546 hrs. Subsequently, relay 2RECR dropped at 10:12:13.031 hrs. Thus, relays 2HECR and 2RECR remained in the picked-up condition simultaneously for approximately 18 seconds. Latter, circuit and operation of signal S2 checked several times but the above situation was not reoccurred. As a precautionary measure, both the Red and Bottom Yellow LED units	APP_REM:@CNLTRKGP/08-06-2026 18:45-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@CNLTRKGP/06-06-2026 18:42-Due to T/C-108 failure, rectified at 12:12hrs@kgpuor/06-06-2026 21:21/PLEASE PROVIDE DATA LOGGER REPORTS TIME SLOT.@CNLTRKGP/07-06-2026 15:08-AS PER SSE/TMZ/INCH , UP LINE T/C 108BT FAILED FROM 12:11 TO 12:12HRS. LATER CHECKED THOROUGHLY FOUND NO FAULT. CCT KEPT UNDER OBSERVATION. AS PER D/L- 108BTTPR FAILED FROM 12:10:08:812 TO 12:12:20:109HRS.	App Remarks
11-06-2026 00:23	08-06-2026 18:45	07-06-2026 15:08	App Remarks Date
08-06-2026 11:27	07-06-2026 11:47	06-06-2026 13:36	Reporting Date

13	12	11	10	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL VISIBILITY	SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL NO PLATE	SUBHEAD
KGP	BHC	BHC	NMP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
SDAH	BLS	BTS	RNTL	FROM
KGP	NGRD	ROP	BHC	TO
KGP0082	NMP2433	NMP2387	NMP1456	CREW/CLIID
BRIHASPATI DAS	EL INDRAJEET KR VERMA G12	EL K SRINIVAS RAO G12	EL PURNENDU PAL G12	CREW/CLINAME
Chief Loco Inspector	SALP	LPG	LPG	DESIG
08-06-2026	08-06-2026	08-06-2026	08-06-2026	ABNDATE
20:50	17:41	16:27	15:25	ABN.TIME
	238/21	210/29	287/7A	FROMKM
	238/23	210/31	287/9A	TO KM
YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	APPUSER	FILLED BY
30529	33189	331891	31378	LOCO
SDAD	BIAE		PTRX	LOCO SHED
22201	ME//N/CBSP	ME//N/CBSP	BRN E JSPK	TRAIN
10-06-26 22:30	11-06-26 15:53	11-06-26 11:35	09-06-26 23:45	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:Visibility of MRGM starter signal is obstructed by tree branches	DETAIL:TRAIN STOP DUE TO LC84 GATE SIGNAL DANGER.PASS AT ON AS PER RULE.	DETAIL:TRAIN STOP DUE LC 66 GATE SIGNAL DANGER.PASS AT ON AS PER RULE.	DETAIL:Ranital Gate Signal 3rd Line Up Km287/7A G Marker Not Found	Detail
CLOSE_REM:AS PER S&T DEPT AS WELL AS eNGG DEPT SSE/PWAY/SRC/CENTRAL STAFF TRIMMING WORK STARTED , COMPLETED WILL 11/06/26.	CLOSE_REM:AS PER S&T DEPT This is not Signal abnormality. There was no complaint given from BLS or NGRD Station. Also no TRAIN passed LC-84 at given time (at 17:41 HRS) . As per Datalogger report it was revealed that LC-84 closed (84KNLR UP at 17:48:45:750 HRS) , later than Train hit Signal replacement MSDAC TRACK SECTION dropped (GS-5XTPR dropped at 17:48:39:937 HRS).	CLOSE_REM:AS PER S&T DEPT No any signal failure on that day for LC gate no 66.. On duty SM didnt gave any signal for that train as it may block traffic on gate no 66 but LP considered it as signal failure and he moved forward till UP home signal.	CLOSE_REM:AS PER S&T DEPT As per JE SIG SFO G marker provided at 16:00 hrs on 9.6.26	Closing Remarks
APP_REM:@CNLTRKGP/10-06-2026 17:42- SSE/PWAY/SRC/CENTRAL STAFF TRIMMING WORK STARTED , COMPLETED WILL 11/06/26.	APP_REM:@CNLTRKGP/11-06-2026 12:13-This is not Signal abnormality. There was no complaint given from BLS or NGRD Station. Also no TRAIN passed LC-84 at given time (at 17:41 HRS) . As per Datalogger report it was revealed that LC-84 closed (84KNLR UP at 17:48:45:750 HRS) , later than Train hit Signal replacement MSDAC TRACK SECTION dropped (GS-5XTPR dropped at 17:48:39:937 HRS).	APP_REM:@CNLTRKGP/11-06-2026 00:26-No any signal failure on that day for LC gate no 66.. On duty SM didn't gave any signal for that train as it may block traffic on gate no 66 but LP considered it as signal failure and he moved forward till UP home signal...	APP_REM:@fault/08-06-2026 16:56- Not pertains to KUR-division please forwarded to KGP-div.@fault/08-06-2026 16:56-Not pertains to KUR-division please forwarded to KGP-div.@CNLTRKGP/09-06-2026 22:43- As per JE SIG SFO 'G' marker provided at 16:00 hrs on 9.6.26	App Remarks
10-06-2026 17:42	11-06-2026 12:13	11-06-2026 00:26	09-06-2026 22:43	App Remarks Date
09-06-2026 00:09	08-06-2026 22:07	08-06-2026 22:01	08-06-2026 15:59	Reporting Date

18	ST	17	16	15	14	SNO.
SIGNAL ASPECT	ST	SIGNAL ASPECT	SIGNAL VISIBILITY	SIGNAL ASPECT	ST	ABN.TYPE
KGP	KGP	KGP	KGP	KGP	OTHER	SUBHEAD
KGP	KGP	KGP	KGP	KGP	SRC	REPORTSTTN
ULB	BCK	DTE	BZN	BHC	BZN	REPORTDIV
ULB	SMCK	BZN	BZN	KGP	BSBP	FROM
KGP1388	KGP1388	KGP2086	NMP1587	SRC1760		TO
EL KAMAL KANTI NATH	EL KAMAL KANTI NATH	EL SADHAN DAS	EL SHIV SHANKAR KUMAR	EL CROMTON GHOSH C		CREW/CLIID
LPM	LPM	LPG	LPG	LPP		CREW/CLNAME
16-06-2026	15-06-2026	12-06-2026	11-06-2026	09-06-2026		DESIG
01:37	02:12	10:55	06:07	15:26		ABNDATE
32/13X	94/6	46/10	215/10	41/22		ABN.TIME
32/15X	94/8	46/08	215/8	41/20		FROMKM
YS	YS	YS	YS	YS		TO KM
CREW	CREW	APPUSER	CREW	CREW		STATUS
22743	22865	39556	33561	39481		FILLED BY
SRCE	SRCE	NGCD	TKDE	HWHE		LOCO
12278	12278	22808	DNE	18010		LOCO SHED
18-06-26 21:08	15-06-26 15:31	13-06-26 21:03	12-06-26 23:31	09-06-26 23:46		TRAIN
KGP	KGP	KGP	KGP	KGP		SMSTO LP
Y	Y	Y	Y	Y		Div
						RemStts
DETAIL:ULB UP MAIN STARTER SIGNAL ON APPROACH TURNS GREEN TO RED.	DETAIL:AS143 PASSED AT ON AS PER RULE	DETAIL:DN. BZN H/Sig. Not View Properly from LP side due to trees branches	DETAIL:ROP GS 69 NO LIGHT	DETAIL:AS 46 PASS AT ON AS PER RULE.INFORM TO SMR / BSBP THROUGH VHF.		
CLOSE_REM:AS PER S&T DEPT ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	CLOSE_REM:AS PER S&T DEPT Due to Train ahead	CLOSE_REM:AS PER S&T DEPT Obstruction cleared, after tree trimming at km 46/8-10 by staff of SSE/TRD/MCA/INC.	CLOSE_REM:AS PER S&T DEPT ACTION TAKEN - @CNLTRKGP/12-06-2026 17:04- FAILED DUE TO 3*12CORE CABLE CUT BY OUTSIDERS BETWEEN KM 215/6-8. RECTIFIED AT 06:30 HRS ON 11.06.26 AFTER CABLE JOINTING WORK.	CLOSE_REM:AS PER S&T DEPT As per JE BZN C3 to C4 contact of 46AT2PR offering high resistance. Same relay was replaced & rectified .		
APP_REM:@CNLTRKGP/18-06-2026 13:32-ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	APP_REM:@CNLTRKGP/15-06-2026 13:29-Due to Train ahead	APP_REM:@CNLTRKGP/13-06-2026 17:40-Obstruction cleared, after tree trimming at km 46/8-10 by staff of SSE/TRD/MCA/INC,	APP_REM:@CNLTRKGP/12-06-2026 17:04-FAILED DUE TO 3*12CORE CABLE CUT BY OUTSIDERS BETWEEN KM 215/6-8. RECTIFIED AT 06:30 HRS ON 11.06.26 AFTER CABLE JOINTING WORK.	APP_REM:@CNLTRKGP/09-06-2026 22:47-As per JE BZN C3 to C4 contact of 46AT2PR offering high resistance. Same relay was replaced & rectified		
18-06-2026 13:32	15-06-2026 13:29	13-06-2026 17:40	12-06-2026 17:04	09-06-2026 22:47		App Remarks Date
16-06-2026 03:30	15-06-2026 03:04	12-06-2026 20:13	11-06-2026 09:37	09-06-2026 17:26		Reporting Date

22	21	20	19	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL BULB	SIGNAL BULB	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
SRC	NMP	SRC	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
KGP	KKQ	SRC	HWH	FROM
BLS	NMP	PDPK	KGP	TO
KGP0028	TATA3119	SRC1501	KGP3819	CREW/CLIID
EL S.C.SUBUDHI	NISHANT PATEL	EL SWAPAN BANERJEE C	EL SUMIT KUMAR II C	CREW/CLINAME
Chief Loco Inspector	LPG	LPP	SALP	DESIG
19-06-2026	19-06-2026	16-06-2026	16-06-2026	ABNDATE
14:34	09:07	15:41	01:37	ABN.TIME
115/11	122/30	PDPK	32/11X	FROMKM
230/23	122/28	7/11	32/11X	TO KM
YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	CREW	FILLED BY
28623	32142	30706	22743	LOCO
RTMD	LDHE	WATE	SRCE	LOCO SHED
N-CONT(E)/PCP	N/APIG	18046	12278	TRAIN
20-06-26 19:14	20-06-26 19:14	18-06-26 21:08	18-06-26 21:08	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:MIDDLE BULB OF TOP LUNAR FOR UP COMMON LOOP LINE AT JER UP MAIN LINE HOME SIGNAL IS NOT GLOWING	DETAIL:NTY FIRST LONNER ONLY FOUR LED GLOWING.	DETAIL:SRC S/S S-114 PUT BACK WITHOUT ANY INTIMATION,AND NOT RESPOND OVER VHF,SIGNAL OFF-15/38,SIGNAL PUT BACK-15/41	DETAIL:WHILE WORKING TRAIN NO-12277 HWH TO KGP AFTER PASSING ULB UP H/S GREEN WE FOUND ULB UP S/S DANGER ASPECT.	
CLOSE_REM:AS PER S&T DEPT AS PER SSE JER 3RD no. ROUTE LED WAS REPLACED ON 20.6.26 AT 10:30 HRS	CLOSE_REM:AS PER S&T DEPT AS PER SSE NMP LED WAS REPLACED ON 20.6.26 AT 6:00 HRS	CLOSE_REM:AS PER S&T DEPT From the Datalogger report, it is observed that the Joint Line-2 slot (SL4YPR) from PDPK failed at 15:40:40.250 hrs. Consequently, 126HR dropped at 15:40:42.031 hrs and 126HECR dropped at 15:40:42.171 hrs. As a result, 114HR dropped at 15:40:46.171 hrs and Signal S114 gone back to the ON position. The SL4YPR circuit was thoroughly checked; however, no abnormality or definite cause for the dropping of SL4YPR could be detected. The circuit has been kept under observa	CLOSE_REM:AS PER S&T DEPT ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	
APP_REM:@CNLTRKGP/20-06-2026 12:02-AS PER SSE JER 3RD NO ROUTE LED WAS REPLACED ON 20.6.26 AT 10:30 HRS	APP_REM:@CNLTRKGP/20-06-2026 10:16-AS PER SSE NMP LED WAS REPLACED ON 20.6.26 AT 6:00 HRS	APP_REM:@CNLTRKGP/18-06-2026 13:31-From the Datalogger report, it is observed that the Joint Line-2 slot (SL4YPR) from PDPK failed at 15:40:40.250 hrs. Consequently, 126HR dropped at 15:40:42.031 hrs and 126HECR dropped at 15:40:42.171 hrs. As a result, 114HR dropped at 15:40:46.171 hrs and Signal S114 gone back to the 'ON' position. The SL4YPR circuit was thoroughly checked; however, no abnormality or definite cause for the dropping of SL4YPR could be detected. The circuit has been kept under observa	APP_REM:@CNLTRKGP/18-06-2026 13:32-ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	
20-06-2026 12:02	20-06-2026 10:16	18-06-2026 13:31	18-06-2026 13:32	App Remarks Date
19-06-2026 22:28	19-06-2026 09:52	16-06-2026 18:22	16-06-2026 03:31	Reporting Date

26	25	24	23	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	OTHER	SIGNAL VISIBILITY	SIGNAL VISIBILITY	SUBHEAD
SRC	SRC	TATA	KGP	REPORTSTIN
KGP	KGP	KGP	KGP	REPORTDIV
ROP	KGP	TATA	TATA	FROM
BTS	GTS	NMP	KGP	TO
SRC1829	KGP0028	CKP0086	KGP4429	CREW/CLIID
DL PRASENJIT BASAK C	EL S.C.SUBUDHI	SARAT KUMAR SAHOO	EL RAHUL KUMAR SINGH G12	CREW/CLINAME
LPP	Chief Loco Inspector	Chief Loco Inspector	SALP	DESIG
20-06-2026	20-06-2026	20-06-2026	20-06-2026	ABNDATE
13:22	11:53	11:44	08:00	ABN.TIME
207/10	115/13	248		FROMKM
207/08	211/21	122		TO KM
YS	YS	YS	YS	STATUS
CREW	APPUSER	APPUSER	CREW	FILLED BY
37010	60090	60383	60383	LOCO
SRCE	SREE	NGPE	NGPE	LOCO SHED
12246	HL/BCNE	BCN/KKH	BCN/NKKH/NMP	TRAIN
21-06-26 10:47	21-06-26 10:47	20-06-26 19:14	21-06-26 10:47	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:ROP IB SIGNAL PASS AT DANGER AS PER RULE AFTER GETTING PRIVET NO AND ID NO FROM TALK BACK TELEPHONE IN IB SIGNAL POST	DETAIL:SIGNAL HEAD OF SIGNAL NO-GSA KT367 AT KM NO-172/10A-172/12A ON UP JOINT LINE BETWEEN GII-CKU SLIGHTLY TURNED TOWARDS RIGHT HAND SIDE CAUSES LESS INTENSITY & VISIBILITY OF SIGNAL ASPECT (TIME - 11.53 HRS)	DETAIL:Signal Visibility Of Gate Signal No GS-18 between GUD-GTS Jointline is Very Poor	DETAIL:GATE SIGNAL G/S 18 OF GATE NO.122 BETWEEN GUD-GTS JOINT LINE RED ASPECT IS NOT VISIBLE PROPERLY AS IT IS VERY DIM	
CLOSE_REM:AS PER S&T DEPT As per SSE JER INCHARGE,Both SSDAC system failed at a time, after passage of 1 Goods train. Both system hanged at IB(NMBR), then attended at IB and both system power made off and on, reset done and and reset accepted. after passage of 12246 train section cleared 14:20 hrs.	CLOSE_REM:AS PER S&T DEPT AS PER SSE GII, TECH GII ATTENDED ON 20.6.26 AT 16:00 HRS, SIGNAL UNIT ADJUSTED. NOW VISIBILITY IS ABOVE 250 MTR	CLOSE_REM:AS PER S&T DEPT Same adjusted and visibility improved on 20-06-2026.	CLOSE_REM:AS PER S&T DEPT AS PER SSE GTS LINE SIGNAL UNIT ADJUSTED ON 20.6.26 AT 17:00 HRS. NOW VISIBILITY IS 600 MTR	Closing Remarks
APP_REM:@CNLTRKGP/21-06-2026 07:42-As per SSE JER INCHARGE,Both SSDAC system failed at a time, after passage of 1 Goods train. Both system hanged at IB(NMBR), then attended at IB and both system power made off and on, reset done and and reset accepted. after passage of 12246 train section cleared 14:20 hrs.	APP_REM:@CNLTRKGP/21-06-2026 07:16-AS PER SSE GII, TECH GII ATTENDED ON 20.6.26 AT 16:00 HRS, SIGNAL UNIT ADJUSTED. NOW VISIBILITY IS ABOVE 250 MTR	APP_REM:@CNLTRKGP/20-06-2026 17:23-Same adjusted and visibility improved.	APP_REM:@CNLTRKGP/21-06-2026 07:17-AS PER SSE GTS LINE SIGNAL UNIT ADJUSTED ON 20.6.26 AT 17:00 HRS. NOW VISIBILITY IS 600 MTR	App Remarks
21-06-2026 07:42	21-06-2026 07:16	20-06-2026 17:23	21-06-2026 07:17	App Remarks Date
20-06-2026 20:01	20-06-2026 16:13	20-06-2026 11:47	20-06-2026 20:15	Reporting Date

TRAFFIC

3	2	1	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SUBHEAD
BWN	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
BWN	BWN	NTY	FROM
ADL	ADL	JGM	TO
BWN3181	ADL1133	NMP2107	CREW/CLIID
CHANCHAL DAS DUAL	EL PALLAB CHAKRABORTY	EL SEKHAR MAHATA G12	CREW/CLINAME
ALP	LPG	LPG	DESIG
03-06-2026	03-06-2026	02-06-2026	ABNDATE
21:20	13:09	22:37	ABN.TIME
01		122/11	FROMKM
08		153/25	TO KM
YS	YS	YS	STATUS
APPUSER	APPUSER	APPUSER	FILLED BY
31216	44131	44370	LOCO
TKDE	CNBE	EDE	LOCO SHED
ME/N/KPPS		E/BOST/ICY	TRAIN
05-06-26 18:12	05-06-26 18:12	04-06-26 09:34	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:We Have Booked C/F - 09/45 O/D -09/15 from BWN To ADL (Lpg - P. K Jha / BWN 2471& ALP - C. Das/BWN 3181). Trn No - ME/N/KPPS Loco No - 31216+31634 . Bwn Dep -11/29 ADL Arr- 19/15 Reliever Came At 20:50 Hrs .After Arriving At ADL We Came To Know That Our Reliever T.O at 21/00 Hrs. We Have Requested ADL PA / TLC KGP/TLC HWH To Relieve Us Quickly As We Have Completed 10 Hrs Duty Already In This Hot Weather & Feel Very Exhausted.But They Have Not Done It , Also We Request For Shutdown As They Have No Reliever But They Also Deny It To Do .	DETAIL:I Was Working Train From Bwn To Adl . After Arrival At Adl At 11.52 Crew Relief At 12.50 Arrived At Andul Panel For Relief Stamp At 13.02 Hrs . After Waiting For 3 Min Andul STATION MASTER refused To Give Stamp At 13.05 And Said He Will Give Stamp At Engine Relief Time. Hence He Did Not Provided Any Stamp To My T34 Tickit	DETAIL:Duty Time 17 Hrs 30 min.What Is The Role Of Long Hrs Monitoring?Why Not Relief In Time?	
CLOSE_REM:as per traffic dept The incoming crew were relieved by outgoing crew at 20:45 hours as there was no shutting TO available at that time.	CLOSE_REM:as per Traffic dept Noted and necessary instructions have been given to on duty staff..	CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	Closing Remarks
APP_REM:@TRAFFICKGP/05-06-2026 13:50-The incoming crew were relieved by outgoing crew at 20:45 hours as there was no shutting TO available at that time.	APP_REM:@TRAFFICKGP/05-06-2026 13:47-Noted and necessary instructions have been given to on duty staff.	APP_REM:@HCHSINGH/04-06-2026 09:07-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	App Remarks
05-06-2026 13:50	05-06-2026 13:47	04-06-2026 09:07	App Remarks Date
03-06-2026 22:04	03-06-2026 13:15	03-06-2026 02:42	Reporting Date

7	6	5	4	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	BRAKE POWER CERTIFICATE	OTHER	OTHER	SUBHEAD
HDCB	KGP	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
ABB	DNT	HDCB	RNTL	FROM
DZK	JER	ADL	BHC	TO
ADL1709	KGP2360	ADL1709	NMP1516	CREW/CLUID
EL RAJ KUMAR RANJAN G12	EL PRAMOD KUMAR DUAL	EL RAJ KUMAR RANJAN G12	EL SUBHAMAY PODDER G12	CREW/CLINAME
SALP	LPG	SALP	LPG	DESIG
08-06-2026	07-06-2026	07-06-2026	06-06-2026	ABNDATE
12:00	10:34	05:15	11:44	ABN.TIME
15	180/2	58		FROMKM
55	180/32	12		TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
33012	70851	42661	33667	LOCO
KJGE	BNDX	AJUE	BJUE	LOCO SHED
EX ABB	DNT ENGG SPL	BTPN-ICB	BFNS/TSIJ	TRAIN
08-06-26 18:43	08-06-26 18:43	08-06-26 18:43	08-06-26 18:36	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	DETAIL:BPC NO.50000830591 ISSUEDATE 07/11/2025 INTENSIVE/INVALIDE CONTINIOUS RUN WITH SCR ORDER NO.	DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	DETAIL:Long Hours Duty of 15 Hrs Plus Performed Though Train Arrived At RNTL 10:20 And Relieved Me 11:45 at RNTL.	Detail
CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TO's of crew.	CLOSE_REM:as per traffic dept 3 BRN(E)/Engineering Spl is being utilised by RE Department for continuous 25 KV mast transferring in a short span of BLDA - DNT - JER - BLDA.	CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew.	Closing Remarks
APP_REM:@TRAFFICKGP/08- 06-2026 13:37-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@CWCKGP/07-06- 2026 22:09-Train running with invalid BPC, is not C&W concern, please forward to the concern department.@TRAFFICKGP/08 -06-2026 18:38-3 BRN(E)/Engineering Spl is being utilised by RE Department for continuous 25 KV mast transferring in a short span of BLDA - DNT - JER - BLDA.	APP_REM:@TRAFFICKGP/08- 06-2026 13:35-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@DTISAFETY/07- 06-2026 15:17-Pertains To KGP Division. @TRAFFICKGP/08-06-2026 13:34-Due to congestion in section and excess put back of TO's of crew.	App Remarks
08-06-2026 13:37	08-06-2026 18:38	08-06-2026 13:35	08-06-2026 13:34	App Remarks Date
08-06-2026 12:05	07-06-2026 17:36	07-06-2026 05:29	06-06-2026 14:26	Reporting Date

11	10	9	8	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	SUBHEAD
BLS	KGP	ADL	TATA	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
BHC	BLS	HDCB	TATA	FROM
NYA	KGP	ADL	NMP	TO
BLS1111	BLS1111	ADL1709	TATA7469	CREW/CLUID
EL SUKESH KUMAR	EL SUKESH KUMAR	EL RAJ KUMAR RANJAN G12	JITENDRA KUMAR	CREW/CLINAME
ALP	ALP	SALP	SGD	DESIG
13-06-2026	11-06-2026	09-06-2026	08-06-2026	ABNDATE
18:05	02:45	10:30	22:34	ABN.TIME
		54		FROMKM
		111		TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSE	FILLED BY
38319	28057	33400	33084	LOCO
AQE	DDUX	LDHE	BNDL	LOCO SHED
JEEP	E/NBOX/E	TCL/BCN/L		TRAIN
15-06-26 19:13	11-06-26 22:38	09-06-26 20:57	09-06-26 20:57	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
Detail				
DETAIL:I GOT RELIVED AFTER 12 HR & SIGN OFF AFTER 17 HR				
CLOSE_REM:AS PER TLC Crew after relief reported long hour tlc , advice sign off at kGP due to nearest cms point but crew not coming kGP then advice pt by 18043 ex-nya to bls due to that time kGP jeep at jgm so jeep not available				
DETAIL:MORE THAN 15 HR DUTY				
CLOSE_REM:AS PER TRAFFIC DEPT -Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.				
DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANANGE BY CONTROLLER.				
CLOSE_REM:as per traffic dept Due to congestion in section and excess put back of TOs of crew.				
DETAIL:TM And Crew .T/O 9:15 , KKQ H/D From 21:40 And Till Now There Is No Any program To Receive Train Or Relief Crew And TM. Train No :-N/MOMG, Bpc No 70000109914, TXR :-NMP/KGP, I/Dt.:-29.05.2026				
CLOSE_REM:as per traffic dept Due to congestion in NMP Yard and crews TO not confirmed at that time.				
Closing Remarks				
App Remarks				
APP_REM:@TRAFFICKGP/15-06-2026 11:56-After relieved advice to long hours TLC for providing JEEP by operating side. JEEP is maintained by TLC/KGP.				
APP_REM:@TRAFFICKGP/11-06-2026 15:35-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.				
APP_REM:@TRAFFICKGP/09-06-2026 13:24-Due to congestion in section and excess put back of TO's of crew.				
APP_REM:@TRAFFICKGP/09-06-2026 18:38-Due to congestion in NMP Yard and crews TO not confirmed at that time.				
App Remarks Date				
Reporting Date				

15	14	13	12	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	SUBHEAD
NMP	BLS	BLS	MLDT	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
ABB	MKO	MKO	RPH	FROM
KGP	MKO	MKO	RPH	TO
ADL1709	NMP1460	NMP1460	MLDT7296	CREW/CLUID
EL RAJ KUMAR RANJAN G12	EL DEBASIS NANDI G12	EL DEBASIS NANDI G12	UTTAM KUMAR	CREW/CLINAME
SALP	LPG	LPG	SGD	DESIG
14-06-2026	13-06-2026	13-06-2026	13-06-2026	ABNDATE
19:20	23:46	23:46	23:00	ABN.TIME
15				FROMKM
115				TO KM
YS	YS	YS	SN	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
41342	28749	28749	24675	LOCO
JHSE	RTMD	RTMD	JHSE	LOCO SHED
CCADL	E/N/DPCB	E/N/DPCB	ICDA	TRAIN
15-06-26 15:34	15-06-26 15:34	15-06-26 15:34	16-06-26 15:36	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:LONG DUTY HOURS DUE TO MISMANAGEMENT BY SECTION CONTROLLER.	DETAIL:TRAIN DETAINED AT MKO JT LINE STR FROM 23-46 TO 05-05 HRS,WE COMPLETED 17+ DUTY	DETAIL:TRAIN DETAINED AT MKO JT LINE STR FROM 23.46 TO 05.05,WE COMPETED 17+ HOURS DUTY	DETAIL:SIR TRAIN ICDA LOCO 24675 BPC 70000111379 ISSUE NMP/KGP/SER DATE 11/06/26 VALIDITY 10/07/26 CC RAKE इस ट्रेन में जो VG दिया गया है वो पुराना VG को EMPTY से LOAD कलम से काट कर लिख दिया गया है जो कि सही नहीं है।सही तरीके से VG लोडिंग स्टेशन से नहीं दी जा रही हैं और लोडिंग पेपर भी नहीं दिया रहा है।इसका लोडिंग स्टेशन CTCS हैं। कमर्शियल स्टॉफ द्वारा लोडिंग पेपर भी नहीं दिया गया है। हमारे उच्च अधिकारियों से नम्र निवेदन है कि इस पर उचित करवाई की जानी चाहिए ताकि सभी पेपर ट्रेन मैनेजर को दी जाए जो मिलना चाहिए।और लोडिंग समान क्या है ICDA में वो भी पूछने के बाद नहीं बताया जाता हैं जबकि TM के पास इसकी जानकारी होनी चाहिए।	
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time.	CLOSE_REM:as per TRAFFIC Dept Necessary instruction has been given to the concerned staff.	Closing Remarks
APP_REM:@TRAFFICKGP/15-06-2026 11:58-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/15-06-2026 11:58-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/15-06-2026 11:57-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time.	APP_REM:@TRAFFICKGP/16-06-2026 12:08-Necessary instruction has been given to the concerned staff.	App Remarks
15-06-2026 11:58	15-06-2026 11:58	15-06-2026 11:57	16-06-2026 12:08	App Remarks Date
14-06-2026 20:42	14-06-2026 06:39	14-06-2026 06:35	13-06-2026 23:42	Reporting Date

20	TRAFFIC	19	18	17	16	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	OTHER	OTHER	OTHER	SUBHEAD
SRC	NMP	ADL	ADL	BLS	TATA	REPORTSTTN
KGP	KGP	KGP	KGP	KGP	KGP	REPORTDIV
HWH	HDCB	ABB	ABB	BHC	TATA	FROM
SRC	ADL	ABB	ABB	BLS	KGP	TO
SRC2094	NMP7611	ADL1135	ADL1135	BLS1114	TATA2782	CREW/CLUID
EL RAJESH KUMAR V/B	NAVNEET KUMAR 2	EL SK. KAMARUL ISLAM	EL RAVI MANDAL G12	RAUSHAN KUMAR II(DLXZZU)..D	CREW/CLINAME	
LPG	GD	LPG	ALP	SALP	DESIG	
20-06-2026	19-06-2026	18-06-2026	17-06-2026	14-06-2026	ABNDATE	
01:30	21:54	00:35	12:55	21:15	ABN.TIME	
3		18			FROMKM	
5		17			TO KM	
YS	YS	YS	YS	YS	STATUS	
CREW	APPUSE	CREW	APPUSE	APPUSE	FILLED BY	
70378	31037	60367	38629	70796	LOCO	
BNDX	PTRX	NGPE	NGCD	BNDX	LOCO SHED	
D/S-I	E/BTPN/RCD	N/ACSY	E/N/ATLP	MD/HL/BCN/SV	TRAIN	
21-06-26 13:27	21-06-26 13:28	19-06-26 17:48	18-06-26 21:04	15-06-26 19:13	SMSTO LP	
KGP	KGP	KGP	KGP	KGP	Div	
Y	Y	Y	Y	Y	RemStts	
DETAIL:PERFORM MORE THAN 13 HRS DUTY DUE TO MISMANAGEMENT	DETAIL:Brake Van Key Missing Of Modified BRAKE Van With No. ER87022613432 Bpc No. 50000911032 I/S :- HLZ_BH YD/KGP/SER I/D :- 19/06/2026(intensive)	DETAIL:SM/ABB REFUSED TO STAMP TOTAL SHUNTING TIME,SHUNTING PERFORMED BY CREW I AFTER RECEIVING MEMO,PLACEMENT,& SHUNTING	DETAIL:More than 14 hours of duty from sign on to sign off.	DETAIL:Mis Behave and abusive language By Operating Staff at KGP GODDS YD.		
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Modified BV Key are not yet supplied to KGP/NMP based TMR.	CLOSE_REM:as per traffic dept Necessary instructions have been given to concerned staff.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Necessary instructions have been given to the concerned staff.	Closing Remarks	
APP_REM:@TRAFFICKGP/21-06-2026 12:11-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@CWCKGP/19-06-2026 22:06-B/V key is not maintained by C&W - it is to be handed over by Yard Master or I/C Guard to O/G Guard - so please forward to Operating department.@TRAFFICKGP/21-06-2026 12:14-Modified BV Key are not yet supplied to KGP/NMP based TMR.	APP_REM:@TRAFFICKGP/19-06-2026 11:43-Necessary instructions have been given to concerned staff.	APP_REM:@TRAFFICKGP/18-06-2026 17:48-Due to congestion in section and excess put back of TO's of crew.	APP_REM:@TRAFFICKGP/15-06-2026 17:42-Necessary instructions have been given to the concerned staff.	App Remarks	
21-06-2026 12:11	21-06-2026 12:14	19-06-2026 11:43	18-06-2026 17:48	15-06-2026 17:42	App Remarks Date	
20-06-2026 01:39	19-06-2026 21:58	18-06-2026 01:20	17-06-2026 13:29	14-06-2026 23:57	Reporting Date	

24	23	22	21	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SIGNAL EXCHANGE	SUBHEAD
NMP	SRC	KGP	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
HAUR	SRC	HDCB	KGP	FROM
NMP	SHM	KGP	TATA	TO
ADL1135	SRC1847	ADL1008	KGP0082	CREW/CLUID
EL SK. KAMARUL ISLAM	EL BABU RAM MONDAL	EL MOHAN ADHIKARI G12	BRIHASPATI DAS	CREW/CLINAME
LPG	LPG	LPG	Chief Loco Inspector	DESIG
20-06-2026	20-06-2026	20-06-2026	20-06-2026	ABNDATE
12:30	12:00	05:25	02:34	ABN.TIME
80	11			FROMKM
120	12			TO KM
YS	YS	YS	YS	STATUS
CREW	CREW	CREW	APPUSER	FILLED BY
34260	70847	38009	37004	LOCO
ROUE	BNDX	SYHE	TATE	LOCO SHED
EX ABB	SHM/PC	BLC/JUNGU	18005	TRAIN
21-06-26 13:27	21-06-26 13:27	21-06-26 13:27	21-06-26 22:35	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:INFORM LONG HRS.@HAU H/S PASS 9HRS DUTY. AS SCR AGREED, HAU ASSURED TO GIVE US WRITTEN PROG,BRING TR TO S/S, WAIT FOR MEMO, NO MEMO CAME THEN HAU REPLY SCR CHANGED MIND, REFUSE TO GIVE PROG. MK ALAM OVER CUG ASSURE REL @MPD/JPR, REL@JPR@9-45,NO TR TO PILOT, DRAINED CREW DUTY HRS APPOX 16HRS.	DETAIL:CREW PERFORMED 13 HOURS DUTY DUE TO NOT RELIEVED WITHIN STIPULATED HOURS.	DETAIL:EXCESSIVE LONG DUTY	DETAIL:All right signal not exchanged from GUD	Detail
CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	CLOSE_REM:AS PER TRAFFIC DEPT On duty staff have been exchanged ARS with LP & TMR. However, they have been counselled by SS/GUD to exchange ARS from clear and visible places.	Closing Remarks
APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	APP_REM:@OPTGCNTL3/20-06-2026 15:41-This abnormality is not pertaining to CKP division.@TRAFFICKGP/21-06-2026 21:02-On duty staff have been exchanged ARS with LP & TMR. However, they have been counselled by SS/GUD to exchange ARS from clear and visible places.	App Remarks
21-06-2026 12:12	21-06-2026 12:12	21-06-2026 12:12	21-06-2026 21:02	App Remarks Date
20-06-2026 12:33	20-06-2026 13:08	20-06-2026 06:03	20-06-2026 15:25	Reporting Date

27	26	25	SNO.
TRAFFIC	TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	OTHER	OTHER	SUBHEAD
BHC	ADL	NMP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
BHC	ADL	ADL	FROM
KGP	ADL	KGP	TO
BHC1612	ADL1135	ADL1709	CREW/CLUID
BAJUNATH PRASAD	EL SK. KAMARUL ISLAM	EL RAJ KUMAR RANJAN G12	CREW/CLINAME
SALP	LPG	SALP	DESIG
21-06-2026	21-06-2026	21-06-2026	ABNDATE
23:51	03:55	00:30	ABN.TIME
	12	12	FROMKM
	11	115	TO KM
YS	YS	YS	STATUS
APPUSER	CREW	CREW	FILLED BY
44031	31055	43950	LOCO
WATE	PTRX	KZJL	LOCO SHED
08046	BCN/BEN/GYP	GFMK/CONTAINER	TRAIN
23-06-26 23:26	22-06-26 18:11	21-06-26 13:27	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:Mera To17:00 Hrs Ko Bhadrak to Kharagpur Coaching LR, Train no 08046,Loco no44031 Diya Gaya Mera Duty Off 23:38hrs Ko Hua Main Kgp Running Room Me Gaya to Kaha gaya Ki Bed Nahi hai Aur Kgp Lobby me Kaha gaya Ki 2gante Ke Bad Kgp to Bhc LR Book Kara Kar Chale Jaye Ab Raat me Main Kya Karu?	DETAIL:TR ARRIVAL 03-55, OUTGOING CREW AVAILABLE 21.30/OVERSTAYED. BUT TO 05-00 HRS.	DETAIL:LONG HOURS DUTY PERFORMED DUE TO MISMANAGE BY CONTROLLER.	
CLOSE_REM:AS PER KGP RUNNING ROOM IC HIGH OCCUPANCY OF COACHING CREW AT THAT TIME. SO THAT WE CAN NOT PROVIDE BED FOR LR CREW. BUT WE HAD ADVICE TO CREW TO GO TO NMP RUNNING ROOM FOR PROPER REST AS BED WAS AVAILABLE AT NMP RUNNING ROOM.	CLOSE_REM:as per traffic dept Due to excess put back of TOs of crew.	CLOSE_REM:AS PER TRAFFIC DEPT Due to congestion in section and excess put back of TOs of crew. Crew demanded but not provided in time	Closing Remarks
APP_REM:@TRAFFICKGP/23-06-2026 11:44-It pertains to Electric department.	APP_REM:@TRAFFICKGP/22-06-2026 16:38-Due to excess put back of TO's of crew.	APP_REM:@TRAFFICKGP/21-06-2026 12:12-Due to congestion in section and excess put back of TO's of crew. Crew demanded but not provided in time	App Remarks
23-06-2026 11:44	22-06-2026 16:38	21-06-2026 12:12	App Remarks Date
22-06-2026 00:05	21-06-2026 05:41	21-06-2026 00:31	Reporting Date

29	28	SNO.
TRAFFIC	TRAFFIC	ABN.TYPE
OTHER	BRAKE POWER CERTIFICATE	SUBHEAD
TDL	NMP	REPORTSTTN
KGP	KGP	REPORTDIV
CNBN	TATA	FROM
TDLN	KGP	TO
TDL8730	NMP7549	CREW/CLIID
SHUSHANT UPADHYAY	MD MUSTAQUE	CREW/CLINAME
GD	GD	DESIG
24-06-2026	23-06-2026	ABNDATE
10:59	05:05	ABN.TIME
460		FROMKM
725		TO KM
PN	PN	STATUS
APPUSER	APPUSER	FILLED BY
33780	41117	LOCO
TKDD	TKDE	LOCO SHED
BVH	BTPN HLZ EMPTY	TRAIN
		SMSTO LP
KGP	KGP	Div
Y	Y	RemStts
DETAIL:Bpc 50000911962 Bksc/Adra/Ser Issue 21/06/26 Valid 03/07/26 Brakevan Ecor 87122211033 Bvcm Return 09/26 Bv Ko Bpc Me Mention Ni Kiya Gya H . Bv Ki Chair Bilkul Bekar H N Hath Rkhne Ki Jgh N Moveble . Khidki Ka Glass Tuta Hua H . Bhut Avaj Or Vibration Ho Rha H. Modified Kre To Thik Se Kre Esi Problems N Ho	DETAIL:Bpc Invalid	Detail
		Closing Remarks
APP_REM:@CWCKGP/24-06-2026 20:24-Mentioned Brake Van Is Now Running With Premium BPC And Which Is Valid Upto 03/07/26. However Int BPC Was Issued By Hlz On Dt 16/06/26 And Allowed For Single Trip Upto Destination. So Kindly Inform Upcoming Examination Point For Necessary Action.@TRAFFICKGP/25-06-2026 16:27-Not pertains to operating department, KGP Division.	APP_REM:@CWCKGP/24-06-2026 18:58-As Per TMR BPC No-50000901054 Issues By NJPT/KIR/NFR on Dt-21/05/26, Which Was Invalid On Dt 19/06/2026. Running Of Train Maintained By Optg Dept. So Kindly Advice To Provide Thevrake At Upcoming C&W Point For Examination.@TRAFFICKGP/25-06-2026 16:20-Since BTPN(E) rakes are not now examined at HLZ depot. Hence, after expiry of BPC the rake send to VZP base depot for C&W examination as per HQ instruction.	App Remarks
25-06-2026 16:27	25-06-2026 16:20	App Remarks Date
24-06-2026 11:03	23-06-2026 05:20	Reporting Date