



STEPPER_MOTOR_CONNECTION_2 0.1uF 50V GND C10 place near SN74AHCT125N U2 SN74AHCT125N Stepper_ENABLED-Stepper_DIRD-PUL+ GND (C DIR+ Stepper_PULSED-J4C RJ45 x4 GND ($GND \sqrt{\frac{4\overline{0E}}{13}}$ +3.3V **←** SIG GND C2 +3.3\ U4B 74HC14 Stepper_END< D4 ESD5Z5_OT1G 0.1uF 50V Sheet: /Stepper02/ File: Stepper02.kicad_sch Title: Size: A4 Date: KiCad E.D.A. kicad 7.0.5-0 ld: 3/5

STEPPER_MOTOR_CONNECTION_3 +5V**↑** GND C5 U3 SN74AHCT125N Stepper_ENABLED-GND (20E J4B RJ45 x4 Stepper_DIRD-PUL+_ GND (B) DIR+ Stepper_PULSED-GND (+3.3V ← SIG GND B2 +3.3V U4A 74HC14 R6 10k Stepper_END⟨ D6 SESD5Z5_OT1G 0.1uF 50V Sheet: /Stepper03/ File: Stepper03.kicad_sch Title: Size: A4 Date: KiCad E.D.A. kicad 7.0.5-0 ld: 4/5

