

CASE SERVICE REPORT

CASE NO. 76118 **SALES ORDER** SO69201

ORDER DATE 1/8/2024

CASETYPE Electrical Private - Service PPM

CASE DETAILS 12 of 21

CUSTOMER DETAILS

ASSET DETAILS

CUSTOMER

HOLI001 HOLIDAY INN (HOLI001) HOLIDAY INN

28 -32 O CONNELL STREET

DUBLIN 1 Ireland ASSET NAME

ADDRESS

Holiday Inn O Connell St O Connell Street, Dublin,

PARTS & CHARGES

QUANTITY ITEM DESCRIPTION

1 SERVICEFA Fire Alarm Service

TASK NO. 4832211

SERVICE DATE: 29/8/2024 TECHNICIAN: Mick Martin TASK TYPE: Site Visit

RESULT FOLLOW UP

ACTIONS COMPLETED DURING SERVICE

Job Completed

Quarterly service of fire alarm system, 3rd-2nd and 1st floor bedrooms tested, all devices tested in good working order. Full report on nimbus. Panel batteries checked. No output test by request, client did test on 28/8 nothing to report. System reset and left in healthy condition. 30x minute test completed on emergency lighting system, full report of failures supplied to client. Disabled refuge system checked all points and locations checked. Handset needs to be replaced as intermittent reception on this occasion.

Fire Alarm System ASSET: Holiday Inn O Connell St Were there any faults on the system before the service commenced Nο Entries in the logbook were checked Yes Event logs checked on the fire alarm panels Yes False alarm reports were investigated and corrective actions communicated to the client Fire panel alarm functions and controls were checked Yes Standby batteries and connections were checked Yes Manual call points and detectors were checked in accordance with current IS3218 standard Yes Sounders & VADs were tested and verified Nο ARC link to the monitoring station was tested and verified N/A Client has been notified of links to third party equipment and the tests required Yes Alternations (if any) to the fire detection and alarm system since the last service has been documented N/A Structural and occupancy alternations (if any) to the building layout which affect the FDAS has been documented N/A All zones are clearly identified Yes A zone chart is fitted beside the fire panel Yes A model D2 fire detection and alarm system certificate is in place and has been updated Yes Logbook has been updated Yes A model D1 Fire detection and alarm system certificate has been issued Yes Fire alarm system returned to normal operating mode on departure Yes Recommendation were made (if yes list in body of report) N/A



CASE SERVICE REPORT

ASSET: Holiday Inn O Connell St Entries in Logbook checked Yes There is a suitable test facility (CTU) for simulating failure of supply Yes A 30 minute duration test was completed in accordance with the current IS3217 standard Yes A 180 minute duration test was completed in accordance with the current IS3217 standard No Status LED's on the emergency light fittings were checked after completing the duration test Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Emergency lighting system certificate for annual inspection and testing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed Yes Emergency lighting system emade (if yes, list in body of report) Poisabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Yes Communications were tested from each outstation to the master panel Recommendation were made (if yes list in body of report) Yes	Emergency Lighting System	
There is a suitable test facility (CTU) for simulating failure of supply A 30 minute duration test was completed in accordance with the current IS3217 standard A 180 minute duration test was completed in accordance with the current IS3217 standard No Status LED's on the emergency light fittings were checked after completing the duration test Yes Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Emergency lighting system certificate for annual inspection and testing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked Yes All refuge outstations were checked for damage and remain unobstructed and conspicuous Yes Communications were tested from each outstation to the master panel	ASSET: Holiday Inn O Connell St	
A 30 minute duration test was completed in accordance with the current IS3217 standard A 180 minute duration test was completed in accordance with the current IS3217 standard No Status LED's on the emergency light fittings were checked after completing the duration test Yes Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Yes Emergency exit signs clearly and unambiguously indicate direction of escape Yes Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed Ni/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Yes Communications were tested from each outstation to the master panel	Entries in Logbook checked	Yes
A 180 minute duration test was completed in accordance with the current IS3217 standard No Status LED's on the emergency light fittings were checked after completing the duration test Yes Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Pisabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Yes Communications were tested from each outstation to the master panel	There is a suitable test facility (CTU) for simulating failure of supply	Yes
Status LED's on the emergency light fittings were checked after completing the duration test Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Poisabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were tested from each outstation to the master panel Yes Communications were tested from each outstation to the master panel	A 30 minute duration test was completed in accordance with the current IS3217 standard	Yes
Structural and occupancy alterations (if any) to the building layout which affects the emergency lighting have been documented Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Poisabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were tested from each outstation to the master panel Yes	A 180 minute duration test was completed in accordance with the current IS3217 standard	No
Emergency exit signs are in maintained operation mode Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked Yes All refuge outstations were tested from each outstation to the master panel Yes	Status LED's on the emergency light fittings were checked after completing the duration test	Yes
Emergency exit signs clearly and unambiguously indicate direction of escape Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated No Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Yes Communications were tested from each outstation to the master panel		N/A
Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated Emergency lighting system report for inspection, testing and servicing were completed Yes Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel	Emergency exit signs are in maintained operation mode	Yes
Emergency lighting system report for inspection, testing and servicing were completed Emergency lighting system certificate for annual inspection and testing were completed N/A Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Emergency exit signs clearly and unambiguously indicate direction of escape	Yes
Emergency lighting system certificate for annual inspection and testing were completed Logbook has been updated Recommendations were made (if yes, list in body of report) Yes Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel N/A Yes N/A Yes	Emergency lighting system model schedule for periodic inspections, tests and servicing due dates were updated	No
Logbook has been updated Recommendations were made (if yes, list in body of report) Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Yes Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Emergency lighting system report for inspection, testing and servicing were completed	Yes
Recommendations were made (if yes, list in body of report) Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Emergency lighting system certificate for annual inspection and testing were completed	N/A
Disabled Refuge System ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Logbook has been updated	Yes
ASSET: Holiday Inn O Connell St Panel alarm functions and controls were checked Standby batteries and connections were checked Yes All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Recommendations were made (if yes, list in body of report)	Yes
Panel alarm functions and controls were checked Standby batteries and connections were checked Yes All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Disabled Refuge System	
Standby batteries and connections were checked All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	ASSET: Holiday Inn O Connell St	
All refuge outstations were checked for damage and remain unobstructed and conspicuous Communications were tested from each outstation to the master panel Yes	Panel alarm functions and controls were checked	Yes
Communications were tested from each outstation to the master panel Yes	Standby batteries and connections were checked	Yes
·	All refuge outstations were checked for damage and remain unobstructed and conspicuous	Yes
Recommendation were made (if yes list in body of report) Yes	Communications were tested from each outstation to the master panel	Yes
	Recommendation were made (if yes list in body of report)	Yes

SIGN OFF

Customer: David

Customer signature not entered