

Boiler / Burners

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 | |
|----------------|--|-----------|--------|--|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | | |
| Client Contact | Darren Murray | | | |
| Date | 19/03/2024 | PPM Visit | 1 of 2 | |

| Asset No | 010 | Asset Location | Plant room |
|--------------------|------------|----------------|------------|
| Make | Eurofluid | Model / Serial | CB 125 HW |
| Applicance type | Gas Boiler | Fuel Type | N-G |
| Rating - KW & Year | 2023 | | |

Maintenance Report


| Checklist | | Combustion Analysis | | |
|---|------------|--|-----------|-----------|
| 1. Check appliance casing condition | Yes | 20. Setting | | |
| 2. Check for leaks | Yes | 21 02 | 6.1% % | 7.4% % |
| 3. Check flues | Good | 22. CO PPM | 52ppm | 5 |
| 4. Clean internally | Inspection | 23. C02 | 8.4% % | 7.7% % |
| 5. Visionally check flame | N/A | 24. Ratio | 0.0006 | 0.0001 |
| 6. Check fan and air flow switch | N/A | 25. Pressure | 0.12 Mbar | 0.13 Mbar |
| 7. Test ignition / ionisation photo cell probes | N/A | 26. Excess Air | 40.9 | 55% |
| 8. Test anodes probes | N/A | 27. Temp Dew Point | °C | °C |
| 9. Appliance set point | 65 °C | 28. Eff NetHE | 98.2 % | 104.4 % |
| 10. Test thermostat / high limit stat | N/A | 29. Eff NetHE | % | % |
| 11. Is air intake clear? | Yes | 30. Eff Gross | % | % |
| 12. Check burner lockout | Yes | 31. Temp | 59 °C | 41 °C |
| 13. System pressure | Yes | 32. Temp Inlet | 20 °C | 20 °C |
| 14. Check pump operation | Yes | 33. Temp Net | 39 °C | 21 °C |
| 15. Low pressure switch | Yes | 34. Check AAV and PRVon appliance | Yes | |
| 16. Check high / low flame | Yes | 35. Check internal expansion vessel | Yes | |
| 17. Check clean gas / oil nozzle | Yes | 36. Condense trap cleaned and primed | Yes | |
| 18. Visionally check oil pip for leaks | N/A | 37. Visually inspection appliance pipework | Yes | |
| 19. Let by and soundness test | Yes | 38. Let by and soundness test results | Pass | |
| Engineer Comments | | | | |

FGA is not matching the manufacturer instructions so will need to be adjusted. Fault code 207 keeps appearing and needs to be rectified via warranty callout.


| Repair Required | No | | |
|-----------------|-------------|---------------------|--|
| Engineers Name | Tadhg Duffy | Engineers Signature | |







Report Ref: B01 / B02 / B06





Boiler / Burners

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 | |
|----------------|--|-----------|--------|--|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | | |
| Client Contact | Darren Murray | | | |
| Date | 19/03/2024 | PPM Visit | 1 of 2 | |

| Asset No | 011 | Asset Location | Plantroom |
|--------------------|------------|----------------|-----------|
| Make | Eurofluid | Model / Serial | CB 125 HW |
| Applicance type | Gas Boiler | Fuel Type | N-G |
| Rating - KW & Year | 2023 | | |

Maintenance Report


| Checklist | | Combustion Analysis | | |
|--|-------|--|-----------|-----------|
| 1. Check appliance casing condition | Yes | 20. Setting | | |
| 2. Check for leaks | Yes | 21 02 | 6.1% % | 7.1 % |
| 3. Check flues | Good | 22. CO PPM | 35 | 5 |
| 4. Clean internally | Yes | 23. C02 | 8.4 % | 7.9 % |
| 5. Visionally check flame | N/A | 24. Ratio | 0.0004 | 0.0001 |
| 6. Check fan and air flow switch | N/A | 25. Pressure | O.15 Mbar | O.14 Mbar |
| 7. Test ignition / ionisation photo cell probes | N/A | 26. Excess Air | 40.8 | 51 |
| 8. Test anodes probes | N/A | 27. Temp Dew Point | °C | °C |
| 9. Appliance set point | 75 °C | 28. Eff NetHE | 98.4 % | 100.1 % |
| 10. Test thermostat / high limit stat | N/A | 29. Eff NetHE | % | % |
| 11. Is air intake clear? | Yes | 30. Eff Gross | % | % |
| 12. Check burner lockout | Yes | 31. Temp | 56 °C | 51 °C |
| 13. System pressure | Yes | 32. Temp Inlet | 21 °C | 21 °C |
| 14. Check pump operation | Yes | 33. Temp Net | 35 °C | 30 °C |
| 15. Low pressure switch | Yes | 34. Check AAV and PRVon appliance | Yes | |
| 16. Check high / low flame | Yes | 35. Check internal expansion vessel | Yes | |
| 17. Check clean gas / oil nozzle | Yes | 36. Condense trap cleaned and primed | Yes | |
| 18. Visionally check oil pip for leaks | N/A | 37. Visually inspection appliance pipework | Yes | |
| 19. Let by and soundness test | Yes | 38. Let by and soundness test results | Pass | |
| Engineer Comments | | | | |
| Boiler 2 is working fine and is within correct parameter | S. | | | |

| Repair Required | | | |
|-----------------|-------------|---------------------|--|
| Engineers Name | Tadhg Duffy | Engineers Signature | |











Boiler / Burners

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 | |
|----------------|--|-----------|--------|--|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | | |
| Client Contact | Darren Murray | | | |
| Date | 19/03/2024 | PPM Visit | 1 of 2 | |

| Asset No | 012 | Asset Location | Plantroom |
|--------------------|------------|----------------|-----------|
| Make | Eurofluid | Model / Serial | CB 125 HW |
| Applicance type | Gas Boiler | Fuel Type | N-G |
| Rating - KW & Year | 2023 | | |


Maintenance Report

| Checklist | Checklist Combustion Analysis | | | |
|---|-------------------------------|--|-----------|---------------|
| 1. Check appliance casing condition | Yes | 20. Setting | | |
| 2. Check for leaks | Yes | 21 02 | 6.0 % | 6.7 % |
| 3. Check flues | Good | 22. CO PPM | 26 | 6 |
| 4. Clean internally | Yes | 23. C02 | 8.5 % | 8.1 % |
| 5. Visionally check flame | N/A | 24. Ratio | | 0.0001 |
| 6. Check fan and air flow switch | N/A | 25. Pressure | 0.0003 MI | oar 0.19 Mbar |
| 7. Test ignition / ionisation photo cell probes | N/A | 26. Excess Air | 40.2 | 47 |
| 8. Test anodes probes | N/A | 27. Temp Dew Point | °C | °C |
| 9. Appliance set point | 75 °C | 28. Eff NetHE | 98.1 % | 98.7 % |
| 10. Test thermostat / high limit stat | N/A | 29. Eff NetHE | % | % |
| 11. Is air intake clear? | Yes | 30. Eff Gross | % | % |
| 12. Check burner lockout | Yes | 31. Temp | 61 °C | 53 °C |
| 13. System pressure | Yes | 32. Temp Inlet | 21 °C | 21 °C |
| 14. Check pump operation | Yes | 33. Temp Net | 40 °C | 32 °C |
| 15. Low pressure switch | Yes | 34. Check AAV and PRVon appliance | Yes | |
| 16. Check high / low flame | Yes | 35. Check internal expansion vessel | Yes | |
| 17. Check clean gas / oil nozzle | Yes | 36. Condense trap cleaned and primed | Yes | |
| 18. Visionally check oil pip for leaks | Yes | 37. Visually inspection appliance pipework | Yes | |
| 19. Let by and soundness test | Yes | 38. Let by and soundness test results | Pass | |
| Engineer Comments | | | | |
| Boiler 3 working fine, FGA readings not matching up | with guidelines. | | | |

| Repair Required | | | |
|-----------------|-------------|---------------------|--|
| Engineers Name | Tadhg Duffy | Engineers Signature | |









Boiler / Burners

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 | |
|----------------|--|--|--------|--|
| Client Site | Findlater House Ltd 28-32 O'Connell Street D | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | |
| Client Contact | Darren Murray | Darren Murray | | |
| Date | 19/03/2024 | DDM Visit | 1 of 2 | |

| Asset No | 013 | Asset Location | Plantroom |
|--------------------|------------|----------------|-----------|
| Make | Eurofluid | Model / Serial | CB 125 HW |
| Applicance type | Gas Boiler | Fuel Type | N-G |
| Rating - KW & Year | 2023 | | |

Maintenance Report

| Checklist | | Combustion Analysis | | | |
|--|-----------------|--|----------|--------------|--|
| 1. Check appliance casing condition | Yes | 20. Setting | | | |
| 2. Check for leaks | Yes | 21 02 | 6.4 % | % | |
| 3. Check flues | Good | 22. CO PPM | 21 | 7.4 | |
| 4. Clean internally | Yes | 23. C02 | 8.3 % | 7.7 % | |
| 5. Visionally check flame | N/A | 24. Ratio | 0.0003 | 0.0001 | |
| 6. Check fan and air flow switch | N/A | 25. Pressure | 0.20 Mba | ar 0.18 Mbar | |
| 7. Test ignition / ionisation photo cell probes | N/A | 26. Excess Air | 44 | 55 | |
| 8. Test anodes probes | N/A | 27. Temp Dew Point | °C | °C | |
| 9. Appliance set point | 75 °C | 28. Eff NetHE | 97.6 % | 98.4 % | |
| 10. Test thermostat / high limit stat | N/A | 29. Eff NetHE | % | % | |
| 11. Is air intake clear? | Yes | 30. Eff Gross | % | % | |
| 12. Check burner lockout | Yes | 31. Temp | 73 °C | 54 °C | |
| 13. System pressure | Yes | 32. Temp Inlet | 22 °C | 22 °C | |
| 14. Check pump operation | Yes | 33. Temp Net | 51 °C | 32 °C | |
| 15. Low pressure switch | Yes | 34. Check AAV and PRVon appliance | Yes | | |
| 16. Check high / low flame | Yes | 35. Check internal expansion vessel | Yes | | |
| 17. Check clean gas / oil nozzle | Yes | 36. Condense trap cleaned and primed | Yes | | |
| 18. Visionally check oil pip for leaks | Yes | 37. Visually inspection appliance pipework | Yes | | |
| 19. Let by and soundness test | Yes | 38. Let by and soundness test results | Pass | | |
| Engineer Comments | | | | | |
| Boiler 4 operating correctly. FGA readings not matchin | ng up with manu | facturer instructions so will need warranty callout. | | | |

| Repair Required | | | |
|-----------------|-------------|---------------------|--|
| Engineers Name | Tadhg Duffy | Engineers Signature | |







Report Ref: B01 / B02 / B06



Roiler / Rurners

| natura. | 1 - I- NI - | 000 |
|---------|------------------|-----|
| | | |
| | | |
| Boller | <i>i</i> Burners | |

Report Ref: B01 / B02 / B06

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 |
|----------------|--|-----------|--------|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | |
| Client Contact | Darren Murray | | |
| Date | 19/03/2024 | PPM Visit | 1 of 2 |

| Asset No | Asset Location | |
|--------------------|----------------|--|
| Make | Model / Serial | |
| Applicance type | Fuel Type | |
| Rating - KW & Year | | |

Maintenance Report

| Checklist | | Combustion Analysis | | | |
|---|------|--|------|------|--|
| 1. Check appliance casing condition | | 20. Setting | | | |
| 2. Check for leaks | | 21 02 | % | % | |
| 3. Check flues | | 22. CO PPM | | | |
| 4. Clean internally | | 23. C02 | % | % | |
| 5. Visionally check flame | | 24. Ratio | | | |
| 6. Check fan and air flow switch | | 25. Pressure | Mbar | Mbar | |
| 7. Test ignition / ionisation photo cell probes | | 26. Excess Air | | | |
| 8. Test anodes probes | | 27. Temp Dew Point | °C | °C | |
| 9. Appliance set point | 0 °C | 28. Eff NetHE | % | % | |
| 10. Test thermostat / high limit stat | | 29. Eff NetHE | % | % | |
| 11. Is air intake clear? | N/A | 30. Eff Gross | % | % | |
| 12. Check burner lockout | | 31. Temp | °C | °C | |
| 13. System pressure | | 32. Temp Inlet | °C | °C | |
| 14. Check pump operation | | 33. Temp Net | °C | °C | |
| 15. Low pressure switch | | 34. Check AAV and PRVon appliance | | | |
| 16. Check high / low flame | | 35. Check internal expansion vessel | | | |
| 17. Check clean gas / oil nozzle | | 36. Condense trap cleaned and primed | | | |
| 18. Visionally check oil pip for leaks | | 37. Visually inspection appliance pipework | | | |
| 19. Let by and soundness test | | 38. Let by and soundness test results | | | |
| Engineer Comments | | | _ | | |

| Repair Required | | | |
|-----------------|-------------|---------------------|--|
| Engineers Name | Tadhg Duffy | Engineers Signature | |