

Site:

FINDLATER HOUSE LTD

FINDLATER HOUSE 28-32 O CONNELL STREET

DUBLIN 1

J86039 Job No:

Summary of Defective Items

End Date:

Customer:

Aviva No.	Serial No.	Description	Status	A Defects	B Defects	Observation
P018	3602468	Air Conditioning Unit No. 3602468 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P014	3602420	Air Conditioning Unit No. 3602420 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P028	2602233	Air Conditioning Unit No. 2602233 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P021	2602210	Air Conditioning Unit No. 2602210 By Daikin	B Defect	No A Defect Noted	Main electrical isolator switch cover loose-rectify by 25-12-2024	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.

Name Of Person Making This Report: ALAN BROWNE





Customer: F

FINDLATER HOUSE LTD

FINDLATER HOUSE 28-32 O CONNELL STREET DUBLIN 1

J86039

Summary of Defective Items

Job No: End Date:

Site:

Aviva No.	Serial No.	Description	Status	A Defects	B Defects	Observation
P015	3602439	Air Conditioning Unit No. 3602439 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P029	3602523	Air Conditioning Unit No. 3602523 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P025	2602218	Air Conditioning Unit No. 2602218 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P026	2602142	Air Conditioning Unit No. 2602142 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.

Name Of Person Making This Report: ALAN BROWNE



Customer:

FINDLATER HOUSE LTD

FINDLATER HOUSE 28-32 O CONNELL STREET DUBLIN 1

J86039 Job No:

Summary of Defective Items

End Date:

Site:

Aviva No.	Serial No.	Description	Status	A Defects	B Defects	Observation
P030	3602486	Air Conditioning Unit No. 3602486 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P032	3602431	Air Conditioning Unit No. 3602431 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P024	2602217	Air Conditioning Unit No. 2602217 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P017	3602442	Air Conditioning Unit No. 3602442 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.

Name Of Person Making This Report: ALAN BROWNE



Customer: FI

FINDLATER HOUSE LTD

FINDLATER HOUSE 28-32 O CONNELL STREET

DUBLIN 1 J86039

Summary of Defective Items

Job No: End Date:

Site:

Aviva No.	Serial No.	Description	Status	A Defects	B Defects	Observation
P020	2602994	Air Conditioning Unit No. 2602994 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P033	2602140	Air Conditioning Unit No. 2602140 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P019	3602437	Air Conditioning Unit No. 3602437 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P027	2602232	Air Conditioning Unit No. 2602232 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.

Name Of Person Making This Report: ALAN BROWNE





Customer:

FINDLATER HOUSE LTD

FINDLATER HOUSE 28-32 O CONNELL STREET

DUBLIN 1 J86039

Summary of Defective Items

Job No: End Date:

Site:

Aviva No.	Serial No.	Description	Status	A Defects	B Defects	Observation
P016	3602438	Air Conditioning Unit No. 3602438 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P031	3602435	Air Conditioning Unit No. 3602435 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.
P023	2602132	Air Conditioning Unit No. 2602132 By Daikin	Observations	No A Defect Noted	No B Defect Noted	All safety/protective devices should be function tested in accordance with the maker's recommendations as part of the routine service by the service engineer and documentation of these records made available for inspection.

Name Of Person Making This Report: ALAN BROWNE