

SERVICE & MAINTENANCE

Water Storage Tank

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 |
|----------------|--|-----------|--------|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | |
| Client Contact | Darren Murray | | |
| Date | 15/03/2024 | PPM Visit | 1 of 2 |

| Asset No | 019 | Asset Location | Plantroom |
|----------|--------|----------------|-----------|
| Make | Tricel | Model | N/A |
| Year | 2016 | | |

Maintenance Report

| 1. Tank Type | Split section | 8. Lid fitted | Yes |
|------------------------------|----------------|--------------------------|---|
| 2. System serving | cws | 9. Tank cleaning updated | Last cleaned on the 28.9.23 / Due 9.24 |
| 3. Ball valve checked | Yes | 10. Tank seals checked | Yes |
| 4. Checked associated valves | Yes | 11. Insulation condition | N/A |
| 5. Overflow pipe checked | Yes | 12. Insect screen fitted | Yes |
| 6. Tank Condition | Good condition | 13. High level alarm | Yes |
| 7. Low level alarm | Yes | | |
| Engineer Comments | | | |

PPM carried out on CWST, both ball valves checked and are operating correctly. Over flow pipes are good, high level alarm fitted. Visual inspection carried out on tank and no signs of any leaks or damage.

| Repair Required | No | | |
|-----------------|-------------|---------------------|----------|
| Engineers Name | Tadhg Duffy | Engineers Signature | 1. Dolly |







Report Ref: WST01











SERVICE & MAINTENANCE

Water Storage Tank

| Client Name | Holiday Inn Express Dublin City Centre | Job No | 206 |
|----------------|--|-----------|--------|
| Client Site | Findlater House Ltd 28-32 O'Connell Street Dublin 1 D01 T2X2 | | |
| Client Contact | Darren Murray | | |
| Date | 15/03/2024 | PPM Visit | 1 of 2 |

| Asset No | Asset Location | |
|----------|----------------|--|
| Make | Model | |
| Year | | |

Maintenance Report

| | maintonaire report | |
|------------------------------|--------------------------|--|
| 1. Tank Type | 8. Lid fitted | |
| 2. System serving | 9. Tank cleaning updated | |
| 3. Ball valve checked | 10. Tank seals checked | |
| 4. Checked associated valves | 11. Insulation condition | |
| 5. Overflow pipe checked | 12. Insect screen fitted | |
| 6. Tank Condition | 13. High level alarm | |
| 7. Low level alarm | | |
| Engineer Comments | | |
| | | |

| Repair Required | | | |
|-----------------|-------------|---------------------|---------|
| Engineers Name | Tadhg Duffy | Engineers Signature | 1. Doly |







