

Parametrix

MX60 MOBILE MAPPING

Internal Review

LIVING DRAFT — INTERNAL REVIEW · WORKING VERSION 2026-09-11-A

Working Version 2026-09-11-a · LIVING DRAFT — INTERNAL REVIEW

These four documents are a living draft for internal Parametrix review, training, testing and workflow development. **They are not an issued Parametrix standard**, and they do not replace professional judgement, project requirements, safety procedures or approved company policy.

Some of what is in them binds anyway. Ten requirements come from Trimble or from the equipment itself — they would bind an MX60 operator at any company, working from no SOP at all. They are listed with their sources at **SOP §2.4**. Everything Parametrix-originated is a proposal: **Parametrix-originated requirements adopted: 0.**

Open this one

YOU ARE	OPEN	START AT
A field operator	Field How To	The Quick Card (Appendix E), then the Preflight Checklist (Appendix A)
An office processor	Office How To	§1, then the section for the step you are on
A surveyor new to mobile mapping	Technical Manual	§4 <i>The workflow end to end</i> , then the In Plain English box at the end of each section
A PLS or QA reviewer	SOP and the Technical Manual	SOP §2.4, §16, §17 — what binds, what QC is, what acceptance is not
A manager or policy reviewer	SOP and the decision register	SOP §17.2 (D-13), then SOP Appendix A

Everyone should read the front matter of whichever document they open. It is short, and it says what the document is and is not.

What feedback matters

This is not primarily a copy-editing exercise. Four questions matter:

1	Is anything technically wrong?

2	Is anything impractical in actual field or office use?
3	Is anything presented more strongly than Parametrix has actually decided?
4	What would prevent you from performing the work using these documents?

Question 3 is the one this project is least able to catch on its own. **Question 4** finds gaps, and a gap is more useful than a correction.

How to comment

Identify the document and the section. For example: `Field How To §17.3` , `Office How To §31` , or `SOP D-13` .

Every section and subsection is numbered, and warnings (`W-n`), open decisions (`D-n`), tests (`Tn`) and vendor questions (`V-n`) carry identifiers that mean the same thing in all four documents.

Comments go to the MX60 Internal Review Log — `_control/mx60-internal-review-log.md` . There is no document owner to send them to yet; that is **D-1**.

The documents

	ANSWERS	WORDS
Technical Manual	Why does it work this way? What is the evidence?	~58,000
SOP	Must I? And on whose authority?	~23,000
Field How To	How do I do it in the vehicle?	~12,000
Office How To	How do I do it in TBC?	~18,000

The SOP governs. A How To cannot create a requirement; if one says something must be done and the SOP does not require it, the SOP is right and the How To is wrong — that is a Q1 comment.

Print on its own

Four Field sheets are built to print without the browser navigation: **Preflight Checklist** · **End-of-Mission Checklist** · **Field Record Form** · **Quick Card** (Field How To appendices A, B, C and E). Each carries the Working Version and the Living Draft status on the page.

What is deliberately unresolved

Open questions are shown as open questions. There are 77 of them — 36 Parametrix decisions, 25 tests and 16 vendor questions — tracked in one register at `_control/master-register.csv` and surfaced as filtered views in the documents. No document carries an item's status independently.

Almost none of them blocks anything. The exceptions are listed at `_control/views/blocking.md`.

D-13, which is the one people ask about

D-13 blocks formal acceptance. It does not block collection, exploratory processing, registration testing, comparison against control, training or workflow development.

The unresolved question is: *until a general Parametrix acceptance standard exists, may MX60 work be accepted against a project-specific written accuracy requirement, using independent check evidence, visual QC and documented professional judgement?* Options **A**, **B** and **C** are set out at **SOP §17.2** and **this draft does not choose between them.**

No numerical acceptance tolerance appears anywhere in these documents, because Trimble publishes none and none has been established by test. Inventing one would be worse than the gap.

Control artefacts

Not reader material, but this is where the machinery lives.

<code>_control/master-register.csv</code>	The one register of open items. Documents carry filtered views, never their own copies
<code>_control/binding-requirements.csv</code>	The ten externally binding requirements, one source quotation each. SOP §2.4 is generated from it
<code>_control/authority-model.md</code>	What makes a statement binding, and on whose authority
<code>_control/warning-register.md</code>	Registered warnings, and the verbatim wording each must carry
<code>_control/ownership-matrix.md</code>	Which document owns each topic, and which only reference it
<code>_control/workflow-stage-names.md</code>	The frozen stage names, identical in all four documents
<code>_control/style/</code>	The shared visual system, cited to the Parametrix Brand Guide v6
<code>_control/circulation/</code>	The Living Draft banner, review panel and Working Version block — one source, four documents
<code>_control/living-draft-change-log.md</code>	What changed at each Working Version, and why

<code>_control/mx60-internal-review-log.md</code>	The comment log template
<code>_control/figure-production-register.md</code>	Figures still to be produced. Project material

Run `python3 tools/check-all.py` before circulating anything. It is the gate.

Parametrix · MX60 Mobile Mapping documentation set · Working Version 2026-09-11-a · **not issued, not approved**