

CALZADO LOBO, S.A. DE C.V. Fracciones por estilo:

LINEA: 4060 JEANS

ESTILO: 4061

	Fracción		Precio	
Departamento			Ma.Obra Vent	
10 CORTE				
	99	CORTAR FORRO A MAQUINA	1.86	1.86
	100	CORTAR PIEL A MAQUINA	3.47	3.47
	111	CORTAR ESPONJA	0.17	0.17
	112	CORTAR MALLA	0.15	0.15
		Total x Depto	5.65	5.65
O RAYADO				
	80	CONTAR TAREA	0.24	0.24
	102	RAYADO	0.76	0.76
	129	ENUMERAR CHINELA Y/O FLORETA	0.08	0.08
	210	PINTAR FILOS	0.11	0.11
		Total x Depto	1.19	1.19
0 REBAJADO Y PERFORADO				
	103	REBAJAR PIEL	0.80	0.80
		Total x Depto	0.8	0.8
0 FOLEADO				
	60	FOLEAR CORTE Y CALIDAD	0.14	0.14
	70	TROQUELAR PLANTILLA	0.08	0.08
	72	TROQUELAR NORMA	0.08	0.08
	75	TROQUELAR CORTE	0.08	0.08
		Total x Depto	0.38	0.38
O PREL-CORTE				
	24	DOMAR CHINELA	0.28	0.28
	74	COTEJAR PIEL Y FORRO	0.34	0.34
	131	LOTEAR ESPONJA	0.08	0.08
		Total x Depto	0.7	0.7
0 ENTRETELADO				
	51	ENTRETELAR	0.34	0.34
		Total x Depto	0.34	0.34
10 PESPUNTE				
	300	PESPUNTE GENERAL	7.72	7.72
	301	PESPUNTAR PLANTILLA	0.71	0.71
		Total x Depto	8.43	8.43
20 PREL-PESPUNTE		·		
	304	PRELIMINAR DE PESPUNTE	4.95	4.95
	333	PONER CASCO - C. PESPUNTE	0.24	0.24
		Total x Depto	5.19	5.19
40 ENSUELADO				
70 27700227 12 0	397	JUNTAR SUELA CORTE	0.01	0.01
	337	Total x Depto	0.01	0.01
80 MONTADO "A"		rotur x Bepto	0.01	0.01
80 WONTADO A	F00	MONTADO GENERAL "A"	11.02	11.02
	500	Total x Depto	11.02	11.02
		тогат х Берго	11.02	11.02
00 PEGADO				
	502	PEGADO DE SUELA	4.53	4.53
		Total x Depto	4.53	4.53
10 ADORNO "A"				
	600	ADORNO GENERAL	2.92	2.92
	605	ARMAR CAJA	0.34	0.34
		Total x Depto	3.26	3.26
		Total x Estilo	41.5	41.5