

Safe Work Procedure

Description of Work:		Booth Production (Exhibitor) , Size 3 x 3 M				
Location : Jiexpo - Kemayoran HALL D (D3 – 07)		Design :  				
Personal Protective Equipment (PPE) Required (Check the box for required PPE):						
 Gloves	 Face Masks	 Eye Protection (Conditional)	 Welding Mask (Not Needed)	 Appropriate Footwear (Not Needed)	 Hearing Protection	 Protective Clothing
☒	☐	☐	☐	☒	☐	☐
Work Checklist:						
1. PRE-Operation : Preparation at Workshop to build module/partitions booth and others booth's items/parts						
2. Operation (Loading-in at Venue) : Set up/install the booth using proper safety items to minimize the risk						
3. Operation (Loading-out) : Dismantle the Booth using proper safety items to minimize the risk						
The following persons are authorised to operate, supervise and test workers on the equipment /process						
Name:	Title:	Contact Details:				
Ridwan Slamet	Account Executive	0856 1679 547				
Supiyanto	Production Coordinator	0812 1106 2276				