
(a) Factories: Planar-2D / HBMS
STV ratio
2
1.5
1
0.5
0
Dedicated
Shared-4
Shared-2
Shared-8
(b) Cultivation: 2D-Cult / HBMS
STV ratio
6
5
4
3
2
1
0
Dedicated
Ancilla
Rows
Full
1
5
10
20
50
100
Coupling error p'/p