
HBMS: Shared-8 Shared-4 Shared-2 Dedicated
Ising-10
Ising-13
Ising-16
Ising-26
Ising-34
Ising-66
Heis-16
Heis-20
Heis-25
Heis-49
Heis-64
HeisXYZ-5
HeisXYZ-10
HeisXYZ-20
HeisXYZ-30
HeisXYZ-40
Chain-10
Chain-20
Chain-30
Chain-40
Chain-50
SK-10
SK-15
Surface-9
Surface-25
Surface-49
H2
LiH
1
0.1
1
STV ratio (Planar-2D / HBMS)
Factories in HBMS / in Planar-2D