
(a) Factories: Planar-2D / HBMS
STV ratio
3
2.5
2
1.5
1
0.5
0
Dedicated
Shared-2
Shared-4
Shared-8
(b) Cultivation: 2D-Cult / HBMS
STV ratio
10
8
6
4
2
0
Dedicated
Rows
Ancilla
Full
Ising-10
Ising-13
Ising-16
Ising-26
Ising-34
Ising-66*
Heis-16
Heis-20
Heis-25
Heis-49*
Heis-64*
GMean