
(a) Factories: Planar-2D and HBMS
Planar-2D
Dedicated
Shared-2
Shared-4
Shared-8
Timesteps / ideal
1
2
5
10
20
0.5
1
2
5
10
20
(b) Cultivation: 2D-Cult and HBMS
2D-Cult
Dedicated
Rows
Ancilla
Full
Timesteps / ideal
1
2
5
10
20
0.5
1
2
5
10
20
Magic-state supply bound / ideal depth