
HBMS: Shared-16 Shared-8 Shared-4 Shared-2 Dedicated
Ising-10
Ising-13
Ising-16
Ising-26
Ising-34
Ising-66
Heis-16
Heis-20
Heis-25
Heis-49
Heis-64
STV ratio (Planar-2D / HBMS)
1
0.1
0.1
1
Factories in HBMS / in Planar-2D