

Infrared Report

726 Sunnywood Rd
York SC 29745

Date:

9/18/2025

Inspectors Name:

Frank Signa

Customer:

Valorie Redwine

People present at the time of inspection:

Buyer(s), Buyers Agent

Building Type:

Single Family.

Utilities Status:

All utilities on

Outside Temperature (F):

80-90 Degrees

House Occupancy/Limitations:

The home was occupied at the time of inspection. When a home is occupied with furniture, clothing, and other stored items, it can obstruct the view and access to walls, receptacle outlets, under sinks, etc.

Payment Type:

Credit Card Online

GENERAL INFORMATION

This is a visual inspection only and the report is intended only as a **general guide** to help the client make their own evaluation of the overall condition of the home, and is not intended to reflect the value of the premises, nor make any representation as to the advisability of purchase.

THIS REPORT WAS INTENDED TO BE VIEWED IN COLOR.

IMPORTANT - Due to (but not limited to) the findings within the report, a qualified licensed contractor that specializes in the respective fields of the findings listed below should be consulted to further evaluate any and all findings to determine the full extent of any damage(s) and/or to determine if additional repairs are required or deemed necessary, as there may be additional defects that were concealed and/or otherwise unseen at the time of the original inspection. Further evaluation is recommended before the close of escrow on the home, due diligence, and/or contingency period, or whichever comes first, to completely understand the extent of the damage(s) and/or the full extent of the repairs that are needed, required, or deemed necessary by the qualified licensed contractor.



1. INFARED THERMAL IMAGING

DESCRIPTION

INFARED INFORMATION

The purpose of an Infrared thermal inspection is to locate and identify anomalies that result in temperature differences at the time of the inspection. An Infrared thermal inspection can vary significantly due to interior and exterior temperature differences. An infrared camera is not a moisture meter, nor does it "see" moisture.

Thermal Imaging only reads temperature differences. It cannot see through walls. If the surface is the same temperature as the interior of the wall the image will be one color and an anomaly will be undetectable. An anomaly can only be detected if the area is wet or a difference in the temperature can be determined in the other than the surface around it.


This is not an energy audit and to determine if the home meets the government energy saving standards.

ITEMS: INFARED THERMAL IMAGING

1.0 DOORS

☒ COMPONENT WAS INSPECTED AND/OR OPERATED.

Normal or typical conditions viewed at the time of inspection.



1.1 WINDOWS

☒ COMPONENT WAS INSPECTED AND/OR OPERATED.




Normal or typical conditions viewed at the time of inspection.



1.2 WALLS AND CEILINGS

☐ CORRECTION, REPAIR, AND/OR REPLACE IS NEEDED.

Evidence of heating and air loss at the Bonus room




1.3 PLUMBING LINES

☑ COMPONENT WAS INSPECTED AND/OR OPERATED.

1.4 ELECTRICAL PANEL

☑ COMPONENT WAS INSPECTED AND/OR OPERATED.

Performing the function for which intended at the time of inspection.



1.5 ATTIC

☑ COMPONENT WAS INSPECTED AND/OR OPERATED.