



April 19, 2024

Fabian Rudko
DR Horton
8025 Arrowridge Rd
Charlotte, NC 28273

Subject: Truss Issues
443 Preston Rd
Mooresville, NC 28166

Background

It is Universal Professional Solutions No. 29 Inc. (UES) formerly known as SUMMIT Engineering Laboratory, & Testing, Inc. understanding that the above referenced structure is a single-family residential structure.

Concerns

It is UES's understanding that several piggy-back trusses in the attic have gaps at both ends where they meet with the base truss. Each truss/piggy-back truss has a 2x4 scab on one side, nailed with (2) rows of nails spaced approximately 3" o.c.

Recommendations


Based on our on-site observations and review, the trusses are adequate as installed and have adequate bearing on the purlins. No further action is required.

Closing

Please note this is not a comprehensive structural evaluation, this is representative of an evaluation of specific areas and elements as requested by the client. Unless specifically noted above, no other areas were inspected or evaluated.

UES appreciates the opportunity to provide our professional services to you on this project.

Sincerely,
UES



Brian C. Philbrick Jr., P.E.
Senior Engineer
UES Professional Solutions No. 29, Inc. Formerly Known as SUMMIT Engineering Laboratory & Testing, Inc.
NC Certificate of Licensure No. F-1454