

On-site Wastewater Inspection

☐ Pre-Inspection Contract, signed by Client is attached to Inspection

Property Address 435 new salem rd
Street
statesville nc
City St Zip

Client Name: randy cox

Current owner of Record _____

Date of Inspection: _____

3 Advertised number of bedrooms as stated in MLS or as stated in attached sworn statement by owner or owner's representative

_____ Gallons per day for designed system size or number of bedrooms as stated in available local health department information

☒ Inspection shall include any part of the system located more than 5 feet from the primary structure that is a part of the operations permit

☒ Copy of Operations permit from irdell County Environmental Health Attached

☐ Operations permit not available

☐ System requires a certified subsurface water pollution control system operator pursuant to G.S. 90A-44

Current Operator's Name _____

Most recent performance, operation and maintenance reports are ☐ attached ☐ not available

Type of water supply ☒ Well ☐ Public Water ☐ Community Water ☐ Spring

Location of Septic Tank and septic tank details:

16 ft from house or structure

130 ft from well if applicable

na ft from water line if applicable and readily visible

na ft. from property line if said property lines are known

20" distance from finished grade to top of tank or access riser

no Access riser(s) ☐ yes ☒ no Describe _____

yes Tank lids intact ☒ yes ☐ no

yes Tank has baffle wall ☒ yes ☐ no Describe condition of baffle wall: good

yes Inflow to tank is noted as sufficient

no Inflow to tank is noted as insufficient or blocked

no Water level in tank is relative to tank outlet

yes Outlet T is present ☒ yes ☐ no Describe condition of Outlet T: good

no Outlet has filter ☐ yes ☒ no Describe condition of filter: _____

yes Effluent leaves the outlet ☒ yes ☐ no

no Roots present in tank ☐ yes ☒ no Describe extent of roots: _____

no Evidence of tank leakage Describe: _____

no Evidence of non-permitted connections, such as downspouts or sump pumps

yes Connection present from house to tank

yes Connection present from tank to next component

na Percentage of solids in tank

_____ Unable to locate tank. System inspection cannot be completed until tank is located

Date tank was last pumped 3/2/23 ☐ unknown

Client requesting this inspection has been advised that for a complete inspection to be performed the tank needs to be pumped. Client has declined to have the tank pumped at inspection and hereby acknowledges they have so declined.

Client Signature _____ Date _____

Does system have pump tank? ☐ yes (complete blanks below) ☒ no

_____ ft from house or structure
_____ ft from well or spring if applicable
_____ ft from water line if applicable
_____ ft. from property line if property lines are known
_____ ft from septic tank
_____ Distance from finished grade to top of tank or access riser
_____ Access risers in place ☐ yes ☐ no
_____ Describe type of access risers: _____
_____ Describe condition of tank lids _____
Location of control panel: _____
Condition of control panel: _____
_____ Audible and visible alarms (as applicable) work
_____ Pump turns on and effluent is delivered to next component
_____ Unable to operate pump due to lack of electricity at site at
time of inspection

Dispersal field: Type of system: ☒ Conventional ☐ Accepted ☐ Innovative ☐ Experimental ☐ Controlled
Demonstration ☐ Pretreatment; Type of Pretreatment _____

Brief Description of System Type _____

10ft _____ ft. from property line if property lines are known

5ft _____ ft from septic/pump tank

3 _____ # of lines

300 _____ length of lines

no _____ Evidence of past or current surfacing at time of inspection

Briefly describe: _____

no _____ Evidence of traffic over the dispersal field

yes _____ Vegetation, grading and drainage noted that may affect the condition of the system or
system components

yes _____ Effluent is reaching the dispersal field

☐ Conditions present that prevented or hindered the inspection

☐ Adverse conditions present that require repair or subsequent observation or warrants further evaluation by the
local health department. Description of adverse condition: _____

Consequences of the adverse condition: _____

Client should contact _____ County Environmental Health and/or a certified on-site wastewater contractor

Other pertinent facts noted during inspection: down spout on back right corner of house needs to be diverted off of drain field .

couple of low places over drain field that could hold/catch water during rain fall

Inspector Name: mike tansey Certification # 7111

Address 4761 hwy 801 woodleaf

Phone 704-202-6459

No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future
performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation
of system facts in place on date of inspection.

Inspector Signature: Michael Tansey Date 3/2/23