



April 16, 2025

Attention: Gabriel Winebarger
Project: FHA Foundation Inspection for Manufactured Home
110 Amber Ln.
Statesville, NC
Project# 25-196


This is to advise that Darden Engineering Services, PLLC inspected the foundation at the above referenced address. The following items should be addressed for the foundation to be FHA compliant.

1. Add surface bonding cement to all piers that have not been coated. Note different types of surface bonding cement are allowed. The type that is recommended is Sakrete Surface bonding cement. Surface bonding cement must be applied $\frac{1}{4}$ " to $\frac{1}{2}$ " min. in thickness to existing piers.
2. Install 6mil vapor barrier to all exposed ground surfaces.
3. The front porch needs to have a brick reset and grout to prevent a trip hazard.
4. Install fasteners to properly attach the crawl space splash guards.

Note the porches themselves don't affect the structure of the manufactured home as they are not attached to the home. However, it is recommended repairs listed above must be done to receive the FHA compliant letter.

Please let me know if you need additional information.

Sincerely, John C. Darden III PE



Sincerely,
John C. Darden III PE
Darden Engineering Services, PLLC
Firm License #P-1663

PICTURES OF FOUNDATION AND FRONT PORCH STEPS

