

L.D F0,0(R4),R6 L.V V1,0(R1),R6 MUL.V V2, V1, F0 L.V V3,0(R2),R6 ADD.V V4, V2, V3 S.V 0(R2),V4,R6