
(a) Success by task
Shared policy
Sparse reward
Separate policies
Sparse reward
Shared policy
Dense reward
Separate policies
Dense reward
N4
N8
N12
N16
GS
GM
GI
R4
R8
R12
R16
P4
P8
P12
P16
USB
WP
BNC
DS
RJ
100
50
0
Success (%)
(b) Success rate ± standard deviation
98.2 ± 0.986%
81.4 ± 1.732%
17.8 ± 0.010%
78.3 ± 0.573%
100
75
50
25
0
Shared
Sparse reward
Separate
Sparse reward
Shared
Dense reward
Separate
Dense reward