Från Kent Nyman [kent.l.nyman@gmail.com]

Skickat: 2015-01-24 16:43:56

Till: Registrator

Ärende: Medborgarförslag om utvärdering av kollektivtraffik

Jag har försökt bilda mig en uppfattning om hur underlaget för en framtida förbindelse till Värmdö ser ut. Förvisso även underlaget för

tunnelbana från Slussen till Nacka Forum. Vad jag kan se finns inga jäm-förande beräkningar för alternativa färdmedel angivna och därför skulle jag gärna se att t.ex s.k. Skyways/Monorails blev beaktade. Jag skulle kunna argumentera för varför jag tror att det finns anledning att.

ifrågasätta tunnelbana men jag bilägger en utförlig och i mitt tycke den $\,$

mest vederhäftiga länk i detta avseende , Sammanfattningsvis tror jag att en Monorail blir ekonomiskt fördelaktigt på lång och kort sikt, är lättare att anlägga (t.ex. efter/över motorvägen), är mer estetiskt både för betraktaren och resenären, förmodligen förenklar brokonstruktionen över Skurusundet samt är relativt flexibelt vid anläggande av nya bostadsområden och ev ersättning av Saltsjöbanan. Hur hanteras ett sådant här ärende av LOU? Kan ev. aspekter framföras på att en sådan här upphandling skall ske enligt lägsta pris / passagerar-kilometer

Bil;

http://monorails.org/tMspages/MonoVs.html

mvh Kent Nyman Älta

```
Received: from DB3PR07MB204.eurprd07.prod.outlook.com (10.242.132.155) by
AMSPR07MB194.eurprd07.prod.outlook.com (10.242.86.141) with Microsoft SMTP
Server (TLS) id 15.1.59.20 via Mailbox Transport; Sat, 24 Jan 2015 15:44:05
Received: from AM3PR07CA0020.eurprd07.prod.outlook.com (10.141.45.148) by
 DB3PR07MB204.eurprd07.prod.outlook.com (10.242.132.155) with Microsoft SMTP
Server (TLS) id 15.1.65.19; Sat, 24 Jan 2015 15:44:03 +0000
Received: from DB3FF011FD013.protection.gbl (2a01:111:f400:7e04::126) by
AM3PR07CA0020.outlook.office365.com (2a01:111:e400:882c::20) with Microsoft
SMTP Server (TLS) id 15.1.59.20 via Frontend Transport; Sat, 24 Jan 2015
15:44:03 +0000
Received: from mail.nacka.se (158.255.217.108) by
 DB3FF011FD013.mail.protection.outlook.com (10.47.216.187) with Microsoft SMTP
Server (TLS) id 15.1.75.11 via Frontend Transport; Sat, 24 Jan 2015 15:44:03
Received: from smtp205.stejtech.net (213.136.34.155) by
NACEXCHP05.adm.nacka.se (10.10.10.75) with Microsoft SMTP Server (TLS) id
14.3.181.6; Sat, 24 Jan 2015 16:44:02 +0100
X-Spam-Status: No, score=-0.1 tagged above=-1000 required=4.5
       tests=[DKIM SIGNED=0.1, DKIM VALID=-0.1, DKIM VALID AU=-0.1,
       HTML MESSAGE=0.001, SPF_PASS=-0.001] autolearn=disabled
X-Spam-STAY-ID: v=2.0 cv=CsI9gwED c=1 sm=0 a=jPJDawAOAc8A:10 a=xqWC Br6kY4A:10
       a=pGLkceISAAAA:8 a=YNv0rlydsVwA:10 a=j0sZDupOAAAA:8 a=7-MmGDX2WtyGDnjJ1M4A:9
       a=QEXdDO2ut3YA:10 a=wMldoodvbkMA:10 a=Cq8FRzNAN6cu8NeinT4A:9
Received: from mail-lb0-x229.google.com (mail-lb0-x229.google.com
 [IPv6:2a00:1450:4010:c04::229])
                                     (using TLSv1 with cipher ECDHE-RSA-RC4-SHA
 (128/128 bits))
                      (No client certificate requested)
                                                            by smtp205.stejtech.net
 (Postfix) with ESMTPS id AA36E1714057
                                             for <registrator@nacka.se>; Sat, 24 Jan
2015 16:43:56 +0100 (CET)
Received: by mail-lb0-f169.google.com with SMTP id f15so2059324lbj.0
        for <registrator@nacka.se>; Sat, 24 Jan 2015 07:43:56 -0800 (PST)
DKIM-Signature: v=1; a=rsa-sha256; c=relaxed/relaxed;
        d=gmail.com; s=20120113;
        h=mime-version:date:message-id:subject:from:to:content-type;
        bh=0BosZRFherPgh+z9iy6Fs25bbqhBkD3B7xnKHqEC6yQ=;
        b=vYd1sSHJQ5boC8xeJUYZS6GqDkm4jhcJtUC/NrFC03zfhfBGcXedG9kDaINMJhBB0u
         OY8Yr3G3bZkP9gfpEp8IF7/bENDAIw8z1DBwnUuw02SLnh4bS0DzZkRpmD/DIrj9rrwS
         hUAiM8wyDsloqu51E3YfiscoAr3KVTwzJOZoAhXWePbbKbHFKCj/1BxdGi0rm5tVRmG7
         mplQBsyhTqrQe7H5ED5Mad+QRMwFjaWy/YnAqvpNL6b2Z+97k9Z2nLKiih6jEWzJvAdV
         TiDM76RaoFUV3rl6XHAHNCn7HOpq5J3TjlbY/iW95xpLkJeDVmCclj1xuJg41VrQYgFE
         weHQ==
MIME-Version: 1.0
X-Received: by 10.152.28.194 with SMTP id d2mr12854918lah.85.1422114236121;
Sat, 24 Jan 2015 07:43:56 -0800 (PST)
Received: by 10.25.31.83 with HTTP; Sat, 24 Jan 2015 07:43:56 -0800 (PST)
Date: Sat, 24 Jan 2015 16:43:56 +0100
Message-ID: <CAOn9Y53t=YT+cwdMvNG6YWu5NyUzD74 Yp 4JYdovqVdNB8Wjg@mail.gmail.com>
Subject: =?UTF-8?Q?Medborgarf=C3=B6rslag om utv=C3=A4rdering av kollektivtraffi?=
       = ?UTF - 8 ?Q?k? =
From: Kent Nyman <kent.l.nyman@gmail.com>
To: <registrator@nacka.se>
Content-Type: multipart/alternative; boundary="089e0160b420dfc9a3050d67c5ea"
Return-Path: kent.l.nyman@gmail.com
X-OrganizationHeadersPreserved: nacexchp05.adm.nacka.se
X-EOPAttributedMessage: 0
X-MS-Exchange-Organization-MessageDirectionality: Originating
Received-SPF: SoftFail (protection.outlook.com: domain of transitioning
gmail.com discourages use of 158.255.217.108 as permitted sender)
Authentication-Results: spf=softfail (sender IP is 158.255.217.108)
smtp.mailfrom=kent.l.nyman@gmail.com; nacka.mail.onmicrosoft.com; dkim=fail
 (body hash did not verify) header.d=gmail.com;nacka.mail.onmicrosoft.com;
dmarc=fail action=none header.from=gmail.com;
X-Forefront-Antispam-Report:
CIP:158.255.217.108;CTRY:SE;IPV:NLI;EFV:NLI;SFV:NSPM;SFS:(82202001)(15395725005)(105596002
) (110136001) (87936001) (224303003) (19617315012) (450100001) (62966003) (77156002) (61266001) (76
482003) (83322999) (73972006) (15975445007) (63696999) (54356999) (42186005) (50986999) (84326002)
(956001) (2351001) (46102003) (98316002) (92566002) (107886001) (73392002) (106466001) (229853001)
(6806004) (512874002) (224313004) (87572001) (55446002) (19580395003) (93516999) (86362001) (81442
002)(7099025);DIR:INB;SFP:;SCL:1;SRVR:DB3PR07MB204;H:mail.nacka.se;FPR:;SPF:SoftFail;MLV:o
vrnspm; PTR: InfoDomainNonexistent; LANG: sv;
X-CrossPremisesHeadersPromoted: DB3FF011FD013.protection.gbl
```

```
X-CrossPremisesHeadersFiltered: DB3FF011FD013.protection.gbl
X-MS-Exchange-Organization-Network-Message-Id: ac871eaa-0927-45ce-f63b-08d20603b721
X-DkimResult-Test: Failed
X-DmarcAction-Test: None
X-DmarcStatus-Test: Failed
X-Microsoft-Antispam: UriScan:;
X-Microsoft-Antispam: BCL:0;PCL:0;RULEID:(3002015)(3005004)(3004004);SRVR:DB3PR07MB204;
X-MS-Exchange-Organization-AVStamp-Service: 1.0
X-Exchange-Antispam-Report-Test: UriScan:;
X-Exchange-Antispam-Report-CFA-Test: BCL:0;PCL:0;RULEID:(601004);SRVR:DB3PR07MB204;
X-MS-Exchange-Organization-SCL: 1
X-Exchange-Antispam-Report-CFA-Test: BCL:0;PCL:0;RULEID:;SRVR:DB3PR07MB204;
X-MS-Exchange-CrossTenant-OriginalArrivalTime: 24 Jan 2015 15:44:03.3047
 (UTC)
X-MS-Exchange-CrossTenant-Id: 85fldefl-344e-41f0-b8fe-137f2800f31a
X-MS-Exchange-CrossTenant-OriginalAttributedTenantConnectingIp: TenantId=85f1def1-344e-
41f0-b8fe-137f2800f31a; Ip=[158.255.217.108]
X-MS-Exchange-CrossTenant-FromEntityHeader: HybridOnPrem
\verb|X-MS-Exchange-Transport-CrossTenantHeadersStamped: DB3PR07MB204|\\
X-MS-Exchange-Organization-AuthSource: nacexchp05.adm.nacka.se
X-MS-Exchange-Organization-AuthAs: Anonymous
X-OriginatorOrg: nacka.onmicrosoft.com
X-MS-Exchange-Transport-EndToEndLatency: 00:00:02.5241690
```