




- 1. Table of Contents (This Page) Created on Wed Jan 29 14:36:37 2014
- 2. top
- 3. bottom
- 4. plated-drill
- 5. componentmask
- 6. soldermask
- 7. topsilk
- 8. bottomsilk
- 9. toppaste
- 10. topassembly
- 11. bottomassembly
- 12. fab



























There are 4 different drill sizes used in this layout, 302 holes total

| Symbol | Diam. (Inch) | Count | Plated? |  |
|--------|--------------|-------|---------|--|
| ¥      | 0.020        | 185   | YES     | Title: (unknown) - Fabrication Drawing                           |
| +      | 0.038        | 95    | YES     | Author: root   |
| ×      | 0.059        | 10    | YES     | Date: Wed 29 Jan 2014 07:36:37 PM GMT UTC                        |
| •      | 0.125        | 12    | YES     | Maximum Dimensions: 4000.000000 mils wide. 4000.000000 mils high |



Board outline is the centerline of this 8.000000 mil rectangle = 0,0 to 4000.000000,4000.000000 mils