
Quiz 8

Cody Frisby

10/28/2016

7.1 First a plot at P chart using the observed data.



We can observe that there is one point that is outside the control limits.

Excluding this one point and then calculating our center, UCL, and LCL the reccomended points are

UCL = 0.1213023

center = 0.0536842

LCL=0