





Technical Bulletin
Important – Please Read!!

TBA0028 Revision Date: 5/31/2013

The replacement alternator in the box may look different than the original... but the unit that you have purchased meets or exceeds the Manufacturer's specifications for correct vehicle performance.

Hitachi Version

Mitsubishi Version



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST




Avertissement!
Advertencia!

TBA0028 Revision Date: 5/31/2013

L'alternateur de rechange que vous trouverez dans la boîte peut paraître différent de l'original mais la pièce que vous avez achetée répond aux spécifications du fabricant, ou les dépasse, pour un fonctionnement correct du véhicule.


El alternador de repuesto en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.

Version Hitachi
Versión Hitachi



Cosse ouverte factice
Terminal muerto

Version Mitsubishi
Versión Mitsubishi



Aucune cosse
No terminal



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST