





Technical Bulletin Important – Please Read!!

TBS0017 Revision Date: 2/08/05

The replacement starter in the box may look different than the original... but the unit that you have purchased meets or exceeds the manufacturer's specifications for correct vehicle performance.



Hitachi 80mm Case
Version Hitachi, boîtier
de 80 mm
Caja Hitachi de 80 mm



Hitachi 90mm Case
Version Hitachi, boîtier
de 90 mm
Caja Hitachi de 90 mm



Mitsubishi Version
Version Mitsubishi
Versión Mitsubishi



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST



Avertissement!
Advertencia!


TBS0017 Revision Date: 2/08/05

Le démarreur de rechange que vous trouverez dans la boîte peut paraître différent de l'original mais la pièce que vous avez achetée répond aux spécifications du fabricant, ou les dépasse, pour un fonctionnement correct du véhicule.

El motor de arranque en la caja puede verse diferente al original... pero la unidad que compro cumple o supera las especificaciones del fabricante para el funcionamiento correcto del vehículo.



Hitachi 80mm Case
Version Hitachi, boîtier
de 80 mm
Caja Hitachi de 80 mm



Hitachi 90mm Case
Version Hitachi, boîtier
de 90 mm
Caja Hitachi de 90 mm



Mitsubishi Version
Version Mitsubishi
Versión Mitsubishi



Technical Support Hotline: 800-228-9672
M-F 5:30AM-5:00PM PST, Sat 6:00AM-2:30PM PST