Power Supply

Z
Ground


Neurtal
S

Hot


Creation Station/ TinyG Mounting Drill Holes

Cut here and line up with power supply position.

Drill at red dots All holes are 5/64" (2mm)



Spindle Controller Board



Caution:

Make sure "do not scale" or "print scale: 100%" is selected when printing!

Cut here and line up with part B.

Opening