

# JOHN R. BELL & ASSOCIATES

JOHN R. BELL M.Inst.A.E.A. M.F.I.E.A.

Motor Claims Assessor, Loss Adjuster & Negotiator

72 Rattle Road, Westham, Pevensey, East Sussex BN24 5DJ

Telephone 01323 766206 e-mail [info@johnrbell.com](mailto:info@johnrbell.com) Mobile 07702 246945





DATE: 21/07/26 MY REF: 9610 CLAIM NO: AMA/46733/1 CLIENT: A COOPER

|                                                                          |                                 |                         |
|--------------------------------------------------------------------------|---------------------------------|-------------------------|
| Repairers<br><b>COUNTRYSIDE AUTO REFINISHING<br/>SERVICES LTD BODIAM</b> | Inspected on<br><b>21/07/26</b> | At<br><b>VIA IMAGES</b> |
|--------------------------------------------------------------------------|---------------------------------|-------------------------|

| VEHICLE DETAILS      |                         |                                  |                                         |                                |                                         |
|----------------------|-------------------------|----------------------------------|-----------------------------------------|--------------------------------|-----------------------------------------|
| Year<br><b>08/25</b> | Make<br><b>BMW</b>      | CC<br><b>2998</b>                | Model<br><b>X5 XDRIVE E50 M SPORT A</b> |                                | Reg.No.<br><b>AC20 PER</b>              |
| Extras/Modifications | Mileage<br><b>23144</b> | Tax Expiry<br><b>07/27</b>       | Tread on tyres - mms.                   |                                | Chassis No.<br><b>WBA42EU0409091107</b> |
|                      |                         |                                  | NSF 5                                   | NSR 5                          |                                         |
|                      |                         |                                  | OSF 5                                   | OSR 5                          |                                         |
| Static test          |                         | Paintwork Colour                 |                                         | Overall Pre-Accident Condition |                                         |
| Footbrake            | <b>IN GOOD ORDER</b>    | <b>GREY 3 STAGE<br/>METALLIC</b> |                                         | <b>VERY GOOD</b>               |                                         |
| Handbrake            |                         |                                  |                                         |                                |                                         |
| Steering             |                         |                                  |                                         |                                |                                         |

| <u>Guide Values</u> |   |                        |   |                  |         | <u>My estimated retail value</u> |
|---------------------|---|------------------------|---|------------------|---------|----------------------------------|
| <u>Glass's</u>      |   | <u>Glassnet Values</u> |   | <u>Other CAP</u> |         | £                                |
| Retail              | £ | Dealer Retail          | £ | Retail           | £       | 65000                            |
| Trade               | £ | Dealer Trade           | £ | Trade            | £ 63112 |                                  |

Direction of Impact



|                  |              |                          |
|------------------|--------------|--------------------------|
| Degree of Damage | <b>Light</b> | Roadworthy/Unroadworthy? |
| Legal to Drive?  | <b>Yes</b>   | Roadworthy               |

## COST OF REPAIRS - DAMAGE DETAILS OVERLEAF


Discussed in detail and agreed Labour £944.53, parts incl auxiliary work £96, Software £95, EPA £22, Paint materials £663.85. AUDATEX Computer generated estimate.

|                                                                                     |            |                                                                                    |
|-------------------------------------------------------------------------------------|------------|------------------------------------------------------------------------------------|
| Approx. Repair time                                                                 | <b>2-3</b> | days. Excluding weekends and subject to availability of all parts. Hourly Rate: 92 |
| Provisional reserve figure for repairs. Subject to MLP & further checking. Inc. VAT |            | <b>£ 2195</b>                                                                      |

## GENERAL REMARKS

This report relates to the damage sustained to vehicle (AC20 PER) in a road traffic accident. Qdos Accident Assistance commissioned this report on behalf of Ashley Cooper on 08/07/26.

I believe that the facts I have stated in this report are true and that the opinions I have expressed are correct. I understand my duty as an independent engineer and have complied with that duty. I now enclose a note of my fee.

  
John R. Bell M.Inst.A.E.A. M.F.I.E.A.

| Vehicle component   | Damage sustained to | Action - RN - RP, etc. |
|---------------------|---------------------|------------------------|
| Chassis             |                     |                        |
| Sub Frames          |                     |                        |
| Radiator Grill      |                     |                        |
| Radiator            |                     |                        |
| Suspension          |                     |                        |
| Steering            |                     |                        |
| Engine              |                     |                        |
| Gearbox             |                     |                        |
| Transmission        |                     |                        |
| Rear Axle           |                     |                        |
| Rear Suspension     |                     |                        |
| Wheels              |                     |                        |
| Wings OSF           |                     |                        |
| Wings NSF           |                     |                        |
| Wings OSR           |                     |                        |
| Wings NSR           |                     |                        |
| Doors OSF           |                     |                        |
| Doors OSR           |                     |                        |
| Doors NSF           |                     |                        |
| Doors NSR           |                     |                        |
| Door Sills          |                     |                        |
| Door Pillars        |                     |                        |
| Bonnet              |                     |                        |
| Front Panel         |                     |                        |
| Inner Wing OS       |                     |                        |
| Inner Wing NS       |                     |                        |
| Rear Panel          |                     |                        |
| Boot Floor          |                     |                        |
| Boot Lid            |                     |                        |
| Tailgate            |                     |                        |
| Roof Panel          |                     |                        |
| Bodyshell           |                     |                        |
| Bumper Front        |                     |                        |
| Bumper Rear         | Cover assy R/Refit  | Repair                 |
| OS Headlamps        |                     |                        |
| NS Headlamps        |                     |                        |
| Front OS S/Flasher  |                     |                        |
| Front NS S/Flasher  |                     |                        |
| Rear OS S/Flasher   |                     | R/Refit                |
| Rear NS S/Flasher   |                     | R/Refit                |
| Fog Lamps           |                     |                        |
| Spot Lamps          |                     |                        |
| Spoilers            |                     |                        |
| OS Mouldings        |                     |                        |
| NS Mouldings        |                     |                        |
| <b>Sundry Items</b> |                     |                        |
| Rear lower bumper   | Difuser             | Repair                 |
| Rear undershield    |                     | Renew                  |
| Rear bumper         | Trim                | r/refit                |
| Rear bumper         | Support             | TBC                    |
| Software            |                     | Reset                  |
| Other fittings      |                     | r/refit as necessary   |
|                     |                     |                        |





# JOHN R. BELL & ASSOCIATES

**JOHN R. BELL** M.Inst.A.E.A. M.F.I.E.A.

Motor Claims Assessor, Loss Adjuster & Negotiator

**72 Rattle Road, Westham, Pevensey, East Sussex BN24 5DJ**

Telephone 01323 766206 e-mail [info@johnrbell.com](mailto:info@johnrbell.com) Mobile 07702 246945

**DATE: 21/07/2026 MY REF: 9610 CLAIM NO: AMA/46733/1CLIENT: A COOPER**

Mr A Cooper  
Prawles Cottages  
1 Shoreham Lane  
Ewhurst Green  
Robertsbridge  
East Sussex  
TN2 5RG

To taking your instructions; inspecting vehicle; discussing repairs and agreeing figures; advising  
you our findings, as per our report of today's date.

**Fee:**

**£110.00**

**Please make cheques payable to John R. Bell**