

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: ECO/35367/1

Date: 4 March 2025

Dear Sirs

Our Client: QDOS Accident Assistance
Our Client's Vehicle: BMW X1 SDRIVE 20I M SPORT MHEV A
Registration: YH74LXL
Date of Accident: 27 February 2025

ENGINEER NOTIFICATION

CLIENT DETAILS

Vehicle Details

Client's Vehicle: BMW X1 SDRIVE 20I M
SPORT MHEV A
Vehicle Registration: YH74LXL
Accident Date: 27/02/2025

Home Tel:
Work Tel:
Mobile:

REPAIRER DETAILS

Tel:
Fax:
Email:
Engineer to Estimate Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Driveable

Please could you check the damage for consistency with the following accident circumstances?

Our client's car was parked, unattended for a few hours on Sommerfield Road, Birmingham. This road is a single lane road allowing for traffic flow in either direction with roadside parking. Your insured, in their car while pulling out from a parked position behind our client's vehicle failed to maintain a safe distance, which resulted in a collision with the rear of our client's vehicle. Your insured knocked on our client's door to exchange details.

Damage Area – Rear: Light, scuffed and scratched

Pre-existing Damage:	no
TP Vehicle:	PEUGEOT 5008 ACTIVE HDI
TP Registration:	KP62OWV
TP Representative Name:	Liverpool Victoria

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully