

Accident Date: Tue Jul 07 2026

Submission date: Tue Jul 07 2026

Case ID: 24da87ec-b765-4986-8cd9-c088dd091d53

Case Details

Initial repair estimate: £1,139.78 (excluding tax)

Vehicle Information

Producer	Toyota
Model	Prius +
Type	-
Year of Production	2020
VIN	JTDZS3EU50J053933
Registration Number	AF20HJG
Registration Date	-
Mileage	73,220
Vehicle Value	£12,435.00

Repair Summary

Remove & Install	-
Panel Repair Hours	3.2 hours @ £65.00/hour
Paint Hours	1.3 hours @ £65.00/hour
Part Costs	£233.88
Paint Material Costs	£421.90
Additional Costs	£354.00

Preliminary AI Estimate

Panel	Operation	Part Number	Producer	Supplier	Unit cost	Qty	Hours	Paint Material	Totals (£)
Main operations									
Rear bumper							2.0		785.78
Rear bumper	Replace	5215947912			233.88	1	2.0	421.90	785.78
Total cost (£)									785.78

Additional operation	Qty	Unit cost	Labour Hour	Total cost (£)
Car Care Kit	1	6.50	-	6.50
Paint Preparation	1	0.00	1.7	110.50
Pre Repair Diagnostics	1	150.00	-	150.00
EPA	1	15.00	-	15.00
Tech Data and Methods	1	20.00	-	20.00
Check and Clean	1	0.00	0.5	32.50
Road Test	1	0.00	0.3	19.50
Total cost (£)				354.00

Totals	Rate	Hours	Totals (£)
Part			233.88
Part cost	-	-	233.88
Labour			292.50
Paint labour	£65.00 / hr	1.3	84.50
Body labour	£65.00 / hr	3.2	208.00
Other costs			613.40
Paint material	-	-	421.90
Other costs	-	-	191.50
Total excluding tax			1,139.78
Tax	20%		227.96
Total including tax			1,367.74

Submitted Vehicle Images

