

Mr Keith McDougall
32 Windsor Grove
Morecambe
LA
Morecambe
LA4 4LP

Date: 12/06/2026
Our Ref: 00037752/JEFFP
Your Ref: EHR102814 \ 24312N82418

To the Court
REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Keith McDougall**

We refer to your instructions received on **06 June 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	SEAT IBIZA XCELLENCE TSI		Colour:	Red	Speedo:	49186	Miles
Reg No:	MJ73XTB	Registered:	Nov 2023	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	VSSZZKJ5RR021571	MOT Exp:		R/H/F Tyre	6	R/H/R Tyre	6
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2023			Spare Tyre	
Brakes:	Not Known	Tax Exp:				Not Know	
Steering:	Not Known	Fuel:	Petrol			Centre Belt	
Extras:	Not Seen	C.C.:	999			Not Tested	
Air Bags Deployed:	Not Known	BHP:	108.	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Collision/Impact	Incident:	05/06/2026	L/H/F Tyre	6	L/H/R Tyre	6
Vehicle Value: £13,313.00		Repair Cost: £7,230.65 inc VAT		(54.31% of PAV)		Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand rear bumper, moderate collision/impact to the right hand rear boot, and moderate collision/impact to the right hand rear quarter panel

VEHICLE HISTORY CHECK

12/06/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Spoiler, L/R Sensor Bracket, R/R Sensor Bracket, Rr Ctr Sensor Brkt, Primer, Badge Model, Cutting Filament, L/S Window Bond Kit, R/S Window Bond Kit, Cleaning Solution, L/R S-Window Primer, R/R S-Window Primer, L/Side Wdw Activator, R/Side Wdw Activator, Sundry Parts

Repairable parts:-Lower Tailgate, Panel System

Repaint only parts:-Description, Rear Bumper New Part Paint K1r, Lower Tailgate Repair Painting <50%, Preparation For Pre-Painting



Specialist/Sundry charges:-Corrosion Protection, Bs10125 Compliance, Glass Lifting Tape, Aries Compliance, Panel Sundries, Adas Methods, Wheel Alignment, E.P.A. Charge, Tech Data + Methods, Car Care Kit, Adas Reset

Blend only parts:-Left Sill Panel Cpl Surface Paint, Right Sill Panel Cpl surface Paint, L/Out/Upp A-Pillar Surface Paint, R/Out/Upp A-Pillar Surface Paint, L/Outer Roof Frame Surface Paint, R/Outer Roof Frame Surface Paint, L/R Side Panel Surface Paint, R/R Side Panel Surface Paint, Fuel Filler Flap Surface Paint Plast., Mask Rear Screen Surface Paint, Mask Front Screen X2 surface Paint, Mask Roof Aperture x2 surface Paint, De Nib & Polish Surface Paint

Remove And Refit parts:-Description, L/Wing Trim, R/Wing Trim, Left Rear Wheelhouse Shell, Right Rear Wheelhouse Shell, Remove And Refit L/Side Panel Parts, Remove And Refit L/Side Panel Parts, Renew Type Badge, Tailgate Handle, Tailgate Trim, Both Rear Lamps, Rear Bumper, Renew Rear Bumper Cover, L/Side Window, R/Side Window, Rear Bumper Drill, Fuel Flap, Rear Wheel (Wheels), Aerial Telescope, Pre & Post System Diagnostics, Corr. Prot. Ext. To 1St Panel

Parts to check:-Rear Bumper Support, R/R Lamp, R/R Lamp Panel, Adas Iir, Wash And Vac, Vehicle Shutdown, Pre Clean, And Road Test, And Quality Control, Adas Roadtest

COST OF REPAIRS

The repairers, Smartxpress Paint and Body Ltd (Tel. 01253350227), have compiled an estimate in the sum of £2,142.00 plus parts at manufacturer's list prices plus £1,605.55 for paint and materials plus £602.09 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £2,976.43. The labour charge is based on 35.74 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £1,605.55. The cost of the necessary replacement parts will be approximately £801.20, the specialist/sundry charges will be £642.36, the VAT liability on this repair will amount to some £1,205.11 giving a total repair cost of £7,230.65 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/11/2023. The corresponding Cazana Guide (model code: 8469917) adjusted retail value for vehicles of this type and age in the June 2026 guide is £13,313.00 at 49186 Miles, trade value is £11,849.00 and mid value is £12,581.00. We place the pre-accident value of this particular vehicle at £13,313.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £7,250.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 12th June 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 8 to 9 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Damage caused rendered the vehicle unroadworthy.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A handwritten signature in dark ink, appearing to read "JP", followed by a period.

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors