

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: SAB/46346/1

Date: 26 June 2026

Dear Sirs

Our Client: Miss Sammy-Jo Wilson
Our Client's Vehicle: NISSAN NOTE ACENTA
Registration: SM13JOX
Date of Accident: 22 June 2026

ENGINEER NOTIFICATION (REPORT + AUDIT REPORT)

CLIENT DETAILS

Miss Sammy-Jo Wilson
25 Southgate
Middlesbrough
TS6 8HU

Vehicle Details

Client's Vehicle: NISSAN NOTE ACENTA
Vehicle Registration: SM13JOX
Accident Date: 22/06/2026

Home Tel:
Work Tel:
Mobile: 07598092010

REPAIRER DETAILS

Tel:
Fax:
Email:
Engineer to Estimate Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Driveable

Please could you check the damage for consistency with the following accident circumstances?

Our client was stationary in their car at traffic lights on Redcar Lane, Redcar, for approximately a few seconds. This is a single-lane road with traffic travelling in both directions. Your insured, who was approaching in their car from behind, failed to apply their brakes in time and collided with the rear of our client's vehicle. As a result of the impact, our client's vehicle sustained damage to the rear boot area.

Damage Area – Rear: Light - two dent by boot handel and piece of the boot flaked off

Pre-existing Damage: offside mech

TP Vehicle: PEUGEOT 5008 GT MHEV AUTO

TP Registration: NX26TZU

TP Representative Name: UKI (Formerly NIG)

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully