

New inspection request for Collision Engineers (51030)

16 Jun 2026

AX Reference : **1070571**
Inspection &
Report Due on : **18/06/2026**

Engineer Instructions

Verbal authority to be provided on the day of inspection. If this cannot be done for any reason, please contact the Credit Repair team on 01675 432266 or by email on CreditRepair_TeamInbox@ax-uk.com

Client Details

Name: **Mr Hamid Reza Azod Azad**
VRM: **SC21VMR**
Vehicle: **TOYOTA COROLLA ICON HEV CVT**
Accident Date: **09 Jun 2026**
Postcode: **G52 4BT**
VAT Registered: **No**
Fault Insurer: **ESURE PROTOCOL**

Repair Notes: **rear wheel hit, wheel arch catching on tyre, gap in rear door**
Accident Circumstances: **Our client correctly proceeding on Craigendmuir Drive when a third party has pulled out from parked position, on our clients left, colliding with our clients rear nearside. Details exchanged.**

Bodyshop Details

Name: **Undentit Ltd**
Address: **15-17 Scotland Street**

Glasgow
Postcode: **G5 8NB**
Telephone: **07402749141**

Third Party Details

VRM: **DG72FSX**
Make/Model: **AUDI/Q5 S LINE 40 TDI MHEV QUA**