

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Samantha Wilson : 28/04/2026


In accordance with your instructions received on 01/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 05/05/2026. Vehicle located at Forwood Road, Wirral, Merseyside, CH627BT. Our findings are as detailed below:

Make	MERCEDES-BENZ	Registration	LS690YW
Model	AMG A 35 4MATIC PRE	Status	T/Loss
Category	S	Salvage Value	£2,487.40
Repair Cost	£23,024.36	Legal Status	Unroadworthy
Engineer Value	£24,874.00	Impact Magnitude	Heavy



Impact Area





Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026

NATURE OF INCIDENT

The vehicle has suffered heavy collision/impact damage to the right hand side, and moderate collision/impact to the left hand side.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside and impacted wheel/tyre and suspension.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £22,386.60 which represents the pre-accident engineer value of the vehicle of £24,874.00 less the value of the salvage of £2,487.40.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £2,487.40. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£24,874.00
Trade Value	£21,640.00
Engineer's Value	£24,874.00
Glass's Code	
VIN	WDD1770512N113903
Odometer	43214
Engine	1991
Fuel	Petrol
Extras	
Condition	Good



Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026

Main new parts required

Right Rear Door Shell
Right Rear Door Lower Hinge
Right Rear Door Window Regulator (Electric)
Right Rear Door Lock with Central Locking Sys
Right Rear Door Insulation
Right Rear Side Panel Bonding Kit
Right Rear Wheelarch with Inner Side Panel
Rear Suspension Arms (Both)
Right Rear Suspension Arm
Left Rear Suspension Stay Bar
Left Rear Suspension Tie Rod (Pinching)
Right Rear Suspension Anti-Roll Bar Linkage
Right Rear Shock Absorber
Right Rear Steering Knuckle
Right Rear Wheel Hub with Bearing
Left Rear Wheel (Aluminium)
Right Rear Door Trim Support Kit
Right Rear Door Trim Screw

Right Rear Door Upper Hinge
Right Rear Door Lock Plate
Right Rear Door Window Regulator Motor
Right Rear Door Striker
Right Rear Side Panel
Right Rear Wheelarch, Inner
Right Side Panel Liner
Left Rear Suspension Arm
Right Rear Suspension Longitudinal Arm
Right Rear Suspension Stay Bar
Right Rear Suspension Tie Rod (Pinching)
Right Rear Suspension Spring
Left Rear Steering Knuckle
Left Rear Wheel Hub with Bearing
Left Rear Driveshaft Complete
Right Rear Wheel (Aluminium)
Right Rear Door Trim Clip


Repairs required

Rear Bumper Lining

Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Corrosion Protection
De-nib
NSR tyre
Wheel Alignment check/toe-adjust
Paint Right Front Door, Complete
Paint Right Rear Door Outer Handle
Paint Right Rear Side Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Corrosion Protection additional panel
Jig, clamp and pull
OSR tyre
Paint Right A-Post, Upper
Paint Right Rear Door, Complete
Paint Right Roof Panel, Side
Paint Rear Bumper k/e
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)



Our Ref: dfd26088


Your Ref: RJP/81517

Date: 06/05/2026

Repair Cost Calculations

Hours	67.90
Hourly Rate	£103.06
Total Labour	£6,997.77
Parts	£10,270.90
Paint/Materials	£1,106.92
Specialist/Other	£811.38
Sub total	£19,186.97
Vat	£3,837.39
Total Estimated Cost	£23,024.36






Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026








Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026






Our Ref: dfd26088
Your Ref: RJP/81517

Date: 06/05/2026






Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026






Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026





Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026










**COLLISION
ENGINEERS**


INDEPENDENT AUTOMOTIVE EXPERTS

Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026





Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - M.Inst.IAEA

engineers@collisionengineers.co.uk



Our Ref: dfd26088

Your Ref: RJP/81517

Date: 06/05/2026

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

Fee Note

LS690YW.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £180.00

Sub Total: £180.00

VAT: £36.00

Total Due: £216.00

Payment

Please make cheques payable to Collision Engineers and quote reference dfd26088.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Davison Flynn Duke confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10