

Calculation

Client:**Make / Model / Type:** Mercedes-Benz / C-Class 205 / C 300h (s/s) Aut. 2016MY [4.2015]**Glass's national Code** 208953001**Vehicle Registration Number:** OY65VZM**VIN:** WDD2050122F258691**Date:** 19.6.2026**Paint system:** AZT**Hail damage logic:** ETG**Labour time unit:** 1 Hour**Currency:** £**Database version:** 2026.03.

Body		Repair type	Labour time	Overlap-time	Labour costs	Material costs
88993001	Roof Drip Moulding (L)	UI	0.10		8.33	0.00
72729001	Rear Door Outer Handle (L)	UI	0.00	0.10		0.00
	Annotation (price): Last known price					
NN	Rear Bumper Lining	R	2.00		166.56	0.00
	Selected criteria: Automatic Parking System Exterior Equipment AMG Line					
NN	Rear Bumper Side Air Grille (L)	UI	0.10	1.10	8.33	0.00
	Annotation (time): Time includes remove and reinstall of bumper					
NN	Rear Bumper Side Air Grille (R)	UI	0.10	1.10	8.33	0.00
	Annotation (time): Time includes remove and reinstall of bumper					
NN	Rear Bumper Cover	UI	1.40		116.59	0.00
	Selected criteria: Exterior Equipment AMG Line					
	Annotation (time): Time includes remove and reinstall of bumper					
NN	Rear Bumper Spoiler	UI	0.00	1.40		0.00
	Annotation (time): Time includes remove and reinstall of bumper					
54107301	Rear Bumper Outer Side Distance-Sensor (L)	RP	0.20	1.10	16.66	54.00
	Annotation (price): Last known price					
	Annotation (time): Time includes remove and reinstall of bumper					
NN	Rear Side Panel (L)	R	4.00		333.12	0.00
88697801	Side Panel Liner (L)	RP	0.20	0.20	16.66	61.00

Labour costs**674.57****Material costs****115.00****Total Body****£ 789.57**

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
60420401	Rear Door Strip & Set-Up for Painting (L)	UI	1.30		108.26	0.00
72847102	Rear Door Weatherstrip (L)					
72526101EET	Rear Door Rear Window Guide Rail (L)					
72696501	Rear Door Protection Trim (L)					
72696901	Rear Door Outer Window Channel Strip (L)					
72729001	Rear Door Outer Handle (L)					
54798902	Disconnect/Conn Earth Cable to Battery					
72642001	Rear Door Trim Panel (L)					
72668601	Rear Door Trim Upper Panel (L)					
60459301	Rear Side Panel Strip & Set-Up for Paint (L)	UI	0.10	0.50	8.33	0.00
NN	.Assessment Damage	EC	0.00			176.96 F

	Appraisal Charge				
NN	.Environmental Charge	EC	0.00		31.23 F
NN	.Pre repair cleaning charge	EC	0.50	41.64	0.00 F
NN	.QC & Road Test	EC	1.00	83.28	0.00 F
NN	.Sundries	EC	0.00		20.00 F
NN	.System Diagnostic Check (Post Repair)	EC	1.00	83.28	0.00 F
NN	.System Diagnostic Check (Pre Repair)	EC	1.00	83.28	0.00 F
NN	.Vehicle Care Kit	EC	0.00		10.41 F
NN	.Wash/Clean	EC	1.00	83.28	0.00 F
NN	Alloy Wheel Refurbish (LB)	EC	0.00		110.35 F
NN	Electric / hybrid risk assessment	EC	0.50	41.64	0.00 F
NN	Electric / hybrid shutdown and power up	EC	3.00	249.84	0.00 F
NN	Hybrid vehicle full charge	EC	0.00		20.82 F
NN	Miracle Pull	EC	1.50	124.92	0.00 F
NN	NSR tyre	EC	0.00		175.00 F
NN	Wheel Alignment (check)	EC	0.00		112.42 F
NN	.Yard Charge	EC	1.00	83.28	0.00 F

Labour costs

991.03

Material costs

657.19

Total Auxiliary work

£ 1,648.22

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
A-Post, Upper (L)	200	B	0.40	33.31	14.70
Rear Door, Complete K (L)	200	B	0.70	58.30	132.00
Annotation (price) Part made from aluminium					
Rear Door Outer Handle (L)	200	B	0.30	24.98	3.80
Roof Panel, Side (L)	200	B	0.40	33.31	31.20
Rear Side Panel, Complete K (L)	200	III	1.40	116.59	153.30
Rear Bumper k/e	200	K2	1.00	83.28	221.80
Rear Bumper Distance-Sensor (L)	200	K1R	0.10	8.33	1.08
Prep. metal (on vehicle without pre-painting)	200		1.70	141.58	114.68
Prep. synthetics (combined-operation work)	200		0.50	41.64	44.68
Colour mixing (1)			0.30	24.98	0.00
Sample colour creation (1)			0.30	24.98	11.06

Labour costs

591.29

Material costs

728.30

Total Paint

£ 1,319.59

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	83.28	8.10	674.57	115.00
Auxiliary work	83.28	11.90	991.03	657.19
Paint	83.28	7.10	591.29	728.30

Total Labour

27.10

2,256.89

Total Material

1,500.49

Repair costs excl. VAT

3,757.38

VAT (20.00 %)

751.48

Repair costs incl. VAT

£ 4,508.86

Part name	Part no.	Previous part no.	Material costs
Rear Bumper Outer Side	00090555049999		54.00

Distance-Sensor		61.00
Side Panel Liner	2056900730	
Total Parts		£ 115.00

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Roof Drip Moulding	88993001
Rear Door Outer Handle	72729001
Rear Bumper Lining	
Rear Bumper Side Air Grille	
Rear Bumper Side Air Grille	
Rear Bumper Cover	
Rear Bumper Spoiler	
Rear Bumper Outer Side	54107301+88880201
Distance-Sensor	
Rear Side Panel	
Side Panel Liner	88697801
Rear Door Strip & Set-Up for Painting	60420401+54798902
Rear Side Panel Strip & Set-Up for Paint	60459301+60301801
.Assessment Damage Appraisal Charge	
.Environmental Charge	
.Pre repair cleaning charge	
.QC & Road Test	
.Sundries	
.System Diagnostic Check (Post Repair)	
.System Diagnostic Check (Pre Repair)	
.Vehicle Care Kit	
.Wash/Clean	
Alloy Wheel Refurbish	
Electric / hybrid risk assessment	
Electric / hybrid shutdown and power up	
Hybrid vehicle full charge	
Miracle Pull	
NSR tyre	
Wheel Alignment (check)	
.Yard Charge	

Abbreviations	Description
F	User defined operations
L	LEFT
R	RIGHT
LB	LEFT REAR
UI	Uninstall and install
R	Repair
RP	Replace
EC	Surcharge
NN	No part number

Paint type	Paint level, Procedure, Method
B	Adjacent Panel Blend
200	2 Coat
III	Repair up to 50%
K2	Surface spraying
K1R	Part priming/part raw

Selected criteria

Additional Fields

Paint material index	100.000 %
Part index	100.000 %

Glass's does not take responsibility for accuracy and completeness of data originating from vehicle manufacturers.