

Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

FAO The Court
C/o QDOS Assistance
3rd Floor, Crown House
Manchester Road
Wilmslow
SK91BH

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Mrs Karin Solomons: 25/04/2026


In accordance with your instructions received on 07/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 18/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	TESLA	Registration	LD710GY
Model	MODEL 3 LONG RANGE	Status	Repair
Category		Salvage Value	
Repair Cost	£10,002.22	Legal Status	Unroadworthy
Engineer Value	£15,700.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

Please note the vehicle is unroadworthy due to the possible wheel, suspension and tyre damage and the NSR door is compromised and not sealing.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE


We consider that a repair reserve of £10,025.00 would be reasonable on this occasion.

REPAIR DURATION

We consider that this repair will take some 7 to 8 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£15,700.00
Glass's Code	
VIN	LRW3F7EK7MC321713
Odometer	44097
Engine	0
Fuel	Electric
Extras	Not Seen
Condition	Good



Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

Main new parts required


L/R Door
Rr Scrn Frt Up Seal
Rear Screen Bond Kit
Rear Screen Harness
L/R Side Panel Cpl
Blind Rivet
Blind Rivet
Rivet Set C 5X7 H4
L/R Wdw Adhesive Kit
L/R Wheel Cover
Sound Pad Small
Sundry Parts

L/R Door Seal
Rear Screen Lwr Seal
Rear Screen Primer
Rear Screen Harness
Lh Panel Repair Kit
Short Rivet 4.8Mm
Blind Rivet
Structure Adhesive
L/R S-Window Primer
Bead Sealer
Heavy Stone Chip

Additional operations

Check Wash And Vac
Paint L/R Side Panel Cpl New Part Painting
Blend L/R Sill Pr2 Surface Paint
Blend L/Roof Rail Surface Paint
Blend Screen Mask Frt Surface Paint
Paint Open Apperture X1 Detail Mask
E.P.A. Charge
Post_Rep_Diag_Chec Specialist
Car Care Kit
Glass Lifting Tape Specialist
Wheel Alignment
Pps Cups X3
Corrosion Protection Materials External

Paint L/R Door New Part Painting
Blend Left Front Door Surface Paint
Blend L/Upp A-Pillar Surface Paint
Paint De Nib
Blend Touch Up Bolts Surface Paint
Paint Preparation For Pre-Painting
Methods Research Specialist
Pre_Rep_Diag_Check Specialist
Body Filler
Adas Reset
Tyre Disposal
Tyre Nsr



Our Ref: qdos261253


Your Ref: JF/SBU/45190/1

Date: 18/05/2026

Repair Cost Calculations

Hours	43.58
Hourly Rate	£95.00
Total Labour	£4,140.10
Parts	£2,022.12
Paint/Materials	£1,323.74
Specialist/Other	£849.22
Sub total	£8,335.18
Vat	£1,667.04
Total Estimated Cost	£10,002.22






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026







Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026






Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026





Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.


I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

Edward Mawdsley - ATA VDA AQP
engineers@collisionengineers.co.uk



Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

FAO The Court
C/o QDOS Assistance
3rd Floor, Crown House
Manchester Road
Wilmslow
SK91BH

Fee Note

LD710GY.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos261253.


Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.



Our Ref: qdos261253

Your Ref: JF/SBU/45190/1

Date: 18/05/2026

Vat number: 262 0937 10