

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102805

Created: 02/07/2026

Vehicle reg : EK25YSG

Calculation

02/07/2026

Labour	Total Panel/Mechanical	£1,434.09
	Total Paintwork	£580.75
Total Labour		£2,014.84
Total Paint/Materials Costs		£388.73
Total Parts		£917.01
Total Additional Costs		£620.66
Overall Discount		£0.00
Repair Grand Total Excl VAT		£3,941.24
Grand Total Excl VAT		£3,941.24
VAT		£788.25
Grand Total Incl VAT		£4,729.49
Total Due		£4,729.49

Repair Information

LABOUR **Time Basis 10 WU=1 HR.**

Repair / Guide

Number	Description	Work Units
54-1011 01	SHORT TEST	3.0
	INCLUDES: CONNECT + DISCONNECT STAR	
	DIAGNOSIS,	
	PRINT DATA,	
	DELETE ERROR MEMORY	
54-7989 02	R + R BATTERY EARTH CABLE	3.0
	(WHEN DISCONNECTING ELECTRIC PLUG AND	
	SOCKET CONNECTIONS)	
61-1073 01)	R + R L/F LOWER COVER	1.0
61-1074 01)	R + R R/F LOWER COVER	1.0
61-1077 01	R + R FRT LWR ENGINE COMPARTMENT COVER	3.0

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102805

Created: 02/07/2026

88-1102 01	R + R FRONT BUMPER CPL	8.0
88-1105 01	DIS + ASS FRONT BUMPER	13.0
	(BUMPER REMOVED)	
	AFTER CHECK: RENEW PARTS IF NECESSARY	
88-1374 01	ADDITION TO FRONT BUMPER DIS + ASS	1.0
	(VEHICLE WITH PEDESTRIAN PROTECT)	
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER	2.0
	(VEHICLE WITH PARK ASSISTANT)	
88-1935 01	ADDITION TO R + R FRONT BUMPER	1.0
	(VEHICLE WITH PEDESTRIAN PROTECT)	
88-1319 01	ADD FOR R + R FRONT BUMPER	1.0
	(VEHICLE WITH PARKTRONIC)	
82-4800 01)	RENEW R/HEADLAMP	3.0
	(BUMPER REMOVED)	
54-1947 ZAX	CARRY OUT CALIBRATION DRIVE	3.0
82-1121 01	ADJUST HEADLAMPS	3.0
0283	REPAIR FRONT BUMPER	10.0
0332	CHECK R/LWR BUMP AIR PIPE	
1000	CHECK PRE_REP_DIAG_CHECK	10.0
1000	CHECK POST_REP_DIAG_CHECK	10.0
1000	CHECK FINAL QC & ROAD TEST	10.0
1000	POST REPAIR AND CLEAN CAR	10.0
1000	ALL HV/EV ELECTRIC RISK ASSESS	5.0
1000	PRE REPAIR AND PRE CLEAN CAR	5.0
1000	IIR CHECKS ADAS EXPLORATION FEE	5.0
1000	12v ONLY VEHICLE SHUTDOWN	10.0
Total Work Units		121.0

PAINT WORK

Time Basis 10 WU=1 HR.

Repair / Guide

Number	TWO COAT METALLIC	Work Units
0	FRONT BUMPER PAINTING	9.0
0	L/F OUTER SENSOR PAINTING	1.0
0	R/F OUTER SENSOR PAINTING	1.0
0	ADD COLOUR SAMPLE 1	2.0
0	ADD COLOUR SAMPLE 2	2.0
0	ADD COLOUR SAMPLE 3	2.0
0	NON WATER BASED REMOVE	3.0
0	DIRT, PRESERVER (GREASE, WAX)	
0	DE-NIB AND POLISH 1 PANEL	3.0
0	SECURITY MEASURES BEFORE	3.0
0	CARRYING OUT OVEN DRYING TIME	

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102805

Created: 02/07/2026

0	PREPARATION WORK FOR TWO COAT PAINTING	7.0
0	OF REMOVED PLASTIC PARTS	
0	CARRY OUT COLOUR SHADE DETERMINATION	3.0
0	INCLUDES: ADJUSTABLE COMPONENT	
0	POLISHING AND COLOR TINTING WITH	
0	COLOR PATTERN/MEASURING INSTRUCTIONS	
0	PRIME PLASTIC/METAL PARTS	3.0
0	APPLY SMOOTHG FILLER ON PLAST/MET PARTS	3.0
0	REPAIR/APPLY FILLER ON PLAST/METAL PARTS	2.0
0	APPLY PRIMER FRONT BUMPER (ADD/WORK)	1.0
0	APPLY FILLER FRONT BUMPER (ADD/WORK)	1.0
0	APPLY FILLER PASTE FRONT BUMPER (ADD)	3.0
Total Work Units		49.0

PARTS

Guide No.	Description	Part Number	Bet.	Price
562	RIGHT HEADLAMP ASSY	206 906 3805	0%	£886.00
Sub Total				£886.00
Deduction from RRP				£0.00
Sundry Parts				£31.01
Total Parts				£917.01

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

EXTRAS

Description	Bet.	Price
Repair Methods And		£37.00
Bs 10125 Fee		£34.00
Panel Repair Sundry		£21.00
Adas Front Radar		£257.00
Adas Method Research		£31.00
Adas Matrix/Led Adj		£128.00
Car Care Kit		£10.41
E.P.A. Charge		£31.23
Aries Support		£26.02
Tech Data + Methods		£45.00
Total Extras		£620.66

Exclusive Repair Network
St. George's House, 56 Peter Street
Manchester, M2 3NQ
Phone Number(s):0333 358 3532
Email Address:info@exclusive-assessors.co.uk

Invoice

Claim Reference: EHR102805

Created: 02/07/2026
