

URGENT NEW INSTRUCTION

Instruction Details

To: Collision Engineers
Date: 17/06/2026
From: Smart Business Link
Introducer: Fleet Mitigation Solutions

Claim & Policyholder

Claim Number: SBL-B0687738
Incident Date: 11/06/2026
Claim Type: Intervention
Driver: Mr Darren Gilbert
Policyholder Name: Mr Darren Gilbert
Policyholder VAT Status: Not VAT Registered
Address: 3 Broomfield Close Welwyn , AL6 9DN
Tel Mobile: 07909 920 433

Vehicle & Damage

Vehicle Make: Ford Fiesta
Engine Size:
Registration: C5 RRW
Vehicle Driveable: Yes
Vehicle Damage: Nearside Front Door: Minor, Nearside Rear Door: Minor
Pre-Existing Damage:
Incident Circumstances: TP doing 3-point turn and reversed into the parked and unattended Client vehicle. Neighbour heard the bang and started filming
Agreed Value:
Current Vehicle Location: In Use

Repairer Details

Repairer Name: CLD Accident Repair Centre
Repairer Address: Legrave Rd, Luton LU3 1RF
Repairer Tel: 01582 561122
Repairer Email: info@cldaccidentrepairs.co.uk
Agreed Labour Rate: 60

Insurance & Hire

Insurance Cover:
Policy Excess: £0
Authorise if in order?: Yes
Hire Supplied:
Hire Company:
Hire Out Date:

Important Notes

Please confirm by return receipt of instruction. Arrange inspection within 24 hours and provide full report within 48 hours.