

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: JF/ND/43090/2

Date: 21 July 2026

Dear Sirs

Our Client: AA Motors
Our Client's Vehicle: MERCEDES-BENZ SPRINTER 314 CDI
Registration: PE69YGD
Date of Accident: 10 January 2025

ENGINEER NOTIFICATION (REPORT + AUDIT REPORT)

CLIENT DETAILS

Mr Bahwol Akhonzada
70 High Street
Yiewsley
West Drayton
Greater London
UB7 7DS

Vehicle Details

Client's Vehicle: MERCEDES-BENZ
SPRINTER 314 CDI
Vehicle Registration: PE69YGD
Accident Date: 10/01/2025

Home Tel:
Work Tel:
Mobile:

REPAIRER DETAILS

Tel:
Fax:
Email:
Engineer to Estimate Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Driveable

Please could you check the damage for consistency with the following accident circumstances?

Our client left their vehicle parked and unattended for two days near their home address on Crowshott Avenue, Stanmore. This portion of the road has one lane for each direction of travel. Your insured, in their vehicle has collided into our client's parked vehicle which has then shunted into another parked third party vehicle (DU62 TTK). Your insured abandoned the vehicle at the scene and fled on foot. Our client became aware of the incident the next morning after approaching their vehicle and seeing the damages.

Damage Area – Front: Moderate, Rear Nearside: Moderate, Rear: Moderate
damage to offside rear

damage to front bumper, grill and bonnet - TP impacted front of vehicle

Pre-existing Damage:

TP Vehicle: TOYOTA AURIS TR

TP Registration: MA60EUM

TP Representative Name: 1st Central Underwriting Insurance

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully